

Mathoura Public School

Works notification | 28 August 2025

Dear staff, parents and carers,

On Monday 28 July 2025, damage was identified to the external eave lining sheet on the library demountable shed located near the administration building at Mathoura West Public School.

The affected area is known to contain bonded asbestos, as documented in the school's asbestos register.

NSW Health advises that "living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged."

As a precaution, the damaged section of the shed was barricaded to restrict access. Works to remove and replace the damaged sheet took place Saturday 16 August 2025.

All work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed asbestos contractors and inspected by an independent hygienist with a clearance certificate issued before the area was reopened.

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your continued cooperation during this important work.

