

New Lambton Public School

Works notification | 15 August 2025

Dear staff, parents and carers,

On Friday 15 August 2025, smoke was detected coming from a fluorescent ceiling light in a classroom in Building B at New Lambton Public School.

No open fire was seen; Fire and Rescue NSW assessed the situation and advised it is localised to one room and one fluorescent ceiling light.

As a precaution, the affected room and the rest of Building B were evacuated.

An electrician is currently onsite to investigate the cause, and confirmed it was a fault with the light fitting. Works are currently underway to install new ceiling lights. To clear the room of the smell of smoke, windows will be opened, and ceiling fans are on in the room.

The affected classroom will be temporarily relocated to the wellbeing room while works are completed. Class will resume in the space from Monday 18 August 2025. All other remaining classrooms in Building B have returned to their rooms.

The health, safety and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your understanding as we continue to manage this situation.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
schoolinfrastructure.nsw.gov.au

