

Dear staff and parents/carers,

During a routine inspection at Nulkaba Public School, suspected asbestos containing material was found in the ceiling cavities of Buildings A and B.

As a precaution, access to these ceiling cavities was cordoned off and an independent hygienist was engaged to undertake testing and provide advice.

Testing confirmed the material in the ceiling cavities contained bonded asbestos, which means it was attached to other materials such as tiles or cement and cannot be crumbled by light pressure.

NSW Health explains that if bonded asbestos is mixed with cement or other hard bonding materials, and in good condition, it is likely to be low-risk.

Following advice from the hygienist, work to remove the material took place outside of school hours on Saturday 6 April 2024.

Work was done under the supervision of an independent hygienist with additional safety measures and air monitoring in place before the work started.

All work was done in accordance with work, health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed and accredited asbestos contractors and monitored by independent hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

Following the work, the buildings were inspected by the independent hygienist and the school received a clearance certificate.

The health, safety, and wellbeing of the school and the local community is our highest priority. We will keep the community updated.

Thank you for your cooperation during this important work.

**NSW Department of Education, School Infrastructure**

Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)

Phone: 1300 482 651

[www.schoolinfrastructure.nsw.gov.au](http://www.schoolinfrastructure.nsw.gov.au)