

Goulburn West Public School

Works notification | 28 August 2025

Dear staff, parents and carers,

On Wednesday 13 August 2025, damage to an external window panel was found in the movement area in Building E, at Goulburn West Public School.

The external window panel is known to contain bonded asbestos, as listed in the school's asbestos register.

NSW Health advises that "living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged."

The movement area was immediately made out of bounds with access restricted for students and staff and the window panel taped up to prevent further damage.

Removal of the damaged panel took place outside of school hours on Tuesday 19 August 2025. A licensed asbestos removalist and an independent hygienist were on site, and air monitoring was conducted.

The affected area has been inspected by the independent hygienist and confirmed it has been fully remediated, and a clearance certificate was issued before the area was reopened.

All work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan.

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au