

Waverley Public School

Works notification | 21 August 2025

Dear staff, parents and carers,

We have been managing a persistent leak underneath a building affecting multiple classrooms in Building A, used by Years 2 and 3 at Waverley Public School. Recent and consistent wet weather has increased the wet conditions within the subfloor area of this building.

The department engaged an independent hygienist to investigate further and provide remediation advice.

Mould remediation started on Wednesday 6 August 2025 and included:

- A full environmental clean of all affected surfaces, using fans, air scrubbers and dehumidifiers to help prevent mould from reoccurring.
- Sealing the floor vents to help prevent moisture from entering the classrooms.
- Removing all porous materials, including items unable to be cleaned such as artwork, books, boardgames, soft furnishings, furniture, clocks and air purifiers.

The hygienist advised that the rooms could continue to be used, however the Year 3 class has been relocated to another available classroom for the rest of this year.

A building specialist is assessing the site. They are planning further remediation once this assessment is complete, and the source of the leak is properly identified. These works will help ensure the classrooms are protected from future water issues.

Further information on how mould is managed can be found on the [NSW Health Mould Factsheet](#).

All work is being carried out by licensed contractors and inspected by independent hygienists in accordance with work health and safety laws.

The health, safety and wellbeing of all members of our school and the local community are our highest priority.

Thank you for your cooperation during this important work.

