

# Speers Point Public School

## Works notification | 9 September 2025

Dear staff, parents and carers,

During roof repairs, mould was found in 2 rooms and adjoining storerooms in the support unit building at Speers Point Public School.

The roof and ceiling were exposed to water, which resulted in mould growth. Mould was also found under the carpets and floorboards.

Access to the building has been restricted and alternative spaces were made available for affected classes.

An independent hygienist was engaged to do air monitoring and provide recommendations on Monday 8 September 2025. Further works will be done by specialist cleaners.

Roof repairs will be scheduled and finished at a later date.

Appropriate safety measures will be in place while work is done. Use of and access to the building remains restricted until repairs and cleaning are finished.

The health, safety and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.



Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)  
Phone: 1300 482 651  
[schoolinfrastructure.nsw.gov.au](http://schoolinfrastructure.nsw.gov.au)