

Cabramatta West Public School

Works notification | 2 September 2025

Dear staff, parents and carers,

On Tuesday 19 August 2025 a member of staff noticed that the eaves on the western side of Building L at Cabramatta West Public School were beginning to come loose due to water damage.

The area below the eaves was cordoned off as a precaution, however school operations were not affected. The eaves were known to contain bonded asbestos as per the schools asbestos register.

NSW Health explains that “living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged”.

The bonded asbestos was removed and the eaves were replaced on the weekend of Saturday 30 August and Sunday 31 August 2025.

All work involving asbestos-containing materials took place outside of school hours.

The new eaves will be painted later this week.

All work was done in accordance with work health and safety laws and the NSW Department of Education’s Asbestos Management Plan. Safety measures were in place while work was being done. All work was completed by licensed asbestos contractors.

The area has been inspected by the independent hygienist to confirm it has been fully remediated and a clearance certificate was issued.

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.

