

# Murwillumbah East Public School

## Works notification | 1 April 2026

Dear staff, parents, carers,

During a routine site inspection, we found damage to a window in the support unit classroom of the south-eastern demountable at Murwillumbah East Public School.

The window putty material is known to contain bonded asbestos, as listed on the school's asbestos register.

For more information about asbestos please visit the [NSW Health website](#) or by scanning the QR code.



We have installed panelling over the damaged window while removal and replacement of the putty material and window repairs are being scheduled during the school holidays, on **Saturday 11 April 2026**.

The support unit demountables will eventually be removed as part of the school upgrade.

All work will be done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. Safety measures will be in place while work is being done. All work will be completed by licensed asbestos contractors.

The area will be inspected by an independent hygienist to confirm it has been fully remediated, and a clearance certificate will be issued before the room reopens.

The health, safety, and wellbeing of the school and the local community is our highest priority.

If you have any questions about this work, please contact the NSW Department of Education using the details below.

Thank you for your understanding and support during this important work.



Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)  
Phone: 1300 482 651  
[schoolinfrastructure.nsw.gov.au](http://schoolinfrastructure.nsw.gov.au)