## Wyoming Public School Works notification | 28 February 2025

Dear staff, parents and carers,

During recent maintenance, mould was found on the carpet in an Administration Building office at Wyoming Public School.

Contractors identified vinyl tiles under the carpet that were lifting. These tiles contain bonded asbestos as listed on the school's asbestos register.

NSW Health explains that 'living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged'.

The office was isolated from students and staff temporarily. The flooring was inspected by an independent hygienist who cleared the room for use. The vinyl tiles will need to be removed before the carpet can be replaced.

Work to remove and replace the flooring is planned to take place on Saturday 1 March 2025.

All work will be done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work will be completed by licensed asbestos contractors and monitored by an independent hygienist.

Following the work, the office will be inspected by the independent hygienist and clearance provided to use the area.

The health, safety and wellbeing of the school and the local community is our highest priority.

If you have any questions about this work, please contact the NSW Department of Education on the details below.

Thank you for your cooperation during this important work.



Email: schoolinfrastructure@det.nsw.edu.au Phone: 1300 482 651 www.schoolinfrastructure.nsw.gov.au

