

# Killarney Vale Public School

## Works notification | 1 September 2025

Dear staff, parents, carers and neighbours,

We repaired a cracked window in the Emerald classroom in Building C at Killarney Vale Public School.

The putty material surrounding the window is undisturbed and is suspected to contain asbestos.

As a precaution, the window was immediately taped up and an independent hygienist was engaged to test the material and provide advice.

Testing confirmed that the window putty contained bonded asbestos.

NSW Health explains that "living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged".

On 30 August 2025, contractors removed the putty and replaced the glass window under the guidance of an independent hygienist.

All work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. Safety measures including air monitoring were in place while work was done. All work was completed by licensed asbestos contractors.

The hygienist issued a clearance certificate after works finished.

The health, safety and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.



Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)  
Phone: 1300 482 651  
[schoolinfrastructure.nsw.gov.au](http://schoolinfrastructure.nsw.gov.au)