

Singleton Heights Public School

Works notification | 21 February 2025

Dear staff, parents and carers,

As part of our regular maintenance, we are repairing a cracked window in a classroom in Building A (general classroom block near the carpark) at Singleton Heights Public School.

The putty material in the window contains bonded asbestos as listed on the school's asbestos register. NSW Health explains that 'living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged'.

The glass was secured on Monday 17 February 2025, and the room was isolated from students and staff. An alternative classroom was made available until window repairs can be completed.

Work to replace the glass and remove the window frame material is planned to take place on Monday 24 February 2025.

All work involving asbestos-containing materials will take place outside of school hours.

All work involving asbestos-containing material will be done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work will be completed by licensed asbestos contractors and monitored by independent hygienists.

The classroom will be inspected by the independent hygienist and clearance will be provided before the room is reopened.

The health, safety and wellbeing of the school and the local community is our highest priority.

If you have any questions about this work, please contact the NSW Department of Education on the details below.

Thank you for your cooperation during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au

