

# Campbellfield Public School

## Works notification | 8 August 2024

Dear staff, parents and carers,

During an inspection of Building 4 on Tuesday, 6 August 2024 at Campbellfield Public School, a cracked eave sheet was found near the covered walkway, which is known to contain bonded asbestos as listed in the school's asbestos register.

NSW Health explains if bonded asbestos is mixed with cement or other hard bonding materials such as vinyl tiles, and in good condition, it is likely to be low-risk.

A certified contractor will attend the school on Saturday, 10 August to seal the area with silicon and fully encapsulate the eave, following advice of an independent hygienist.

School staff are supporting students to remain clear of the walkway and ensure no access to the area.

All work will be completed by licensed and accredited asbestos contractors and monitored by independent hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

All work will be done outside of school hours, in accordance with work, health and safety laws and the NSW Department of Education's Asbestos Management Plan. Air monitoring will be in place while the work is carried out.

The eave will be inspected by an independent hygienist, and a clearance certificate will be issued before the area can be accessed.

The health and wellbeing of students, staff and the local community is our highest priority.

Thank you for your cooperation during this important work.



Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)  
Phone: 1300 482 651  
[www.schoolinfrastructure.nsw.gov.au](http://www.schoolinfrastructure.nsw.gov.au)

