

# Singleton High School

Works notification | 27 October 2023

Dear staff and parents/carers,

A small section of flooring in Building C at Singleton High School was damaged. The vinyl tiles are known to contain bonded asbestos, as per the school's asbestos register.

Bonded asbestos means it is attached to other material and cannot be crumbled by light pressure.

The area was cordoned off immediately after the damage was identified. Licenced asbestos contractors attended before school hours on Monday 23 October 2023 and secured the tiles under the supervision of an independent hygienist, who conducted air monitoring during the work.

All work was done in accordance with SafeWork NSW regulations and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed and accredited asbestos contractors and monitored by occupational hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

The hygienist inspected the area and provided clearance for it to be reopened.

The health, safety, and wellbeing of the school and the local community is our highest priority.

Thank you for your cooperation during this important work.

