

# Singleton High School

Works notification | 1 March 2024

Dear staff and parents/carers,

On 22 February 2024, during a routine inspection, a contractor identified a section of damaged ceiling material in the boy's toilet in Building H at Singleton High School. The ceiling in this room is known to contain asbestos as per the school's asbestos register.

The room was immediately cordoned off from staff and students. A hygienist attended and air monitoring was installed.

The ceiling was repaired after school hours on Monday 26 February 2024. Additional safety measures were in place before the work started.

Work was done in accordance with work, health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed and accredited asbestos contractors and monitored by occupational hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

Air monitoring returned results below the minimum detectable limit, which means it is consistent with acceptable levels in ambient air (i.e. <0.01 fibres/mL) as per SafeWork NSW guidelines.

After the work was finished the school received a clearance certificate from the independent hygienist to reopen the toilets.

The health, safety, and wellbeing of the school and local community is our highest priority, and we will continue to keep the community updated.

Thank you for your cooperation during this important work.

