

Brisbane Water Secondary College Woy Woy Campus

Works notification | 5 June 2026

Dear staff, parents and carers,

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

Due to recent bad weather, a roof leak has caused damage to the carpet in a Building D classroom at Brisbane Water Secondary College, Woy Woy Campus.

The ceiling cavities in Building D are known to contain friable asbestos, meaning it can be crumbled, pulverised or reduced to a powder by hand pressure. As a precaution, the classroom was isolated and classes were relocated to alternative rooms within the school.

An independent hygienist attended the school on Monday 1 June 2026 to inspect the room, provide advice and install air monitoring. The independent hygienist provided clearance for repair and cleaning works to proceed.

Work to environmentally clean all surfaces and repair the roof was done on Tuesday 2 June 2025.

Following this, the building was reinspected by the independent hygienist and clearance was issued for the room to be reopened.

If you have any questions about this, please contact the NSW Department of Education using the details below.

Thank you for your understanding and support during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au