

Windsor High School

Works notification | 12 March 2026

Dear staff, parents and carers,

On Monday 9 March 2026, as part of planned maintenance work to replace carpet in multiple classrooms in Building L2 at Windsor High School, a contractor identified vinyl tiles suspected to contain bonded asbestos.

The carpet flooring currently remains in place over the vinyl flooring. Work was stopped and the area was isolated. The area was already inaccessible to students and staff.

An independent hygienist inspected the area and collected samples. Test results confirmed the presence of bonded asbestos in the Building L2 ground floor classrooms 4, 9 and 14 and first floor classrooms 10 and 14.

NSW Health explains that “living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged”.

This location is not in an area identified on the School Asbestos Management Plan (SAMP).

Learning has been relocated to other available classrooms.

The vinyl tiles will be removed on Saturday 14 March 2026. Work hours are between 8 am and 1 pm on Saturday, in line with NSW Environment Protection Authority guidelines.

An independent hygienist will oversee the work and conduct air monitoring and testing. A clearance certificate will be provided before the classrooms are reopened.

All work will be done in accordance with work health and safety laws as well as the NSW Department of Education’s Asbestos Management Plan. Safety measures will be in place while work is being done. All work will be completed by licensed asbestos contractors.

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
schoolinfrastructure.nsw.gov.au