

Endeavour Sports High School

Works notification | 24 February 2026

Dear staff, parents and carers,

On Friday 20 February 2026, a fragment of material suspected to contain asbestos was found on the grass near Building B at Endeavour Sports High School.

An independent hygienist was engaged to collect the fragment for testing and advise on remediation. Testing confirmed that the fragment contained bonded asbestos.

NSW Health explains that 'living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged'.

Access to the area was immediately restricted. Work took place the same day to remove asbestos-containing material from the soil.

The area was inspected by an independent hygienist and a clearance certificate was issued before the area was reopened for use.

This location is not in an area identified on the School Asbestos Management Plan (SAMP). The register will be updated to include this recent find.

All asbestos-related work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed asbestos contractors.

The health, safety and wellbeing of the school and the local community are our highest priorities.

If you have any questions about this work, please contact the NSW Department of Education on the details below.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
schoolinfrastructure.nsw.gov.au