### **NSW Department of Education – School Infrastructure**

# James Busby High School

## Works notification

#### 8 March 2021

Dear parents/carers,

During planned maintenance at James Busby High School, asbestos containing material was found in the flue pipe of the hot water heating system in unused room BR1003. The material has been confirmed as bonded asbestos which means it is attached to other material such as cement or vinyl and cannot be crumbled by light pressure.

Safety measures and monitoring have been put in place to ensure there is no risk to students, staff or the local community. As a precaution, the area has been cordoned off and will remain out of bounds to students and staff until remediation is completed.

This area will be remediated in accordance with the Department of Education's Asbestos Management Plan and SafeWork NSW regulations. All work will be completed by licensed and accredited asbestos contractors, and monitored by occupational hygienists in strict accordance with all applicable legislation, regulations, policies and guidelines.

All asbestos containing material will be removed outside of school hours on Saturday 13 and Sunday 14 March 2021.

Testing will be completed to ensure the area has been fully remediated. The school will receive a clearance certificate before the area is open to students and staff.

The health, safety, and well-being of the school and the local community is our highest priority and we will continue to keep the community updated.

Thank you for your cooperation during this important work.

### For more information contact:

School Infrastructure NSW Email: schoolinfrastructure@det.nsw.edu.au Phone: 1300 482 651

www.schoolinfrastructure.nsw.gov.au

