

Tuggerah Lakes Secondary College, The Entrance

Works notification | 18 December 2025

Dear staff, parents and carers,

On Wednesday 10 December 2025, a cracked window was identified in a classroom in Building B at Tuggerah Lakes Secondary Collage, The Entrance Campus.

The putty material in this window is known to contain bonded asbestos. NSW Health explains that 'living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged'.

The glass was temporarily secured and access to the classroom was immediately restricted.

Work to repair the window took place on Saturday 13 December 2025. An independent hygienist inspected the area and provided clearance for the classroom to be reopened for normal lessons from Monday 13 December 2025.

All work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed asbestos contractors and monitored by independent hygienists.

If you have any questions about this work, please contact the NSW Department of Education on the details below.

The health, safety and wellbeing of the school and the local community is our highest priority.

Thank you for your understanding during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
schoolinfrastructure.nsw.gov.au