



60m

Views of the trees to the Council strip.





60m

General views of the footpath, kerb and gutter.





70m

General views of the footpath, kerb and gutter.





70m

General views of the footpath, kerb and gutter.





70m

General views of the footpath, kerb and gutter.







70m

Various cracks throughout the kerb and gutter.





70m

Various cracks throughout the kerb and gutter.







80m

General views of the footpath, kerb and gutter.





80m

Various cracks and damage throughout the kerb and gutter.







80m

Various cracks and damage throughout the kerb and gutter.





80m

Views of the telegraph pole.





90m

General views of the footpath, kerb and gutter.







90m

General views of the footpath, kerb and gutter.







90m

Various sections of crack damage throughout the kerb and gutter.





90m

Various sections of crack damage throughout the kerb and gutter.





97m


View of the gas inspection point.





100m

General views of the footpath, kerb and gutter.





100m

General views of the footpath, kerb and gutter.





100m

Various cracks and damage to the kerb and gutter.







100m

Various cracks and damage to the kerb and gutter.





110m

General views of the footpath, kerb and gutter.







110m

General views of the footpath, kerb and gutter.





110m

Various cracks and damage to the kerb and gutter.







110m

Various cracks and damage to the kerb and gutter.



115m

View of the inspection lid to the footpath.





120m

General views of the footpath, kerb and gutter.





120m

General views of the footpath, kerb and gutter.





120m

Various cracks and damage to the kerb and gutter.





120m

Various cracks and damage to the kerb and gutter.





130m

Views of the street sign.





130m

General views of the footpath, kerb and gutter.





130m

General views of the footpath, kerb and gutter.





130m

Crack damage throughout the kerb and gutter.





130m

Crack damage throughout the kerb and gutter.





131m

View of the inspection lid to the footpath.







130m

Views of the inspection lid and telegraph pole.





130m


Views of the inspection lid and telegraph pole.





130m

Views of the inspection lid and telegraph pole.





140m

General views of the footpath, kerb and gutter.





140m

General views of the footpath, kerb and gutter.







142m

Views of the telegraph poles.

