



40m

Crack damage and repaired section noted to the road surface.





40m

Crack damage and repaired section noted to the road surface.





40m

Crack damage and repaired section noted to the road surface.





40m

Crack damage throughout the kerb and gutter.





40m

Crack damage throughout the kerb and gutter.



46m

Views of the telegraph pole and inspection lid.





46m

Views of the telegraph pole and inspection lid.





50m

General views of the kerb, gutter and road surface.





50m

General views of the kerb, gutter and road surface.



50m

General views of the kerb, gutter and road surface.





50m

Crack damage throughout the road surface.





50m

Crack damage throughout the road surface.





50m

Crack damage throughout the kerb and gutter.





50m

Crack damage throughout the kerb and gutter.



56m


Views of the tree to the Council strip.





60m

Views of the telegraph pole.





60m

Crack damage throughout the kerb, gutter and road surface.





60m

Crack damage throughout the kerb, gutter and road surface.





60m

Crack damage throughout the kerb, gutter and road surface.





60m

Crack damage throughout the kerb, gutter and road surface.





65m

Crack damage throughout the driveway layback and gutter.





65m

Crack damage throughout the driveway layback and gutter.





70m

Crack damage throughout the kerb, gutter and road surface.





70m

Crack damage throughout the kerb, gutter and road surface.



70m

Crack damage throughout the kerb, gutter and road surface.





70m

Crack damage throughout the kerb, gutter and road surface.





70m

Crack damage throughout the kerb, gutter and road surface.



80m

Crack damage to the kerb and gutter.





80m

Crack damage to the kerb and gutter.



80m

Crack damage throughout the road surface.





80m

Crack damage throughout the road surface.





80m

Crack damage throughout the road surface.





90m

Crack damage throughout the kerb and gutter.



90m

Crack damage throughout the kerb and gutter.



90m

General views of the road surface.





90m

General views of the road surface.



100m

Views of the street sign and telegraph pole.



100m

Views of the street sign and telegraph pole.



100m

Views of the street sign and telegraph pole.



100m

Crack damage to the kerb and gutter.

