

Asbestos Register


(Hazardous Materials and Risk Assessment)

School:	Fairfield West Public School (1896)
Region:	South Western Sydney AMU
State Electorate:	Fairfield
Local Government Area:	Fairfield

Last Reviewed By:	WSP 11-SEP-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

1896 - Fairfield West Public School
Site Plan (11678)



Printed: 04-Jun-2020

Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Staff Facilities - 1968 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - External Movement - 7.2 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0002 - Cleaning Distributed Store - 2.68 m2							
No Asbestos							
B00A - R0003 - Staff Room Annexe - 7.35 m2							
No Asbestos							
B00A - R0004 - General Storeroom - 7.45 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0007 - Movement - 5.97 m2							
No Asbestos							
B00A - R0008 - General Storeroom - .46 m2							
No Asbestos							
B00A - R0009 - Distribution Board - .46 m2							
Note: No inspection of live electrical installation							
Electrical - Mounting Board	Resinous Board	1	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0010 - Staff Kitchen - 8.59 m2							
No Asbestos							
B00A - R0011 - Staff Room - 70.76 m2							
No Asbestos							
B00A - R0012 - Toilet - Lobby - 1.98 m2							
Wall Linings Internal	Flat AC Sheeting	20m2	All Walls	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00A - R0013 - Staff Toilet - 1.52 m2							
Wall Linings Internal	Flat AC Sheeting	20m2	All Walls	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00A - R0014 - Staff Toilet - 1.55 m2							
Wall Linings Internal	Flat AC Sheeting	20m2	All Walls	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00A - R0015 - Toilet - Lobby - 2.01 m2							
Wall Linings Internal	Flat AC Sheeting	20m2	All Walls	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00B - General Learning/Support Unit - 1970 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00B - R0001 - Home Base - 60.03 m2							
Wn dow	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0002 - Home Base Store - 3.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0003 - Distribution Board - .59 m2 Note: No inspection of live electrical installation							
Door - Lining	Flat AC Sheeting	4	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0004 - Practical Activities - 1hb - 23.89 m2							
Floor Coverings Res/Textile	Vinyl Tiles	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0005 - Movement - 2.94 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0006 - Staff Room Annexe - 15.8 m2							
Wn dow	Compressed AC Sheet	1	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0007 - Home Base - 58.14 m2							
Wn dow	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0008 - Disabled Toilet - 12.89 m2							
No Asbestos							
B00B - R0009 - Personal Effects Storage - 14.57 m2							
Floor Coverings Res/Textile	Vinyl Tiles	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0010 - Practical Activities - 1hb - .53 m2							
No Asbestos							
B00B - R0011 - Distribution Board - .53 m2 Note: No inspection of live electrical installation							
No Asbestos							
B00B - R0012 - Home Base - M - 59.53 m2							
Wn dow	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0013 - Home Base - 59.05 m2							
Wn dow	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0014 - Craft Store - 8.26 m2							
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0015 - Personal Effects Storage - 14.56 m2							
Wall Linings Internal	Flat AC Sheeting						
Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0016 - Distribution Board - .57 m2 Note: No inspection of live electrical installation							
Door - Lining	Flat AC Sheeting	4	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0017 - Music Store - 7.57 m2							
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00B - R0018 - Home Base Store - 4.05 m2							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0019 - Home Base - 58.55 m2							
Window	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0020 - Home Base Store - 7.5 m2							
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0021 - Sports Store - 7.48 m2							
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0022 - Movement - 9.55 m2							
No Asbestos							
B00B - R0023 - Movement - 5.18 m2							
No Asbestos							
B00B - R0024 - Movement - 103.97 m2							
Ceiling Structures/Linings	Flat AC Sheeting	104m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0025 - Movement - 6.44 m2							
No Asbestos							
B00B - R0026 - External Movement - 23.24 m2							
No Asbestos							
B00B - R0027 - External Movement - 11.82 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00B - R0028 - Stairs - 14.84 m2							
No Asbestos							
B00B - R0029 - Stairs - 10.66 m2							
No Asbestos							
B00B - R1001 - Home Base - 75.24 m2							
Window	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R1002 - Movement - 4.55 m2							
No Asbestos							
B00B - R1003 - Movement - 2.89 m2							
No Asbestos							
B00B - R1004 - General Storeroom - 2.54 m2							
No Asbestos							
B00B - R1005 - Distribution Board - .9 m2							
						Note: No inspection of live electrical installation	
Door - Lining	Flat AC Sheeting	5	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1007 - Personal Effects Storage - 11.4 m2							
No Asbestos							
B00B - R1008 - Home Base - 74.02 m2							
Window	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R1009 - Home Base - 59.21 m2							
Window	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R1010 - Practical Activities - 1hb - 28.37 m2							
Window	Compressed AC Sheet	2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R1011 - Home Base - 57.98 m2							
Window	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R1012 - Movement - 4.55 m2							
No Asbestos							
B00B - R1013 - Craft Store - 6.64 m2							
No Asbestos							
B00B - R1015 - Practical Activities - 1hb - 21.2 m2							
No Asbestos							
B00B - R1016 - Distribution Board - .64 m2							Note: No inspection of live electrical installation
Door - Lining	Flat AC Sheeting	4	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1017 - Home Base Store - 4.2 m2							
No Asbestos							
B00B - R1018 - Home Base - 60.03 m2							
Window	Compressed AC Sheet	1	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R1019 - Movement - 103.99 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00B - R1020 - Stairs - 14.84 m2							
No Asbestos							
B00B - R1021 - Stairs - 15.04 m2							
No Asbestos							
B00B - R1022 - Toilet - Lobby - 2.42 m2							
No Asbestos							
B00B - R1023 - Toilets - Boys/Girls - 1.4 m2							
No Asbestos							
B00B - R1024 - Toilet - Lobby - 2.5 m2							
No Asbestos							
B00B - R1025 - Toilets - Boys/Girls - 1.35 m2							
No Asbestos							
B00B - R9001 - Toilets - Girls - 107.25 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	50m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R9002 - Cleaning Distributed Store - 7.99 m2							
No Asbestos							
B00B - R9003 - Movement - 16.93 m2							
No Asbestos							
B00B - R9004 - Movement - 51.43 m2							
No Asbestos							
B00B - R9005 - Stairs - 7.84 m2							
No Asbestos							
B00C - General Learning - 1969 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00C - R0001 - Home Base - 57.17 m2							
No Asbestos							

B00C - R0002 - Home Base Store - 5.93 m2							
No Asbestos							
B00C - R0005 - External Movement - 5.43 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0006 - Home Base Store - 6.01 m2							
No Asbestos							
B00C - R0007 - Home Base - 56.55 m2							
No Asbestos							
B00C - R0008 - Home Base - 56.55 m2							
No Asbestos							
B00C - R0009 - Home Base Store - 6.01 m2							
No Asbestos							
B00C - R0012 - External Movement - 5.35 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0013 - Home Base Store - 6 m2							
No Asbestos							
B00C - R0014 - Home Base - 56.78 m2							
No Asbestos							
B00C - R0015 - External Movement - 16.83 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0016 - Practical Activities - 1hb - 15.18 m2							
No Asbestos							
B00C - R0017 - Practical Activities - 1hb - 15.13 m2							
No Asbestos							
B00D - General Learning/Tiered Learning - 1956 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00D - R0001 - Home Base - 56.96 m2							
No Asbestos							
B00D - R0002 - Home Base Store - 4.15 m2							
No Asbestos							
B00D - R0005 - External Movement - 5.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0006 - Home Base Store - 4.15 m2							
No Asbestos							

B00D - R0011 - Staff Room Annexe - 15.21 m2							
Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0013 - External Movement - 5.52 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0014 - Home Base - 56.25 m2							
No Asbestos							
B00D - R0015 - Home Base Store - .6 m2							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0016 - Movement - 1.46 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0017 - General Storeroom - .69 m2							
No Asbestos							
B00D - R0022 - Practical Activities - 1hb - 18.94 m2							
No Asbestos							
B00D - R0023 - Home Base - 56.27 m2							
No Asbestos							
B00D - R0024 - Special Programs Room - 27.56 m2							
No Asbestos							
B00D - R0025 - Movement - 6.48 m2							
No Asbestos							
B00D - R0026 - General Storeroom - 5.68 m2							
No Asbestos							
B00D - R0027 - Home Base Store - 8.46 m2							
No Asbestos							
B00D - R0028 - Practical Activities - 1hb - 15.31 m2							
No Asbestos							
B00D - R9001 - Garden Store - 34.07 m2							
Material - Packing	Flat AC Sheeting						
B00D - R9002 - General Storeroom - 33.81 m2							
Material - Packing	Flat AC Sheeting						
B00D - R9003 - Special Programs Room - 53.36 m2							
Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R9004 - Movement - 19.6 m2							
No Asbestos							
B00E - Library - 1965 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							

B00E - R0005 - Distribution Board - .46 m2							Note: No inspection of live electrical installation
Wall Linings Internal	Flat AC Sheeting	4m2	Door backing	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0006 - Movement - 23.37 m2							
No Asbestos							
B00E - R0009 - Handwashing Facilities - 25.21 m2							
No Asbestos							
B00E - R0010 - Drinking Facilities - 15.74 m2							
No Asbestos							
B00E - R0011 - Toilets - Boys - 49.74 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	25m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0012 - Movement - 14.81 m2							
No Asbestos							
B00E - R0013 - Communications Room - 14.03 m2							
No Asbestos							
B00E - R0014 - Library Office/Workroom - 28.62 m2							
No Asbestos							
B00E - R0015 - Reading Area - 126.88 m2							
No Asbestos							
B00E - R0017 - External Movement - 3.97 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00E - R0018 - Lift - 1.63 m2							
No Asbestos							
B00E - R0019 - Reading Area - 132.64 m2							
No Asbestos							
B00H - Other-After School Care - 1964 - Timber							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00H - R0001 - Cleaning Supplies - 13.29 m2							
No Asbestos							
B00H - R0002 - External Movement - 40.04 m2							
No Asbestos							
B00H - R0003 - Special Programs Room - 47.96 m2							
No Asbestos							
B00H - R0004 - Home Base - 47.96 m2							
No Asbestos							
B00H - R0005 - General Storeroom - 6.83 m2							
No Asbestos							
B00J - General Learning - 1968 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						

Underfloor Voids	No Asbestos Found						
Interior							
B00J - R0001 - Home Base - 56.8 m2							
No Asbestos							
B00J - R0005 - External Movement - 5.32 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00J - R0008 - Home Base - 56.33 m2							
No Asbestos							
B00J - R0009 - Community Clinic - 21.5 m2							
No Asbestos							
B00J - R0010 - Cleaning Distributed Store - 2.07 m2							
No Asbestos							
B00J - R0011 - Movement - 4.13 m2							
No Asbestos							
B00J - R0012 - External Movement - 5.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00J - R0013 - Movement - 18.19 m2							
No Asbestos							
B00J - R0014 - Home Base Store - 4.61 m2							
No Asbestos							
B00J - R0015 - Withdrawal Space - 2hb - 8.93 m2							
No Asbestos							
B00J - R0016 - Practical Activities - 2hb - 8.89 m2							
No Asbestos							
B00J - R0017 - Home Base Store - 4.61 m2							
No Asbestos							
B00K - General Learning - 1962 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00K - R0001 - External Movement - 5.52 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0002 - Movement - 6.3 m2							
No Asbestos							
B00K - R0004 - Staff Room Annexe - 21.36 m2							
Floor Coverings Res/Textile	Vinyl Tiles	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00K - R0011 - Home Base Store - 4.31 m2							
No Asbestos							
B00K - R0013 - External Movement - 4.88 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0014 - Toilet - Lobby - 1.57 m2							
Wall Linings Internal	Flat AC Sheeting	18m2	All Walls	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00K - R0015 - Toilets - Boys/Girls - 1.58 m2							
Wall Linings Internal	Flat AC Sheeting	18m2	All Walls	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00K - R0016 - Practical Activities - 1hb - 6.39 m2							
No Asbestos							
B00K - R0017 - Home Base - 69.87 m2							
No Asbestos							
B00K - R0018 - Home Base Store - 3.98 m2							
No Asbestos							
B00K - R0019 - Toilet - Lobby - 1.97 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00K - R0020 - Toilets - Boys/Girls - 1.73 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00K - R0021 - Practical Activities - 1hb - 6.64 m2							
No Asbestos							
B00K - R0022 - Home Base - 73.13 m2							
No Asbestos							
B00M - General Learning/Communal Facilities - 1969 - Concrete							
Exterior							
Eaves Linings	Flat AC Sheeting	60m2	North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00M - R0001 - Practical Activities - 1hb - 1.09 m2							
Electrical - Mounting Board	Resinous Board	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00M - R0002 - Other-Commercial - 53.45 m2							
No Asbestos							
B00M - R0003 - Home Base - 53.23 m2							
No Asbestos							
B00M - R0004 - No Access - 6.61 m2							
No Asbestos							
B00M - R0005 - Withdrawal Space - 1hb - 10.34 m2							
No Asbestos							
B00M - R0006 - Craft Store - 11.1 m2							
No Asbestos							
B00M - R0007 - Personal Effects Storage - 6.61 m2							

No Asbestos							
B00M - R0008 - Withdrawal Space - 1hb - 13.63 m2							
No Asbestos							
B00M - R0010 - External Movement - 63.14 m2							
Floor Coverings Res/Textile	Vinyl Tiles	40m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	63m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00M - R0011 - External Movement - 5.97 m2							
No Asbestos							
B00M - R0012 - External Movement - 4.63 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00M - R0013 - Home Base - 53.53 m2							
No Asbestos							
B00M - R0014 - Home Base - 53.46 m2							
No Asbestos							
B00O - Pupil Facilities - 1935 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00O - R0001 - Staff Toilet - 2.86 m2							
No Asbestos							
B00O - R0002 - Movement - 3.07 m2							
No Asbestos							
B00O - R0003 - Uniform Shop - 4.42 m2							
No Asbestos							
B00O - R0004 - Canteen - 32.03 m2							
No Asbestos							
B00O - R0005 - Movement - 12.11 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00P - Pupil Facilities - 1938 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	30m2	North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00P - R0001 - Garden Store - 11.6 m2							
No Asbestos							
B00P - R0002 - General Assistant/Bulk Store - 31.88 m2							
No Asbestos							
B00P - R0003 - Staff Toilet - 1.23 m2							
No Asbestos							
B00P - R0004 - Cleaning Distributed Store - 5.66 m2							
No Asbestos							

B00P - R0005 - General Storeroom - 5.66 m2							
No Asbestos							
B00P - R0006 - K.L.A. Store - 37.31 m2							
No Asbestos							
B00P - R0007 - Drinking Facilities - 11.6 m2							
No Asbestos							
B00Q - Pupil Facilities - 1963 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00Q - R0001 - Drinking Facilities - 12.16 m2							
No Asbestos							
B00Q - R0002 - Toilets - Boys - 36.68 m2							
Partition Walls (Cubides)	Compressed AC Sheet	12m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00Q - R0003 - General Storeroom - 5.39 m2							
No Asbestos							
B00Q - R0004 - General Storeroom - 5.39 m2							
No Asbestos							
B00Q - R0005 - Toilets - Girls - 31.31 m2							
Partition Walls (Cubides)	Compressed AC Sheet	20m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00Q - R0006 - Cleaning Distributed Store - 1.22 m2							
No Asbestos							
B00Q - R0007 - Drinking Facilities - 11.93 m2							
No Asbestos							
B00Q - R0008 - External Movement - 50.28 m2							
No Asbestos							
B00R - Building Services - 1968 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00R - R0001 - Cleaning Supplies - 10.13 m2							
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00S - Communal Facilities - 2009 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00S - R0001 - Communal Space - 210.18 m2							
No Asbestos							

B00S - R0002 - Movement - 13.61 m2		
No Asbestos		
B00S - R0003 - Ramp - 12.99 m2		
No Asbestos		
B00S - R0004 - Raised Platform - 61.36 m2		
No Asbestos		
B00S - R0005 - Hall Chair Store - 11.36 m2		
No Asbestos		
B00S - R0006 - Movement - 2.98 m2		
No Asbestos		
B00S - R0007 - External Movement - 6.76 m2		
No Asbestos		
B00S - R0008 - Other - 3.65 m2		
No Asbestos		
B00S - R0009 - Plant - 1.61 m2		
No Asbestos		
B00S - R0010 - Main Switch Board - 3.09 m2		
No Asbestos		
B00S - R0011 - Cleaning Distributed Store - 3.53 m2		
No Asbestos		
B00S - R0012 - Toilet - Lobby - 3.49 m2		
No Asbestos		
B00S - R0013 - Toilets - Girls - 10.15 m2		
No Asbestos		
B00S - R0014 - Sound Cupboard - 2.71 m2		
No Asbestos		
B00S - R0015 - Access Shower/Toilet - 7.02 m2		
No Asbestos		
B00S - R0017 - Toilet - Lobby - 1.84 m2		
No Asbestos		
B00S - R0018 - Toilets - Boys - 7.45 m2		
No Asbestos		
B00S - R0019 - P.E Store - 16.68 m2		
No Asbestos		
B00S - R0020 - Movement - 2.32 m2		
No Asbestos		
B00S - R0021 - External Movement - 3.82 m2		
No Asbestos		
B00S - R0022 - Communal/Performance Store - 10.82 m2		
No Asbestos		
B00S - R0023 - External Movement - 59.2 m2		
No Asbestos		
B00S - R0024 - Covered Outdoor Learning Area - 167.57 m2		
No Asbestos		
B00T - General Learning - 2010 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00T - R0001 - Practical Activities - 1hb - 18.98 m2		

No Asbestos							
B00T - R0002 - Home Base Store - 6 m2							
No Asbestos							
B00T - R0003 - Home Base - 60.66 m2							
No Asbestos							
B00T - R0004 - Withdrawal Space - 2hb - 11.78 m2							
No Asbestos							
B00T - R0005 - Home Base - 60.59 m2							
No Asbestos							
B00T - R0006 - Home Base Store - 6.07 m2							
No Asbestos							
B00T - R0007 - Practical Activities - 1hb - 18.46 m2							
No Asbestos							
B00T - R0008 - Distribution Board - .51 m2							
							Note: No inspection of live electrical installation
No Asbestos							
B00T - R0009 - External Movement - 56.85 m2							
No Asbestos							
B00T - R0010 - External Stairs - 17.16 m2							
No Asbestos							
B00T - R1001 - Practical Activities - 1hb - 19.21 m2							
No Asbestos							
B00T - R1002 - Home Base Store - 6.08 m2							
No Asbestos							
B00T - R1003 - Home Base - 61.09 m2							
No Asbestos							
B00T - R1004 - Withdrawal Space - 2hb - 11.78 m2							
No Asbestos							
B00T - R1005 - Home Base - 61.13 m2							
No Asbestos							
B00T - R1006 - Home Base Store - 6.12 m2							
No Asbestos							
B00T - R1007 - Practical Activities - 1hb - 19.21 m2							
No Asbestos							
B00T - R1008 - External Movement - 57.88 m2							
No Asbestos							
B00T - R1009 - External Movement - 17.16 m2							
No Asbestos							
B011 - General Learning - 1969 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B011 - R0001 - Deputy Principal - 29.16 m2							
Window	Compressed AC Sheet	2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B011 - R0002 - Uniform Shop - 4.9 m2							

Window	Compressed AC Sheet	1	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B011 - R0003 - Cleaning Distributed Store - 1.58 m2							
No Asbestos							
B011 - R0004 - Personal Effects Storage - 13.57 m2							
No Asbestos							
B011 - R0005 - Practical Activities - 1hb - .69 m2							
No Asbestos							
B011 - R0006 - Distribution Board - .51 m2							
Note: No inspection of live electrical installation							
Door - Lining	Flat AC Sheeting	4	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0007 - General Storeroom - 2.46 m2							
No Asbestos							
B011 - R0009 - Home Base - 88.46 m2							
Window	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B011 - R0010 - Home Base - 89.28 m2							
Window	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B011 - R0012 - General Storeroom - 2.63 m2							
No Asbestos							
B011 - R0013 - Personal Effects Storage - 7.23 m2							
No Asbestos							
B011 - R0014 - Practical Activities - 1hb - .42 m2							
No Asbestos							
B011 - R0015 - External Movement - 70.54 m2							
Ceiling Structures/Linings	Flat AC Sheeting	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0016 - Principal - 18.56 m2							
Window	Compressed AC Sheet	1	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B011 - R0017 - Staff Room Annexe - 12.92 m2							
Window	Compressed AC Sheet	1	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B011 - R0018 - Entry Vestibule - 32.94 m2							
No Asbestos							
B011 - R0019 - Movement - 16.58 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0020 - Main Switch Board - 11.22 m2							
Electrical - Mounting Board	Resinous Board						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0021 - Staff Room Annexe - 19.01 m2							
No Asbestos							
B011 - R0022 - Cleaning Distributed Store - 1.46 m2							
No Asbestos							
B011 - R0023 - Staff Toilet - 3.35 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0024 - General Storeroom - 5.27 m2							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0025 - Movement - 3.37 m2							
No Asbestos							

B011 - R0026 - Plant - 1.16 m2							
Door - Lining	Flat AC Sheeting	4	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0027 - Clerical Office - 21.46 m2							
Window	Compressed AC Sheet	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B011 - R0028 - Toilet - Lobby - 2.11 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0029 - Toilets - Boys/Girls - 1.62 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0030 - Toilet - Lobby - 2.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0031 - Toilets - Boys/Girls - 1.7 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - Administration/General Learning - 1965 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B012 - R0001 - Movement - 5.23 m2							
No Asbestos							
B012 - R0002 - Sick Bay - 10.42 m2							
Window	Compressed AC Sheet	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B012 - R0003 - Duplicating Workroom - 31.1 m2							
Window	Compressed AC Sheet	1	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B012 - R0004 - General Storeroom - 4.1 m2							
Window	Compressed AC Sheet	0.5	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B012 - R0005 - Interview - 10.73 m2							
Window	Compressed AC Sheet	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B012 - R0006 - Security Store - 9.91 m2							
No Asbestos							
B012 - R0007 - Home Base - 89.61 m2							
Window	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B012 - R0008 - Home Base - 74.2 m2							
Window	Compressed AC Sheet	4	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B012 - R0010 - Home Base Store - 2.6 m2							
No Asbestos							
B012 - R0011 - Distribution Board - .8 m2							
Note: No inspection of live electrical installation							

Door - Lining	Flat AC Sheeting	4	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B012 - R0012 - Personal Effects Storage - 6.12 m2							
No Asbestos							
B012 - R0013 - Practical Activities - 1hb - .45 m2							
No Asbestos							
B012 - R0014 - External Movement - 74.84 m2							
Ceiling Structures/Linings	Flat AC Sheeting	76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0015 - Toilet - Lobby - 2.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0016 - Toilets - Boys/Girls - 1.68 m2							
No Asbestos							

Demountables			
OS 602 10419 - Learning Unit - Standard With P.A.A. - Placement Date : 04-JAN-2016			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 601 11048 - Learning Unit - Standard/Withdrawal - Placement Date : 23-DEC-2014			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 602 13056 - Learning Unit - Standard With P.A.A. - Placement Date : 23-DEC-2014			
No Asbestos Found			
OS 750 16784 - Learning Unit - ESL - Placement Date : 02-FEB-2016			
No Asbestos Found			
OS 606 19019 - Learning Unit - Standard With P.A.A A/C - Placement Date : 22-AUG-2017			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 606 19052 - Learning Unit - Standard With P.A.A A/C - Placement Date : 08-AUG-2017			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 606 19053 - Learning Unit - Standard With P.A.A A/C - Placement Date : 08-AUG-2017			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			