

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Harrington Street Public School (4314)
Region:	South Western Sydney AMU
State Electorate:	Cabramatta
Local Government Area:	Fairfield

Last Reviewed By:	WSP 11-SEP-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

4314 - Harrington Street Public School
Site Plan (11005)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning - 1963 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - Movement - 1.6 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0002 - Community Clinic - 15.36 m2							
No Asbestos							
B00A - R0003 - General Storeroom - 1.03 m2							
No Asbestos							
B00A - R0004 - General Storeroom - 6.11 m2							
No Asbestos							
B00A - R0005 - Distribution Board - .23 m2							
No Asbestos							
B00A - R0006 - Shower/Change - 4.42 m2							
No Asbestos							
B00A - R0007 - Main Switch Board - 5.64 m2							
No Asbestos							
B00A - R0008 - General Storeroom - 2.99 m2							
No Asbestos							
B00A - R0009 - General Storeroom - 1.4 m2							
No Asbestos							
B00A - R0010 - Staff Room Annexe - 21.19 m2							
No Asbestos							
B00A - R0011 - Movement - 20.99 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0012 - External Movement - 1.59 m2							
No Asbestos							
B00A - R0013 - Home Base - 56.53 m2							
No Asbestos							
B00A - R0014 - Home Base Store - 6.53 m2							
No Asbestos							
B00A - R0015 - Personal Effects Storage - 6.41 m2							
No Asbestos							
B00A - R0016 - Movement - 4.2 m2							
No Asbestos							
B00A - R0017 - General Storeroom - .56 m2							
No Asbestos							
B00A - R0018 - Movement - 1.41 m2							

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0019 - General Storeroom - .56 m2							
No Asbestos							
B00A - R0020 - Home Base - 56.38 m2							
No Asbestos							
B00A - R0021 - Home Base Store - 6.53 m2							
No Asbestos							
B00A - R0022 - Home Base - 56.37 m2							
No Asbestos							
B00A - R0023 - Home Base Store - 6.53 m2							
No Asbestos							
B00A - R0024 - Personal Effects Storage - 3.38 m2							
Wall Linings Internal	Flat AC Sheeting	9m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0025 - Music Store - 2.95 m2							
Wall Linings Internal	Flat AC Sheeting	9m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0026 - Movement - 4.13 m2							
No Asbestos							
B00A - R0027 - Other-Vacant - .54 m2							
No Asbestos							
B00A - R0028 - Movement - 1.46 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0029 - General Storeroom - .54 m2							
No Asbestos							
B00A - R0030 - Special Programs Room - 56.77 m2							
No Asbestos							
B00A - R0031 - Home Base Store - 6.53 m2							
No Asbestos							
B00C - General Learning - 1981 - Brick/Veneer							
Exterior							
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	80m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Interior							
B00C - R0001 - External Movement - 1.41 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0002 - General Storeroom - .58 m2							
No Asbestos							
B00C - R0003 - General Storeroom - .58 m2							
No Asbestos							

B00C - R0004 - Movement - 5.96 m2							
No Asbestos							
B00C - R0005 - Personal Effects Storage - 4.59 m2							
No Asbestos							
B00C - R0006 - Personal Effects Storage - 4.64 m2							
No Asbestos							
B00C - R0007 - Home Base Store - 4.72 m2							
No Asbestos							
B00C - R0008 - Home Base - 57.01 m2							
No Asbestos							
B00C - R0009 - Home Base - 56.46 m2							
No Asbestos							
B00C - R0010 - Home Base Store - 4.66 m2							
No Asbestos							
B00C - R0011 - Home Base - 56.46 m2							
No Asbestos							
B00C - R0012 - Home Base Store - 6.53 m2							
No Asbestos							
B00C - R0013 - Personal Effects Storage - 3.6 m2							
No Asbestos							
B00C - R0014 - External Movement - 4.07 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0015 - Withdrawal Space - 1hb - 21.38 m2							
No Asbestos							
B00C - R0016 - Practical Activities - 1hb - 21.2 m2							
No Asbestos							
B00C - R0017 - General Storeroom - 1.35 m2							
No Asbestos							
B00C - R0018 - Communal/Performance Store - 2.99 m2							
No Asbestos							
B00C - R0019 - General Storeroom - 5.75 m2							
No Asbestos							
B00C - R0020 - External Movement - 1.65 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0021 - Distribution Board - .31 m2							
							Note: No inspection of live electrical installation
Wall Linings Internal	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0022 - Interview - 15.06 m2							
No Asbestos							
B00C - R0023 - General Storeroom - 1.04 m2							
No Asbestos							
B00C - R0024 - Staff Toilet - 4.39 m2							
No Asbestos							
B00C - R0025 - Movement - 1.82 m2							
No Asbestos							
B00C - R0026 - Withdrawal Space - 1hb - 4.36 m2							
No Asbestos							
B00C - R0027 - Movement - 30.4 m2							
No Asbestos							

B00D - General Learning - 1970 - Brick/Veneer

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior

B00D - R0001 - Home Base - 56.63 m2

No Asbestos

B00D - R0002 - Home Base Store - 4.16 m2

No Asbestos

B00D - R0005 - Cleaning Supplies - .5 m2

No Asbestos

B00D - R0006 - External Movement - 1.46 m2

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------	--

B00D - R0007 - Cleaning Distributed Store - .5 m2

No Asbestos

B00D - R0008 - Home Base Store - 4.19 m2

No Asbestos

B00D - R0009 - Home Base - 56.32 m2

No Asbestos

B00D - R0010 - Home Base - 56.16 m2

No Asbestos

B00D - R0011 - Home Base Store - 4.16 m2

No Asbestos

B00D - R0014 - Cleaning Distributed Store - .5 m2

No Asbestos

B00D - R0015 - External Movement - 1.43 m2

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------	--

B00D - R0016 - Cleaning Distributed Store - .5 m2

No Asbestos

B00D - R0017 - Home Base - 56.71 m2

No Asbestos

B00D - R0018 - Home Base Store - 4.16 m2

No Asbestos

B00D - R0019 - Practical Activities/Movement - 2hb - 15.85 m2

No Asbestos

B00D - R0020 - Practical Activities/Movement - 2hb - 15.79 m2

No Asbestos

B00E - Administration/General Learning - 1963 - Brick/Block

Exterior

Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Ceiling Voids	No Asbestos Found							
Underfloor Voids	AC Fragments/Debris							
Interior								
B00E - R0001 - Movement - 4.53 m2								
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00E - R0002 - Movement - 3.27 m2								
No Asbestos								
B00E - R0003 - General Storeroom - 10.46 m2								
No Asbestos								
B00E - R0004 - Movement - 6.57 m2								
No Asbestos								
B00E - R0005 - Staff Kitchen - 21.18 m2								
No Asbestos								
B00E - R0009 - Staff Toilet - 4.24 m2								
Partition Walls (Cubicles)	Compressed AC Sheet							
B00E - R0010 - Movement - 4.85 m2								
No Asbestos								
B00E - R0011 - Staff Toilet - 4.74 m2								
Partition Walls (Cubicles)	Compressed AC Sheet							
B00E - R0013 - Raised Platform - 42.15 m2								
No Asbestos								
B00E - R0014 - General Storeroom - .54 m2								
No Asbestos								
B00E - R0015 - General Storeroom - .54 m2								
No Asbestos								
B00E - R0016 - Security Store - 19.39 m2								
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00E - R0018 - Clerical Office - 20.63 m2								
No Asbestos								
B00E - R0019 - Clerical Office/Workroom - 13.74 m2								
No Asbestos								
B00E - R0020 - General Storeroom - 4.33 m2								
Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00E - R0021 - Movement - 2.47 m2								
No Asbestos								
B00E - R0022 - Sick Bay - 7.12 m2								
No Asbestos								
B00E - R0023 - Principal - 14.44 m2								
No Asbestos								
B00E - R0026 - Staff Room Annexe - 13.5 m2								
No Asbestos								
B00E - R0028 - Cleaning Distributed Store - .61 m2								
No Asbestos								

B00E - R0030 - Entry Vestibule - 24.15 m2							
No Asbestos							
B00E - R0033 - Movement - 4.33 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0034 - Movement - 6.99 m2							
No Asbestos							
B00E - R0035 - Home Base - 56.92 m2							
No Asbestos							
B00E - R0036 - Home Base Store - 5.16 m2							
No Asbestos							
B00E - R0037 - Personal Effects Storage - 4.91 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00E - R0038 - General Storeroom - 2.92 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00E - R0039 - Staff Room Annexe - 15.05 m2							
No Asbestos							
B00E - R0040 - General Assistant/Bulk Store - 27.57 m2							
No Asbestos							
B00E - R0041 - Movement - 1.19 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0042 - Movement - 2.1 m2							
No Asbestos							
B00E - R0043 - Personal Effects Storage - 4.98 m2							
No Asbestos							
B00E - R0044 - Home Base Store - 4.83 m2							
No Asbestos							
B00E - R0045 - Home Base - 56.77 m2							
No Asbestos							
B00E - R0046 - Clerical Office - 57.02 m2							
No Asbestos							
B00E - R0047 - Home Base Store - 5.19 m2							
No Asbestos							
B00E - R0050 - General Storeroom - .52 m2							
No Asbestos							
B00E - R0051 - External Movement - 9.7 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0052 - Movement - 8.84 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0053 - Movement - 3.88 m2							
No Asbestos							
B00E - R0054 - Cleaning Distributed Store - 4.32 m2							
Wall Linings Internal	Flat AC Sheeting						
B00E - R0055 - Staff Toilet - 2.05 m2							

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0056 - Toilet - Lobby - 1.65 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0057 - Toilet - Lobby - 1.67 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0058 - Staff Toilet - 2.05 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0059 - Other - 1.46 m2							
Ceiling Structures/Linings	No Asbestos Found						
B00E - R0060 - External Movement - 3.4 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00E - R0061 - Entry Vestibule - 22.44 m2							
Ceiling Structures/Linings	No Asbestos Found						
B00E - R0062 - Staff Room - 84.79 m2							
Ceiling Structures/Linings	No Asbestos Found						
B00E - R0063 - Movement - 14.13 m2							
Ceiling Structures/Linings	No Asbestos Found						
B00F - General Learning - 1963 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	32	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00F - R0001 - Home Base - 57.36 m2							
No Asbestos							
B00F - R0002 - Home Base Store - 5.71 m2							
No Asbestos							
B00F - R0003 - Personal Effects Storage - 8.2 m2							
No Asbestos							
B00F - R0004 - Movement - 6.96 m2							
No Asbestos							
B00F - R0005 - Home Base - 57.36 m2							
No Asbestos							
B00F - R0006 - Home Base Store - 5.81 m2							
No Asbestos							

B00F - R0007 - Sports Store - 16.73 m2							
No Asbestos							
B00F - R0008 - Home Base - 57.36 m2							
No Asbestos							
B00F - R0009 - Home Base Store - 6.25 m2							
No Asbestos							
B00F - R0010 - Personal Effects Storage - 14.7 m2							
No Asbestos							
B00F - R0011 - Home Base - 57.29 m2							
No Asbestos							
B00F - R0012 - Home Base Store - 6.17 m2							
No Asbestos							
B00F - R0013 - External Movement - 76.01 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	32m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0014 - P.E Store - 16.56 m2							
No Asbestos							
B00H - Library - 1963 - Brick/Block							
Exterior							
No Asbestos							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00H - R0001 - Reading Area - 230.14 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00H - R0003 - K.L.A. Store - 13.01 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00H - R0004 - Distribution Board - 1.77 m2							
Note: No inspection of live electrical installation							
Wall Linings Internal	Compressed AC Sheet	8m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0005 - Special Programs Room - 44.74 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00H - R0006 - Plant - 1.73 m2							
No Asbestos							
B00H - R0007 - Special Programs Store - 4.95 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00H - R0008 - Movement - 2.78 m2							
No Asbestos							
B00H - R0009 - Cleaning Distributed Store - 6.53 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0010 - Toilets - Girls - 6.5 m2							

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0012 - Movement - 3.47 m2							
No Asbestos							
B00H - R0013 - Staff Kitchen - 3.06 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00H - R0014 - Library Office/Workroom - 21.54 m2							
No Asbestos							
B00H - R0015 - Movement - 11.28 m2							
No Asbestos							
B00H - R0016 - External Movement - 138.03 m2							
No Asbestos							
B00J - Pupil Facilities - 1963 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00J - R0001 - Drinking Facilities - 12.73 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0002 - Toilets - Girls - 33.85 m2							
Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00J - R0003 - Cleaning Supplies - 6.58 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00J - R0004 - Toilets - Boys - 41.88 m2							
Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00J - R0005 - Drinking Facilities - 12.78 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0006 - Garden Store - 6.52 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - Pre-School Facilities - 1963 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						

Underfloor Voids	No Asbestos Found							
Interior								
B00K - R0001 - Clerical Office - 13.82 m2								
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - R0002 - Craft Store - 5.69 m2								
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles							
B00K - R0003 - Withdrawal - Pre - 29.76 m2								
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - R0004 - Home Base - Pre - 46.04 m2								
Ceiling Structures/Linings	Flat AC Sheeting	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles							
B00K - R0005 - Personal Effects - Pre - 4.97 m2								
No Asbestos								
B00K - R0006 - Toilets - Boys/Girls - Pre - 5.04 m2								
Wall Linings Internal	Flat AC Sheeting	6m2	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - R0007 - Staff Room - Pre - 23.15 m2								
No Asbestos								
B00K - R0008 - Withdrawal - Pre - 29.79 m2								
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - R0009 - Home Base - Pre - 46.17 m2								
Ceiling Structures/Linings	Flat AC Sheeting	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles							
B00K - R0010 - Personal Effects - Pre - 4.98 m2								
No Asbestos								
B00K - R0011 - Toilets - Boys/Girls - Pre - 4.98 m2								
Wall Linings Internal	Flat AC Sheeting	5m2	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - R0012 - Cleaning Distributed Store - 7.38 m2								
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles							
B00K - R0013 - Distribution Board - .5 m2								
No Asbestos								
B00K - R0015 - Kitchen - Pre - 8.82 m2								
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	

Note: No inspection of live electrical installation

Floor Coverings Res/Textile	Vinyl Tiles							
B00K - R0016 - Entry Vestibule - 36.09 m2								
No Asbestos								
B00K - R0017 - External Movement - 8.32 m2								
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - R0018 - External Movement - 12.04 m2								
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - R0019 - External Movement - 60.28 m2								
Ceiling Structures/Linings	Flat AC Sheeting	61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - R0020 - External Movement - 11.96 m2								
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - R0021 - General Storeroom - 10.4 m2								
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - R0022 - Toilet - Lobby - 1.86 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00K - R0023 - Staff Toilet - 2.18 m2								
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00L - Pupil Facilities - 1963 - Brick/Block								
Exterior								
Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found							
Underfloor Voids	No Asbestos Found							
Interior								
B00L - R0001 - Drinking Facilities - 12.7 m2								
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00L - R0002 - Toilets - Girls - 23.98 m2								
Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00L - R0003 - Handwashing Facilities - 5.59 m2								
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00L - R0004 - P.E Store - 6.5 m2								
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00L - R0005 - Toilets - Boys - 34.31 m2							
Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00L - R0006 - Drinking Facilities - 12.75 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00L - R0007 - Uniform Shop - 6.5 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00M - General Learning - 2004 - Fibre Cement Clad							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00M - R0001 - External Movement - 38.5 m2							
No Asbestos							
B00M - R0002 - Practical Activities - 1hb - 19.39 m2							
No Asbestos							
B00M - R0003 - Home Base Store - 6.01 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00M - R0004 - Home Base - 59.21 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00M - R0005 - Withdrawal Space - 2hb - 11.36 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00M - R0006 - Home Base - 59.2 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00M - R0007 - Home Base Store - 6.01 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00M - R0008 - Practical Activities - 1hb - 19.41 m2							
No Asbestos							
B00N - Communal Facilities/Other - 2009 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00N - R0001 - Communal Space - 203.11 m2							
No Asbestos							
B00N - R0002 - Raised Platform - 62.45 m2							
No Asbestos							
B00N - R0003 - Hall Chair Store - 10.81 m2							
No Asbestos							
B00N - R0004 - Cleaning Distributed Store - 8.07 m2							
No Asbestos							
B00N - R0005 - Toilets - Girls - 10.14 m2							

No Asbestos		
B00N - R0006 - Toilet - Lobby - 2.98 m2		
No Asbestos		
B00N - R0007 - Sound Cupboard - 3.37 m2		
No Asbestos		
B00N - R0008 - Toilets - Boys - 7.43 m2		
No Asbestos		
B00N - R0009 - General Assistant/Bulk Store - 16.53 m2		
No Asbestos		
B00N - R0010 - Communal/Performance Store - 11.22 m2		
No Asbestos		
B00N - R0011 - Distribution Board - 3.23 m2		Note: No inspection of live electrical installation
No Asbestos		
B00N - R0012 - Canteen - 43.86 m2		
No Asbestos		
B00N - R0013 - Canteen Office/Store - 10.27 m2		
No Asbestos		
B00N - R0014 - External Movement - 7.15 m2		
No Asbestos		
B00N - R0015 - Covered Outdoor Learning Area - 223.23 m2		
No Asbestos		
B00N - R0016 - External Movement - 63.94 m2		
No Asbestos		
B00N - R0017 - Toilet - Lobby - 1.86 m2		
No Asbestos		
B00N - R0018 - Movement - 2.27 m2		
No Asbestos		
B00N - R0019 - External Movement - 3.95 m2		
No Asbestos		
B00N - R0020 - Movement - 13.75 m2		
No Asbestos		
B00N - R0021 - Movement - 12.9 m2		
No Asbestos		
B00N - R0022 - Movement - 5.87 m2		
No Asbestos		
B00N - R0023 - Movement - 3.01 m2		
No Asbestos		
B00N - R0024 - External Movement - 6.94 m2		
No Asbestos		
B00N - R0025 - Plant - .8 m2		
No Asbestos		
B00N - R0026 - Access Shower/Toilet - 7.03 m2		
No Asbestos		
B00O - General Learning - 2010 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
No Asbestos		
Interior		
B00O - R0001 - Practical Activities - 1hb - 18.75 m2		

No Asbestos	
B000 - R0002 - Home Base - 59.4 m2	
No Asbestos	
B000 - R0003 - Home Base Store - 6.1 m2	
No Asbestos	
B000 - R0004 - Withdrawal Space - 1hb - 7.68 m2	
No Asbestos	
B000 - R0005 - Practical Activities - 1hb - 18.53 m2	
No Asbestos	
B000 - R0006 - Home Base - 60.39 m2	
No Asbestos	
B000 - R0007 - Home Base Store - 6.27 m2	
No Asbestos	
B000 - R0008 - Withdrawal Space - 2hb - 11.69 m2	
No Asbestos	
B000 - R0009 - Practical Activities - 1hb - 19.63 m2	
No Asbestos	
B000 - R0010 - Home Base - 60.72 m2	
No Asbestos	
B000 - R0011 - Home Base Store - 6.21 m2	
No Asbestos	
B000 - R0012 - Distribution Board - .43 m2	Note: No inspection of live electrical installation
No Asbestos	
B000 - R0013 - External Movement - 91.38 m2	
No Asbestos	
B000 - R0014 - External Stairs - 11.63 m2	
No Asbestos	
B000 - R1001 - Practical Activities - 1hb - 19.49 m2	
No Asbestos	
B000 - R1002 - Home Base - 58.72 m2	
No Asbestos	
B000 - R1003 - Home Base Store - 6.1 m2	
No Asbestos	
B000 - R1004 - Withdrawal Space - 1hb - 7.68 m2	
No Asbestos	
B000 - R1005 - Practical Activities - 1hb - 19.62 m2	
No Asbestos	
B000 - R1006 - Home Base - 60.58 m2	
No Asbestos	
B000 - R1007 - Home Base Store - 6.12 m2	
No Asbestos	
B000 - R1008 - Withdrawal Space - 2hb - 11.81 m2	
No Asbestos	
B000 - R1009 - Practical Activities - 1hb - 19.52 m2	
No Asbestos	
B000 - R1010 - Home Base - 60.63 m2	
No Asbestos	
B000 - R1011 - Home Base Store - 6.13 m2	
No Asbestos	
B000 - R1012 - External Movement - 88.05 m2	
No Asbestos	
B000 - R1013 - External Stairs - 15.32 m2	

No Asbestos							
B0B1 - General Learning - 1963 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B0B1 - R0001 - External Movement - 4.37 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0B1 - R0002 - Staff Toilet - 2.61 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	3m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0B1 - R0003 - Personal Effects Storage - 6.46 m2							
No Asbestos							
B0B1 - R0004 - Home Base - 84.93 m2							
No Asbestos							
B0B1 - R0005 - Home Base Store - 5.71 m2							
No Asbestos							
B0B1 - R0006 - External Movement - 66.4 m2							
No Asbestos							
B0B1 - R0007 - External Movement - 1.37 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0B1 - R0008 - Personal Effects Storage - 3.87 m2							
No Asbestos							
B0B1 - R0009 - Personal Effects Storage - 3.92 m2							
No Asbestos							
B0B1 - R0010 - Movement - 4.72 m2							
No Asbestos							
B0B1 - R0011 - Craft Store - .55 m2							
No Asbestos							
B0B1 - R0012 - Cleaning Distributed Store - .55 m2							
No Asbestos							
B0B1 - R0013 - Home Base - 56.46 m2							
No Asbestos							
B0B1 - R0014 - Home Base Store - 4.71 m2							
No Asbestos							
B0B1 - R0015 - Home Base Store - 4.71 m2							
No Asbestos							
B0B1 - R0016 - Home Base - 57.09 m2							
No Asbestos							

B0B2 - General Learning - 1977 - Brick/Veneer**Exterior**

Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior**B0B2 - R0001 - External Movement - 66.12 m2**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	South, East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
----------------------------	------------------	-----	-------------	--------------------	---------	--------------------	-----------------------------

B0B2 - R0002 - External Movement - 4.6 m2

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------	-----------------------------

B0B2 - R0003 - Personal Effects Storage - 8.37 m2

No Asbestos

B0B2 - R0004 - Home Base Store - 5.36 m2

No Asbestos

B0B2 - R0005 - Home Base - 84.85 m2

No Asbestos

B0B2 - R0007 - Home Base - 56.31 m2

No Asbestos

B0B2 - R0008 - Home Base Store - 5.43 m2

No Asbestos

B0B2 - R0009 - Personal Effects Storage - 6.67 m2

No Asbestos

B0B2 - R0010 - External Movement - 1.18 m2

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------	-----------------------------

B0B2 - R0011 - Toilet - Lobby - 2.22 m2

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------	--

B0B2 - R0012 - Toilets-Unisex - 2.24 m2

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------	--

B0G1 - General Learning/Support Unit - 1963 - Timber**Exterior**

Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						

Interior**B0G1 - R0001 - Home Base - 52.7 m2**

No Asbestos

B0G1 - R0002 - Home Base - M - 52.7 m2

No Asbestos

B0G1 - R0003 - Out Of School Hours Care Centre - 47.28 m2		
No Asbestos		
B0G1 - R0004 - External Movement - 50.25 m2		
No Asbestos		
B0G2 - General Learning - 1963 - Timber		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B0G2 - R0001 - External Movement - 11.79 m2		
No Asbestos		
B0G2 - R0002 - Special Programs Room - 47.29 m2		
No Asbestos		

Demountables**OS 601 10148 - Learning Unit - Standard/Withdrawal - Placement Date : 11-JUN-2003****Exterior**

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior**R1- Entry**

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos

R2- General Learning Space

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

R3- Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
----------------------------	------------------	------	------------------

OS 602 10227 - Learning Unit - Standard With P.A.A. - Placement Date : 04-DEC-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 601 10409 - Learning Unit - Standard/Withdrawal - Placement Date : 22-AUG-2001**Exterior**

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior**R1- Entry**

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos

R2- General Learning Space

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

R3- Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
----------------------------	------------------	------	------------------

OS 601 10702 - Learning Unit - Standard/Withdrawal - Placement Date : 04-JAN-2003**Exterior**

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior**R1- Entry**

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos

R2- General Learning Space

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

R3- Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
----------------------------	------------------	------	------------------

OS 602 11137 - Learning Unit - Standard With P.A.A. - Placement Date : 09-JAN-2006**Exterior**

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
---------------	------------------	---------	------------------

Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Learning space/withdrawal/entry			
Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
R2- Home Base Store			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos
OS 601 11140 - Learning Unit - Standard/Withdrawal - Placement Date : 05-JAN-2006			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 601 11358 - Learning Unit - Standard/Withdrawal - Placement Date : 30-DEC-2004			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 601 11533 - Learning Unit - Standard/Withdrawal - Placement Date : 05-FEB-1997			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 601 11790 - Learning Unit - Standard/Withdrawal - Placement Date : 23-DEC-1999			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 601 11818 - Learning Unit - Standard/Withdrawal - Placement Date : 03-JAN-2002			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 601 11964 - Learning Unit - Standard/Withdrawal - Placement Date : 22-AUG-2001			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 601 12158 - Learning Unit - Standard/Withdrawal - Placement Date : 25-JAN-1996			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			

R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 601 12436 - Learning Unit - Standard/Withdrawal - Placement Date : 13-MAY-1997			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 601 14846 - Learning Unit - Standard/Withdrawal - Placement Date : 23-DEC-1999			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 606 19162 - Learning Unit - Standard With P.A.A A/C - Placement Date : 01-FEB-2018			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 751 70034 - Learning Unit - ESL - Placement Date : 22-FEB-1996			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Esl			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Assumed Asbestos
R2- Esl			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos

Ceiling Structures/Linings	Flat AC Sheeting	36m2	Assumed Asbestos
----------------------------	------------------	------	------------------