

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Inner Sydney High School (8913)
Region:	Sydney AMU
State Electorate:	
Local Government Area:	Sydney

Last Reviewed By:	
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B1 - General Learning - 1856 - Brick/Block							
Exterior							
							Require Inspection
Interior							
	B1 - 1.1 - Movement - 140.23 m2						Require Inspection
	B1 - 1.10 - Seminar - 32.08 m2						Require Inspection
	B1 - 1.11 - Administration - Clerical - 20.26 m2						Require Inspection
	B1 - 1.12 - Stairs - 6.26 m2						Require Inspection
	B1 - 1.13 - Stairs - 16.19 m2						Require Inspection
	B1 - 1.14 - Independent Learning Space - 16.96 m2						Require Inspection
	B1 - 1.15 - General Learning Space - 41.52 m2						Require Inspection
	B1 - 1.16 - Stairs - 9.35 m2						Require Inspection
	B1 - 1.17 - Distribution Board Cupboard - .48 m2						Require Inspection Note: No inspection of live electrical installation
	B1 - 1.2 - General Storeroom - 3.13 m2						Require Inspection
	B1 - 1.3 - Science Laboratory - 113.06 m2						Require Inspection
	B1 - 1.4 - Chemical Store - 3.16 m2						Require Inspection
	B1 - 1.5 - General Learning Space - 47.86 m2						Require Inspection
	B1 - 1.6 - General Storeroom - 11.36 m2						Require Inspection
	B1 - 1.7 - General Learning Space - 51.2 m2						Require Inspection
	B1 - 1.8 - General Learning Space - 54.26 m2						Require Inspection
	B1 - 1.9 - Preparation - 17.47 m2						Require Inspection
	B1 - G.1 - Movement - 143.1 m2						Require Inspection
	B1 - G.10 - General Storeroom - 19.39 m2						Require Inspection
	B1 - G.11 - Stairs - 2.58 m2						Require Inspection
	B1 - G.12 - Stairs - 2.58 m2						Require Inspection
	B1 - G.13 - Independent Learning Space - 15.42 m2						Require Inspection
	B1 - G.14 - Stairs - 6.39 m2						Require Inspection

B1 - G15 - Stairs - 5.86 m2	
Require Inspection	
B1 - G16 - Movement - 2.12 m2	
Require Inspection	
B1 - G17 - External Movement - 10.82 m2	
Require Inspection	
B1 - G2 - Science Laboratory - 136.47 m2	
Require Inspection	
B1 - G3 - General Learning Space - 41.59 m2	
Require Inspection	
B1 - G4 - General Learning Space - 48.24 m2	
Require Inspection	
B1 - G5 - Interview/Meeting - 11.23 m2	
Require Inspection	
B1 - G6 - General Learning Space - 50.72 m2	
Require Inspection	
B1 - G7 - General Learning Space - 55.05 m2	
Require Inspection	
B1 - G8 - Distribution Board Cupboard - .5 m2	Note: No inspection of live electrical installation
Require Inspection	
B1 - G9 - Seminar - 31.44 m2	
Require Inspection	
B1 - LG1.1 - Sport Equipment Store - 36.46 m2	
Require Inspection	
B1 - LG1.10 - Cleaning Store - Distributed - 6.51 m2	
Require Inspection	
B1 - LG1.11 - Plant - 12.04 m2	
Require Inspection	
B1 - LG1.12 - Plant - .59 m2	
Require Inspection	
B1 - LG1.13 - Stairs - 5.57 m2	
Require Inspection	
B1 - LG1.14 - Movement - 17.29 m2	
Require Inspection	
B1 - LG1.15 - Movement - 30.29 m2	
Require Inspection	
B1 - LG1.16 - Distribution Board Cupboard - 1.24 m2	Note: No inspection of live electrical installation
Require Inspection	
B1 - LG1.17 - External Movement - 17.16 m2	
Require Inspection	
B1 - LG1.18 - Stairs - 10.2 m2	
Require Inspection	
B1 - LG1.19 - Plant - 138.52 m2	
Require Inspection	
B1 - LG1.2 - Plant - 8.9 m2	
Require Inspection	
B1 - LG1.3 - Movement - 9.55 m2	
Require Inspection	
B1 - LG1.4 - Movement - 16.87 m2	
Require Inspection	
B1 - LG1.5 - Garden Store Room - 19.67 m2	
Require Inspection	

B1 - LG1.6 - Bulk Store - 26.85 m2
Require Inspection
B1 - LG1.7 - Archive Store - 55.78 m2
Require Inspection
B1 - LG1.8 - Uniform Shop - 38.66 m2
Require Inspection
B1 - LG1.9 - Plant - 16.14 m2
Require Inspection
B1 - M.1 - Movement - 4.65 m2
Require Inspection
B1 - M.2 - Toilets-Girls - 20.67 m2
Require Inspection
B1 - M.3 - Stairs - 5.27 m2
Require Inspection
B1 - M.4 - Stairs - 2.67 m2
Require Inspection
B2 - General Learning - 1867 - Brick/Block
Exterior
Require Inspection
Interior
B2 - 1.1 - Staff Study - 75.77 m2
Require Inspection
B2 - 1.10 - Interview/Meeting - 15.01 m2
Require Inspection
B2 - 1.11 - Stairs - 17.2 m2
Require Inspection
B2 - 1.12 - Stairs - 15.3 m2
Require Inspection
B2 - 1.13 - Movement - 4.69 m2
Require Inspection
B2 - 1.2 - Interview/Meeting - 10.49 m2
Require Inspection
B2 - 1.3 - Toilets-Unisex - 6.4 m2
Require Inspection
B2 - 1.4 - Interview/Meeting - 7.92 m2
Require Inspection
B2 - 1.5 - Staff Kitchen - 19.15 m2
Require Inspection
B2 - 1.6 - Administration - Executive - 26.28 m2
Require Inspection
B2 - 1.7 - Interview/Meeting - 9.27 m2
Require Inspection
B2 - 1.8 - Principal Office - 12.1 m2
Require Inspection
B2 - 1.9 - Movement - 81.02 m2
Require Inspection
B2 - G1 - Staff Study - 71.81 m2
Require Inspection
B2 - G10 - Interview/Meeting - 11.72 m2
Require Inspection
B2 - G11 - Clinic - 14.3 m2

Require Inspection	
B2 - G.12 - Clinic - 14.14 m2	
Require Inspection	
B2 - G.13 - Public Reception - 31.23 m2	
Require Inspection	
B2 - G.14 - Student Waiting - 13.37 m2	
Require Inspection	
B2 - G.15 - Toilets-Unisex - 7.74 m2	
Require Inspection	
B2 - G.16 - Cleaning Store - Distributed - 2.9 m2	
Require Inspection	
B2 - G.17 - Toilets-Unisex - 3.9 m2	
Require Inspection	
B2 - G.18 - Distribution Board Cupboard - .4 m2	Note: No inspection of live electrical installation
Require Inspection	
B2 - G.19 - Movement - 77.15 m2	
Require Inspection	
B2 - G.2 - Movement - 10.81 m2	
Require Inspection	
B2 - G.20 - Chair Store - 2.08 m2	
Require Inspection	
B2 - G.21 - Study Space - 2.97 m2	
Require Inspection	
B2 - G.22 - Chair Store - 3.83 m2	
Require Inspection	
B2 - G.23 - Study Space - 4.33 m2	
Require Inspection	
B2 - G.24 - Staff Kitchen - 11.44 m2	
Require Inspection	
B2 - G.25 - Stairs - 4.74 m2	
Require Inspection	
B2 - G.26 - Distribution Board Cupboard - .24 m2	Note: No inspection of live electrical installation
Require Inspection	
B2 - G.27 - Movement - 6.51 m2	
Require Inspection	
B2 - G.28 - Stairs - 4.91 m2	
Require Inspection	
B2 - G.29 - Stairs - 7.14 m2	
Require Inspection	
B2 - G.3 - Printing/Photocopying - 12.91 m2	
Require Inspection	
B2 - G.4 - Store - 7.48 m2	
Require Inspection	
B2 - G.5 - Multi-Purpose Space - 123.22 m2	
Require Inspection	
B2 - G.6 - Stairs - 3.45 m2	
Require Inspection	
B2 - G.7 - Store - 10.9 m2	
Require Inspection	
B2 - G.8 - Administration - Clerical - 19.6 m2	
Require Inspection	
B2 - G.9 - Utility Space - 7.47 m2	

Require Inspection
B2 - LG1.1 - Change - 27.01 m2
Require Inspection
B2 - LG1.10 - Plant - 9.98 m2
Require Inspection
B2 - LG1.11 - Fitness Laboratory - 160.15 m2
Require Inspection
B2 - LG1.12 - Toilets-Unisex - 6.62 m2
Require Inspection
B2 - LG1.13 - Toilets-Disabled - 2.5 m2
Require Inspection
B2 - LG1.14 - Movement - 15.42 m2
Require Inspection
B2 - LG1.15 - Movement - 10.18 m2
Require Inspection
B2 - LG1.16 - Plant - .34 m2
Require Inspection
B2 - LG1.17 - Movement - 13.16 m2
Require Inspection
B2 - LG1.2 - Change - 26.23 m2
Require Inspection
B2 - LG1.3 - Toilets-Disabled - 7.11 m2
Require Inspection
B2 - LG1.4 - Plant - 9.38 m2
Require Inspection
B2 - LG1.5 - Distribution Board Cupboard - .34 m2
Note: No inspection of live electrical installation
Require Inspection
B2 - LG1.6 - Movement - 27.85 m2
Require Inspection
B2 - LG1.7 - Stairs - 5.36 m2
Require Inspection
B2 - LG1.8 - Sport Equipment Store - 163.59 m2
Require Inspection
B2 - LG1.9 - Sport Equipment Store - 13.53 m2
Require Inspection
B3 - General Learning - 1924 - Brick/Block
Exterior
Require Inspection
Interior
B3 - 1.1 - Resources - 52.37 m2
Require Inspection
B3 - 1.10 - Distribution Board Cupboard - 1.14 m2
Note: No inspection of live electrical installation
Require Inspection
B3 - 1.2 - Movement - 51.28 m2
Require Inspection
B3 - 1.3 - General Learning Space - 47.42 m2
Require Inspection
B3 - 1.4 - Practical Activities - 46.84 m2
Require Inspection
B3 - 1.5 - Staff - Toilet - 2.26 m2
Require Inspection

B3 - 1.6 - Toilets-Disabled - 5.59 m2	
Require Inspection	
B3 - 1.7 - Stairs - 12.37 m2	
Require Inspection	
B3 - 1.8 - Stairs - 12.2 m2	
Require Inspection	
B3 - 1.9 - Plant - 1.5 m2	
Require Inspection	
B3 - G1 - Resources Space - 52.66 m2	
Require Inspection	
B3 - G10 - Stairs - 9.05 m2	
Require Inspection	
B3 - G11 - Stairs - 4.14 m2	
Require Inspection	
B3 - G2 - Movement - 42.54 m2	
Require Inspection	
B3 - G3 - General Learning Space - 80.2 m2	
Require Inspection	
B3 - G4 - Practice/Seminar - 15.21 m2	
Require Inspection	
B3 - G5 - Practice/Seminar - 14.27 m2	
Require Inspection	
B3 - G6 - Plant - 1.19 m2	
Require Inspection	
B3 - G7 - Distribution Board Cupboard - 1.51 m2	Note: No inspection of live electrical installation
Require Inspection	
B3 - G8 - Stairs - 10.09 m2	
Require Inspection	
B3 - G9 - Stairs - 4.61 m2	
Require Inspection	
B3 - LG1.1 - Music Learning Space - 49.4 m2	
Require Inspection	
B3 - LG1.10 - Stairs - 4.7 m2	
Require Inspection	
B3 - LG1.11 - Stairs - 4.13 m2	
Require Inspection	
B3 - LG1.12 - Distribution Board Cupboard - 1.23 m2	Note: No inspection of live electrical installation
Require Inspection	
B3 - LG1.13 - External Movement - .99 m2	
Require Inspection	
B3 - LG1.2 - Movement - 74.91 m2	
Require Inspection	
B3 - LG1.3 - Cleaning Store - Distributed - 2.45 m2	
Require Inspection	
B3 - LG1.4 - Performance Workspace - 76.14 m2	
Require Inspection	
B3 - LG1.5 - Music Store - 14.04 m2	
Require Inspection	
B3 - LG1.6 - Music Store - 5.9 m2	
Require Inspection	
B3 - LG1.7 - Plant - 8.21 m2	
Require Inspection	

B3 - LG1.8 - Practical Activities - 89.12 m2

Require Inspection

B3 - LG1.9 - Movement - 8.62 m2

Require Inspection

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020