

# Asbestos Register

(Hazardous Materials and Risk Assessment)

|                        |                                 |
|------------------------|---------------------------------|
| School:                | James Meehan High School (8497) |
| Region:                | South Western Sydney AMU        |
| State Electorate:      | Macquarie Fields                |
| Local Government Area: | Campbelltown                    |

|                   |                      |
|-------------------|----------------------|
| Last Reviewed By: | Greencap 26-AUG-2014 |
| Last Revised By:  |                      |

|  |           |
|--|-----------|
| Historical Fibro In Grounds Investigations/Events  | <b>No</b> |
| <p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p> |           |



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

| Rating                     | Description  |
|----------------------------|--|
| Good condition (1)         | For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles  |
| Minimal damage (2)         | For non-friable asbestos that has a very small amount of damage, eg hairline cracks.   |
| Some damage / unsealed (3) | For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed. |
| Poor condition (4)         | For non-friable asbestos that has extensive damage. Visible asbestos debris  |
| Friable asbestos (5)       | Any occurrence of friable asbestos   |

| Product   | Material Description                                    | Extent | Location   | Material Condition | Risk Status | Remediation Priority                                       | Result                      |
|---|---|--------|------------|--------------------|-------------|--|-----------------------------|
| <b>B001 - Technological &amp; Applied Studies/Pupil Facilities - 1975 - Brick/Block</b> |   |        |            |                    |             |  |                             |
| <b>Exterior</b>   |   |        |            |                    |             |  |                             |
| Ceiling Voids - Raked Ceiling   | Non Accessible Area                                     |        |            |                    |             |  |                             |
| Underfloor Voids - Slab on Ground   | Non Accessible Area                                     |        |            |                    |             |  |                             |
| <b>Interior</b>   |   |        |            |                    |             |  |                             |
| <b>B001 - R0003 - Materials Store - 7.94 m2</b>   |   |        |            |                    |             |  |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 8m2    | Throughout | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) |
| <b>B001 - R0009 - Distribution Board Cupboard - 2.74 m2</b>                             |   |        |            |                    |             | <b>Note: No inspection of live electrical installation</b> |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 3m2    | Throughout | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) |
| <b>B001 - R0010 - Cleaning Store - Distributed - 1.67 m2</b>                            |   |        |            |                    |             |  |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 2m2    | Throughout | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) |
| <b>B001 - R0012 - Toilets-Boys - 68.4 m2</b>  |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0015 - Art Learning Space - 64.21 m2</b>                                     |   |        |            |                    |             |  |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |        |            |                    |             |  |                             |
| <b>B001 - R0016 - Kiln Space - 12.69 m2</b>   |   |        |            |                    |             |  |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |        |            |                    |             |  |                             |
| <b>B001 - R0017 - External Movement - 1.68 m2</b>                                       |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0018 - External Movement - .99 m2</b>  |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0019 - External Movement - .87 m2</b>  |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0020 - External Movement - 18.27 m2</b>                                      |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0021 - Movement - 25.65 m2</b>   |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0022 - Project Store - Type 1 - 29.75 m2</b>                                 |   |        |            |                    |             |  |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |        |            |                    |             |  |                             |
| <b>B001 - R0023 - Metal Technology L.S. - 149.57 m2</b>                                 |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0024 - Materials Store - Type 1 - 11.06 m2</b>                               |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0025 - Materials Store - Type 1 - 23.16 m2</b>                               |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0026 - Welding Area - 4.24 m2</b>  |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0027 - Welding Area - 4.26 m2</b>  |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R0028 - Welding Area - 4.36 m2</b>  |   |        |            |                    |             |  |                             |
| No Asbestos   |   |        |            |                    |             |  |                             |
| <b>B001 - R1001 - General Storeroom - 26 m2</b>   |   |        |            |                    |             |  |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 27m2   | Throughout | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) |

|  |  |      |            |                    |         |  |                             |  |
|--|--|------|------------|--------------------|---------|--|-----------------------------|--|
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |  |                             |  |
| <b>B001 - R1002 - Staff Study - 52.8 m2</b>                            |  |      |            |                    |         |  |                             |  |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |  |                             |  |
| <b>B001 - R1003 - Cleaning Store - Distributed - .82 m2</b>            |  |      |            |                    |         |  |                             |  |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )     |      |            |                    |         |  |                             |  |
| <b>B001 - R1004 - Wood Technology L.S. - 82.84 m2</b>                  |  |      |            |                    |         |  |                             |  |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |                    |         |  |                             |  |
| <b>B001 - R1005 - Materials Store - 13.69 m2</b>                       |  |      |            |                    |         |  |                             |  |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |  |                             |  |
| <b>B001 - R1006 - Plant - 6.05 m2</b>                                  |  |      |            |                    |         |  |                             |  |
| No Asbestos  |  |      |            |                    |         |  |                             |  |
| <b>B001 - R1009 - Distribution Board Cupboard - .9 m2</b>              |  |      |            |                    |         |  |                             |  |
|  |  |      |            |                    |         | <b>Note: No inspection of live electrical installation</b> |                             |  |
| Floor Coverings Res/Textile  | Vinyl Tiles  | 1m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)   | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )     |      |            |                    |         |  |                             |  |
| <b>B001 - R1010 - Resources Store - 12.81 m2</b>                       |  |      |            |                    |         |  |                             |  |
| Floor Coverings Res/Textile  | Vinyl Tiles  | 13m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)   | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |  |                             |  |
| <b>B001 - R1011 - General Learning Space - 52.56 m2</b>                |  |      |            |                    |         |  |                             |  |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |  |                             |  |
| <b>B001 - R1012 - Movement - 64.2 m2</b>                               |  |      |            |                    |         |  |                             |  |
| Floor Coverings Res/Textile  | Vinyl Tiles  | 65m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)   | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |  |                             |  |
| <b>B001 - R1013 - Wood Technology L.S. - 94.04 m2</b>                  |  |      |            |                    |         |  |                             |  |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |                    |         |  |                             |  |
| <b>B001 - R1014 - External Movement - 1.98 m2</b>                      |  |      |            |                    |         |  |                             |  |
| No Asbestos  |  |      |            |                    |         |  |                             |  |
| <b>B001 - R1015 - External Movement - 13.16 m2</b>                     |  |      |            |                    |         |  |                             |  |
| No Asbestos  |  |      |            |                    |         |  |                             |  |
| <b>B001 - R1016 - External Movement - 4.3 m2</b>                       |  |      |            |                    |         |  |                             |  |
| No Asbestos  |  |      |            |                    |         |  |                             |  |
| <b>B002 - Physical Education/Pupil Facilities - 1975 - Brick/Block</b> |  |      |            |                    |         |  |                             |  |
| <b>Exterior</b>  |  |      |            |                    |         |  |                             |  |
| Underfloor Voids - Slab on Ground                                      | Non Accessible Area                                      |      |            |                    |         |  |                             |  |
| Ceiling Voids - Raked Ceiling  | Non Accessible Area                                      |      |            |                    |         |  |                             |  |
| <b>Interior</b>  |  |      |            |                    |         |  |                             |  |
| <b>B002 - R0001 - Gymnasium - 308.87 m2</b>                            |  |      |            |                    |         |  |                             |  |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( > 250 m2) - ( X25 )   |      |            |                    |         |  |                             |  |
| <b>B002 - R0002 - Sport Equipment Store - 34.28 m2</b>                 |  |      |            |                    |         |  |                             |  |
| No Asbestos  |  |      |            |                    |         |  |                             |  |
| <b>B002 - R0003 - Plant - .78 m2</b>                                   |  |      |            |                    |         |  |                             |  |

|   |  |      |            |                    |         |                    |                             |
|---|--|------|------------|--------------------|---------|--------------------|-----------------------------|
| Electrical - Backing Board                                  | Resinous Board   | 1    | South      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B002 - R0004 - Machine Storage - 15.56 m2</b>            |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0005 - Cleaning Store - Distributed - .99 m2</b> |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0006 - Sport Equipment Store - 20.42 m2</b>      |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0007 - Movement - 79.55 m2</b>                   |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 80m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |                    |         |                    |                             |
| <b>B002 - R0008 - Main Switchroom - 10.29 m2</b>            |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0009 - Pantry - 6.26 m2</b>                      |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )     |      |            |                    |         |                    |                             |
| <b>B002 - R0010 - Other-Vacant - .92 m2</b>                 |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0011 - Student Canteen - 55.62 m2</b>            |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B002 - R0012 - Staff - Toilet - 4.01 m2</b>              |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0013 - Cleaning Supplies Store - 5.73 m2</b>     |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 7m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B002 - R0014 - Staff - Toilet - 3.22 m2</b>              |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0015 - General Storeroom - 52.94 m2</b>          |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0016 - General Storeroom - 7.19 m2</b>           |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0017 - External Movement - 3.1 m2</b>            |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0018 - External Movement - 3.07 m2</b>           |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0019 - External Movement - 3.09 m2</b>           |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0020 - External Movement - 3.07 m2</b>           |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0021 - General Storeroom - 7.19 m2</b>           |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0022 - External Stairs - .67 m2</b>              |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0023 - External Movement - 5.18 m2</b>           |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0024 - External Movement - 14.55 m2</b>          |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0025 - External Movement - 37.69 m2</b>          |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B002 - R0026 - External Stairs - .42 m2</b>              |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |

|  |   |      |            |                    |         |                    |                             |
|--|---|------|------------|--------------------|---------|--------------------|-----------------------------|
| <b>B002 - R0027 - General Storeroom - 19.13 m2</b>                           |   |      |            |                    |         |                    |                             |
| No Asbestos  |   |      |            |                    |         |                    |                             |
| <b>B002 - R0028 - General Storeroom - 18.56 m2</b>                           |   |      |            |                    |         |                    |                             |
| No Asbestos  |   |      |            |                    |         |                    |                             |
| <b>B002 - R1001 - Toilets-Girls - 62.86 m2</b>                               |   |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings   | Compressed AC Sheet                                     | 64m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B002 - R1002 - Toilets-Boys - 63.09 m2</b>                                |   |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings   | Compressed AC Sheet                                     | 64m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B002 - R1003 - Plant - 3.36 m2</b>  |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles   | 4m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )    |      |            |                    |         |                    |                             |
| Plant / Equipment - Flue   | Fibre Cement Pipe                                       | 1    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B002 - R1006 - Staff - Toilet - 7.8 m2</b>                                |   |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings   | Compressed AC Sheet                                     | 8m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B002 - R1008 - Plant - 3.36 m2</b>  |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles   | 4m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings   | Compressed AC Sheet                                     | 4m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Plant / Equipment - Flue   | Fibre Cement Pipe                                       | 1    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B002 - R1009 - Movement - 66.26 m2</b>                                    |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles   | 67m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |      |            |                    |         |                    |                             |
| <b>B002 - R1010 - External Stairs - 7.94 m2</b>                              |   |      |            |                    |         |                    |                             |
| No Asbestos  |   |      |            |                    |         |                    |                             |
| <b>B002 - R1011 - External Movement - 33.88 m2</b>                           |   |      |            |                    |         |                    |                             |
| No Asbestos  |   |      |            |                    |         |                    |                             |
| <b>B002 - R1012 - General Storeroom - 7.21 m2</b>                            |   |      |            |                    |         |                    |                             |
| No Asbestos  |   |      |            |                    |         |                    |                             |
| <b>B002 - R1013 - Staff Shower - 1.63 m2</b>                                 |   |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings   | Compressed AC Sheet                                     | 2m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B002 - R1014 - Staff - Toilet - 8.21 m2</b>                               |   |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings   | Compressed AC Sheet                                     | 9m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B002 - R1015 - Staff Shower - 1.65 m2</b>                                 |   |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )    |      |            |                    |         |                    |                             |
| <b>B002 - R1016 - Sport Equipment Store - 7.21 m2</b>                        |   |      |            |                    |         |                    |                             |
| No Asbestos  |   |      |            |                    |         |                    |                             |
| <b>B002 - R1017 - External Movement - 29.08 m2</b>                           |   |      |            |                    |         |                    |                             |
| No Asbestos  |   |      |            |                    |         |                    |                             |
| <b>B002 - R1018 - External Stairs - 8.18 m2</b>                              |   |      |            |                    |         |                    |                             |
| No Asbestos  |   |      |            |                    |         |                    |                             |
| <b>B003 - Technological &amp; Applied Studies/Music - 1975 - Brick/Block</b> |   |      |            |                    |         |                    |                             |
| Exterior   |   |      |            |                    |         |                    |                             |

|  |  |      |            |                    |         |                    |                             |  |
|--|--|------|------------|--------------------|---------|--------------------|-----------------------------|--|
| Ceiling Voids - Raked Ceiling                                | Non Accessible Area                                      |      |            |                    |         |                    |                             |  |
| Underfloor Voids - Slab on Ground                            | Non Accessible Area                                      |      |            |                    |         |                    |                             |  |
| <b>Interior</b>  |  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0001 - Toilets-Girls - 65.58 m2</b>               |  |      |            |                    |         |                    |                             |  |
| Partition Walls (Cubicles)                                   | Compressed AC Sheet                                      | 28m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B003 - R0002 - Food Technology L.S. - 82.77 m2</b>        |  |      |            |                    |         |                    |                             |  |
| No Asbestos  |  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0008 - Design/Technology L.S. - 65.67 m2</b>      |  |      |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0009 - Resources Store - 9.92 m2</b>              |  |      |            |                    |         |                    |                             |  |
| No Asbestos  |  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0010 - Cleaning Store - Distributed - 5.37 m2</b> |  |      |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 6m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B003 - R0011 - Staff Study - 32.05 m2</b>                 |  |      |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 33m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0012 - General Assistants - 4.56 m2</b>           |  |      |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 5m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )     |      |            |                    |         |                    |                             |  |
| <b>B003 - R0013 - General Assistants - 18.16 m2</b>          |  |      |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 19m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B003 - R0014 - Distribution Board Cupboard - .82 m2</b>   |  |      |            |                    |         |                    |                             |  |
| <b>Note: No inspection of live electrical installation</b>   |  |      |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 1m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )     |      |            |                    |         |                    |                             |  |
| <b>B003 - R0015 - Movement - 73.87 m2</b>                    |  |      |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 74m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B003 - R0018 - Food Technology L.S. - 81.65 m2</b>        |  |      |            |                    |         |                    |                             |  |
| No Asbestos  |  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0020 - Food Technology L.S. - 43.43 m2</b>        |  |      |            |                    |         |                    |                             |  |
| No Asbestos  |  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0021 - Preparation - Materials - 27.58 m2</b>     |  |      |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0022 - Laundry - 1.56 m2</b>                      |  |      |            |                    |         |                    |                             |  |
| No Asbestos  |  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0023 - Plant - .99 m2</b>                         |  |      |            |                    |         |                    |                             |  |
| No Asbestos  |  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0024 - External Movement - 2.02 m2</b>            |  |      |            |                    |         |                    |                             |  |
| No Asbestos  |  |      |            |                    |         |                    |                             |  |
| <b>B003 - R0025 - External Movement - .99 m2</b>             |  |      |            |                    |         |                    |                             |  |

|   |  |      |            |                    |         |                    |                             |
|---|--|------|------------|--------------------|---------|--------------------|-----------------------------|
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B003 - R0026 - External Movement - 2.19 m2</b>           |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B003 - R0027 - External Movement - 13.05 m2</b>          |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B003 - R1001 - Music Learning Space - 65.33 m2</b>       |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B003 - R1002 - Music Learning Space - 65.07 m2</b>       |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B003 - R1003 - Staff Study - 31.22 m2</b>                |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |                    |                             |
| <b>B003 - R1004 - Art Learning Space - 64.35 m2</b>         |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B003 - R1005 - Visual Arts Store - 13.74 m2</b>          |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 14m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |                    |                             |
| <b>B003 - R1006 - Art Learning Space - 65.71 m2</b>         |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 66m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B003 - R1007 - Art Learning Space - 69.19 m2</b>         |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 70m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B003 - R1008 - Distribution Board Cupboard - .6 m2</b>   |  |      |            |                    |         |                    |                             |
| <b>Note: No inspection of live electrical installation</b>  |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 1m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Electrical - Backing Board                                  | Resinous Board   | 1    | East       | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B003 - R1009 - Movement - 77.36 m2</b>                   |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 77m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |                    |         |                    |                             |
| <b>B003 - R1010 - Music Learning Space - 65.65 m2</b>       |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B003 - R1011 - External Movement - 1.74 m2</b>           |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B003 - R1012 - External Movement - 12.79 m2</b>          |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B004 - Library/Science Learning - 1975 - Brick/Block</b> |  |      |            |                    |         |                    |                             |
| <b>Exterior</b>   |  |      |            |                    |         |                    |                             |
| Ceiling Voids - Raked Ceiling                               | Non Accessible Area                                      |      |            |                    |         |                    |                             |
| Underfloor Voids - Slab on Ground                           | Non Accessible Area                                      |      |            |                    |         |                    |                             |
| <b>Interior</b>   |  |      |            |                    |         |                    |                             |
| <b>B004 - M1001 - Study Space - 149.34 m2</b>               |  |      |            |                    |         |                    |                             |



|  |  |        |            |                    |         |                    |                             |  |
|--|--|--------|------------|--------------------|---------|--------------------|-----------------------------|--|
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 120 - 250 m2) - ( X15 ) |        |            |                    |         |                    |                             |  |
| <b>B004 - M1002 - Study Space - 22.36 m2</b>               |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )    |        |            |                    |         |                    |                             |  |
| <b>B004 - M1003 - General Storeroom - 23.05 m2</b>         |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )    |        |            |                    |         |                    |                             |  |
| <b>B004 - M1004 - Stairs - 2.8 m2</b>                      |  |        |            |                    |         |                    |                             |  |
| No Asbestos  |  |        |            |                    |         |                    |                             |  |
| <b>B004 - M1005 - Stairs - 2.96 m2</b>                     |  |        |            |                    |         |                    |                             |  |
| No Asbestos  |  |        |            |                    |         |                    |                             |  |
| <b>B004 - R0001 - Laboratory L.S. - 90.94 m2</b>           |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )   |        |            |                    |         |                    |                             |  |
| <b>B004 - R0002 - Preparation - Science - 49.04 m2</b>     |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )    |        |            |                    |         |                    |                             |  |
| <b>B004 - R0003 - Laboratory L.S. - 90.54 m2</b>           |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )   |        |            |                    |         |                    |                             |  |
| <b>B004 - R0004 - Distribution Board Cupboard - .96 m2</b> |  |        |            |                    |         |                    |                             |  |
| <b>Note: No inspection of live electrical installation</b> |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Flat AC Sheeting   | 0.96m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Electrical - Backing Board                                 | Resinous Board   | 0.3    | North      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B004 - R0005 - Laboratory L.S. - 90.95 m2</b>           |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )   |        |            |                    |         |                    |                             |  |
| <b>B004 - R0006 - Staff Study - 49.1 m2</b>                |  |        |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                                | Vinyl Tiles  | 50m2   | South      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )    |        |            |                    |         |                    |                             |  |
| <b>B004 - R0007 - Laboratory L.S. - 90.75 m2</b>           |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )   |        |            |                    |         |                    |                             |  |
| <b>B004 - R0008 - Movement - 58.66 m2</b>                  |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Flat AC Sheeting   | 60m2   | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B004 - R0009 - Plant - 14.03 m2</b>                     |  |        |            |                    |         |                    |                             |  |
| No Asbestos  |  |        |            |                    |         |                    |                             |  |
| <b>B004 - R0010 - External Movement - 2.21 m2</b>          |  |        |            |                    |         |                    |                             |  |
| No Asbestos  |  |        |            |                    |         |                    |                             |  |
| <b>B004 - R0011 - External Movement - 57.49 m2</b>         |  |        |            |                    |         |                    |                             |  |
| No Asbestos  |  |        |            |                    |         |                    |                             |  |
| <b>B004 - R0012 - External Movement - 2.02 m2</b>          |  |        |            |                    |         |                    |                             |  |
| No Asbestos  |  |        |            |                    |         |                    |                             |  |
| <b>B004 - R0013 - External Movement - 18.37 m2</b>         |  |        |            |                    |         |                    |                             |  |
| No Asbestos  |  |        |            |                    |         |                    |                             |  |
| <b>B004 - R1003 - Seminar/Study - 13.33 m2</b>             |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )    |        |            |                    |         |                    |                             |  |
| <b>B004 - R1004 - Seminar/Study - 13.05 m2</b>             |  |        |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                 | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )    |        |            |                    |         |                    |                             |  |
| <b>B004 - R1005 - Plant - .48 m2</b>                       |  |        |            |                    |         |                    |                             |  |

|  |   |  |      |                    |         |                    |                             |
|--|---|--|------|--------------------|---------|--------------------|-----------------------------|
| No Asbestos  |   |  |      |                    |         |                    |                             |
| <b>B004 - R1007 - Distribution Board Cupboard - .96 m2</b>         |   | <b>Note: No inspection of live electrical installation</b> |      |                    |         |                    |                             |
| No Asbestos  |   |  |      |                    |         |                    |                             |
| <b>B004 - R1008 - Study Space - 13.34 m2</b>                       |   |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |  |      |                    |         |                    |                             |
| <b>B004 - R1009 - System Administrators Office - 13.88 m2</b>      |   |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |  |      |                    |         |                    |                             |
| <b>B004 - R1010 - Printing/Photocopying - 13.4 m2</b>              |   |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |  |      |                    |         |                    |                             |
| <b>B004 - R1011 - Workroom - 35.34 m2</b>                          |   |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |  |      |                    |         |                    |                             |
| <b>B004 - R1012 - Librarian - 9.98 m2</b>                          |   |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |  |      |                    |         |                    |                             |
| <b>B004 - R1013 - General Storeroom - 14.13 m2</b>                 |   |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |  |      |                    |         |                    |                             |
| <b>B004 - R1014 - Multi Media Store - 8.25 m2</b>                  |   |  |      |                    |         |                    |                             |
| No Asbestos  |   |  |      |                    |         |                    |                             |
| <b>B004 - R1016 - Movement - 4.26 m2</b>                           |   |  |      |                    |         |                    |                             |
| No Asbestos  |   |  |      |                    |         |                    |                             |
| <b>B004 - R1017 - Main Entry - 25.8 m2</b>                         |   |  |      |                    |         |                    |                             |
| No Asbestos  |   |  |      |                    |         |                    |                             |
| <b>B004 - R1018 - Main Area - 344.06 m2</b>                        |   |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( > 250 m2) - ( X25 )  |  |      |                    |         |                    |                             |
| <b>B004 - R1019 - Staff - Toilet - 4.29 m2</b>                     |   |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )    |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Flat AC Sheeting  | 1.5m2  | East | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B004 - R1020 - Staff - Toilet - 4.18 m2</b>                     |   |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )    |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Flat AC Sheeting  | 1.5m2  | East | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B004 - R1021 - Cleaning Store - Distributed - 1.85 m2</b>       |   |  |      |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )    |  |      |                    |         |                    |                             |
| <b>B004 - R1022 - Stairs - 1.87 m2</b>                             |   |  |      |                    |         |                    |                             |
| No Asbestos  |   |  |      |                    |         |                    |                             |
| <b>B004 - R1023 - Stairs - 1.87 m2</b>                             |   |  |      |                    |         |                    |                             |
| No Asbestos  |   |  |      |                    |         |                    |                             |
| <b>B004 - R1024 - External Movement - 36.71 m2</b>                 |   |  |      |                    |         |                    |                             |
| No Asbestos  |   |  |      |                    |         |                    |                             |
| <b>B004 - R1025 - External Movement - 26.98 m2</b>                 |   |  |      |                    |         |                    |                             |
| No Asbestos  |   |  |      |                    |         |                    |                             |
| <b>B004 - R1026 - External Movement - 17.34 m2</b>                 |   |  |      |                    |         |                    |                             |
| No Asbestos  |   |  |      |                    |         |                    |                             |
| <b>B005 - Administration/General Learning - 1975 - Brick/Block</b> |   |  |      |                    |         |                    |                             |
| Exterior   |   |  |      |                    |         |                    |                             |

|   |   |         |            |                    |         |                    |                             |  |
|---|---|---------|------------|--------------------|---------|--------------------|-----------------------------|--|
| Underfloor Voids - Slab on Ground                         | Non Accessible Area                                     |         |            |                    |         |                    |                             |  |
| <b>Interior</b>   |   |         |            |                    |         |                    |                             |  |
| <b>B005 - R0001 - Deputy Principal Office - 19.88 m2</b>  |   |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles   | 19.87m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B005 - R0002 - Deputy Principal Office - 15.97 m2</b>  |   |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles   | 15.96m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B005 - R0003 - Staff - Toilet - 9.45 m2</b>            |   |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |  |
| <b>B005 - R0004 - Staff - Toilet - 9.48 m2</b>            |   |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |  |
| <b>B005 - R0005 - Toilets-Girls - 9.9 m2</b>              |   |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |  |
| <b>B005 - R0006 - Toilets-Boys - 9.28 m2</b>              |   |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |  |
| <b>B005 - R0007 - Staff Study - 11.9 m2</b>               |   |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles   | 11.9m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B005 - R0008 - Computer Resource - 13.34 m2</b>        |   |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                                | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles   | 13.34m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B005 - R0011 - Ancillary Staff - 13.71 m2</b>          |   |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles   | 14m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                                | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0012 - Printing/Photocopying - 9.32 m2</b>     |   |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles   | 10m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                                | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                               | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0013 - Interview/Office - Type 1 - 9.43 m2</b> |   |         |            |                    |         |                    |                             |  |

|  |   |         |            |  |         |                    |                             |
|--|---|---------|------------|--|---------|--------------------|-----------------------------|
| Floor Coverings Res/Textile                                  | Vinyl Tiles   | 10m2    | Throughout | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles - Adhesive                                  |         |            |  |         |                    |                             |
| <b>B005 - R0014 - Cleaning Store - Distributed - 2.49 m2</b> |   |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles   | 3m2     | Throughout | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Floor Coverings Res/Textile                                  | Vinyl Tiles - Adhesive                                  |         |            |  |         |                    |                             |
| <b>B005 - R0015 - Distribution Board Cupboard - .69 m2</b>   |   |         |            | <b>Note: No inspection of live electrical installation</b> |         |                    |                             |
| Electrical - Backing Board                                   | Resinous Board  | 1       | North      | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )    |         |            |  |         |                    |                             |
| <b>B005 - R0016 - Administration - Clerical - 15.36 m2</b>   |   |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles   | 16m2    | Throughout | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Floor Coverings Res/Textile                                  | Vinyl Tiles - Adhesive                                  |         |            |  |         |                    |                             |
| <b>B005 - R0017 - Principal Office - 22.01 m2</b>            |   |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles   |         |            |  |         |                    |                             |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles - Adhesive                                  |         |            |  |         |                    |                             |
| <b>B005 - R0018 - General Storeroom - 2.22 m2</b>            |   |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles   | 3m2     | Throughout | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Floor Coverings Res/Textile                                  | Vinyl Tiles - Adhesive                                  |         |            |  |         |                    |                             |
| <b>B005 - R0022 - Public Entry - 12.19 m2</b>                |   |         |            |  |         |                    |                             |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |  |         |                    |                             |
| <b>B005 - R0023 - Student Reception - 31.96 m2</b>           |   |         |            |  |         |                    |                             |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |  |         |                    |                             |
| <b>B005 - R0024 - Administration - Clerical - 58.1 m2</b>    |   |         |            |  |         |                    |                             |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles - Adhesive                                  |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles   | 58.08m2 | Throughout | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B005 - R0025 - Movement - 28.54 m2</b>                    |   |         |            |  |         |                    |                             |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles   | 28.53m2 | Throughout | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B005 - R0026 - Movement - 35.92 m2</b>                    |   |         |            |  |         |                    |                             |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles - Adhesive                                  |         |            |  |         |                    |                             |
| Floor Coverings Res/Textile                                  | Vinyl Tiles   | 35.9m2  | Throughout | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B005 - R0027 - General Learning Space - 165.83 m2</b>     |   |         |            |  |         |                    |                             |

|   |  |         |            |                    |         |                    |                             |  |
|---|--|---------|------------|--------------------|---------|--------------------|-----------------------------|--|
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( 120 - 250 m2) - ( X15 ) |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                     |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                             | Vinyl Tiles  | 139m2   | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B005 - R0028 - Practical Activities - 9.46 m2</b>    |  |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )       |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                     |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                             | Vinyl Tiles  | 9.46m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B005 - R0029 - Stairs - 7.43 m2</b>                  |  |         |            |                    |         |                    |                             |  |
| No Asbestos   |  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0030 - External Movement - .96 m2</b>        |  |         |            |                    |         |                    |                             |  |
| No Asbestos   |  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0031 - Movement - 3.92 m2</b>                |  |         |            |                    |         |                    |                             |  |
| No Asbestos   |  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0032 - Movement - 39.29 m2</b>               |  |         |            |                    |         |                    |                             |  |
| No Asbestos   |  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0033 - Garden Store Room - 9.14 m2</b>       |  |         |            |                    |         |                    |                             |  |
| No Asbestos   |  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0034 - Movement - 16.01 m2</b>               |  |         |            |                    |         |                    |                             |  |
| No Asbestos   |  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0035 - External Stairs - 1.69 m2</b>         |  |         |            |                    |         |                    |                             |  |
| No Asbestos   |  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0037 - Movement - 4.88 m2</b>                |  |         |            |                    |         |                    |                             |  |
| Require Inspection                                      |  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0038 - Lift - 2.66 m2</b>                    |  |         |            |                    |         |                    |                             |  |
| Require Inspection                                      |  |         |            |                    |         |                    |                             |  |
| <b>B005 - R0039 - Movement - 4.93 m2</b>                |  |         |            |                    |         |                    |                             |  |
| Require Inspection                                      |  |         |            |                    |         |                    |                             |  |
| <b>B005 - R1001 - Computer Learning Space - 53.6 m2</b> |  |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )    |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                     |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                             | Vinyl Tiles  | 53.58m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B005 - R1002 - General Learning Space - 53.67 m2</b> |  |         |            |                    |         |                    |                             |  |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )    |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                     |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                             | Vinyl Tiles  | 53.65m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B005 - R1003 - Performance Store - 22.24 m2</b>      |  |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                             | Vinyl Tiles  | 23m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )    |         |            |                    |         |                    |                             |  |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                     |         |            |                    |         |                    |                             |  |
| <b>B005 - R1004 - Resources Store - 6.99 m2</b>         |  |         |            |                    |         |                    |                             |  |

|   |  |         |            |                    |         |                    |                             |
|---|--|---------|------------|--------------------|---------|--------------------|-----------------------------|
| Floor Coverings Res/Textile   | Vinyl Tiles  | 7m2     | South      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - (< 10 m2) - ( X2 )      |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| <b>B005 - R1005 - Cleaning Store - Distributed - 2.87 m2</b>  |  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles  | 4m2     | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - (< 10 m2) - ( X2 )      |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| <b>B005 - R1008 - Performance Workshop - 53.74 m2</b>   |  |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles  | 53.73m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B005 - R1009 - General Learning Space - 40.47 m2</b>   |  |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles  | 40.46m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B005 - R1010 - General Learning Space - 40.55 m2</b>   |  |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles  | 40.53m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B005 - R1011 - Distribution Board Cupboard - .7 m2</b> <span style="float: right;"><b>Note: No inspection of live electrical installation</b></span> |  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles  |         |            |                    |         |                    |                             |
| <b>B005 - R1012 - Aboriginal Resource Centre - 17.96 m2</b>   |  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles  | 19m2    | South      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| <b>B005 - R1013 - Staff Study - 40.69 m2</b>  |  |         |            |                    |         |                    |                             |
| Furniture / Fixtures - Sink   | Bituminous Membrane                                      |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles  | 41m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| <b>B005 - R1014 - Movement - 56.78 m2</b>   |  |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |         |            |                    |         |                    |                             |
| <b>B005 - R1015 - Movement Studio - 80.21 m2</b>  |  |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |         |            |                    |         |                    |                             |

| <b>B005 - R1016 - Performance Workshop - 39.86 m2</b>                        |   |         |            |                    |         |                    |                             |
|--|---|---------|------------|--------------------|---------|--------------------|-----------------------------|
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles   | 39.85m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B005 - R1017 - Stairs - 11.66 m2</b>                                      |   |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |
| <b>B005 - R1018 - External Movement - 1.5 m2</b>                             |   |         |            |                    |         |                    |                             |
| No Asbestos  |   |         |            |                    |         |                    |                             |
| <b>B005 - R1019 - External Movement - 56.58 m2</b>                           |   |         |            |                    |         |                    |                             |
| No Asbestos  |   |         |            |                    |         |                    |                             |
| <b>B005 - R1020 - External Stairs - 11.58 m2</b>                             |   |         |            |                    |         |                    |                             |
| No Asbestos  |   |         |            |                    |         |                    |                             |
| <b>B006 - General Learning/Intensive English Centre - 1975 - Brick/Block</b> |   |         |            |                    |         |                    |                             |
| <b>Exterior</b>  |   |         |            |                    |         |                    |                             |
| Ceiling Voids - Raked Ceiling  | Non Accessible Area                                     |         |            |                    |         |                    |                             |
| Underfloor Voids - Slab on Ground  | Non Accessible Area                                     |         |            |                    |         |                    |                             |
| <b>Interior</b>  |   |         |            |                    |         |                    |                             |
| <b>B006 - R0001 - General Learning Space - 53.09 m2</b>                      |   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles   | 54m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| <b>B006 - R0002 - General Learning Space - 53.75 m2</b>                      |   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles   | 55m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| <b>B006 - R0003 - Staff Study - 37.88 m2</b>                                 |   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles   | 10m2    | North      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| <b>B006 - R0004 - General Learning Space - 52.06 m2</b>                      |   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles   | 53m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| <b>B006 - R0005 - General Learning Space - 53.38 m2</b>                      |   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile  | Vinyl Tiles   | 54m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |                    |         |                    |                             |

| <b>B006 - R0006 - General Learning Space - 52.36 m2</b>       |  |      |            |                    |         |                    |                             |
|---|--|------|------------|--------------------|---------|--------------------|-----------------------------|
| Floor Coverings Res/Textile                                   | Vinyl Tiles  | 54m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                    | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles - Adhesive                                   |      |            |                    |         |                    |                             |
| <b>B006 - R0007 - Resources Store - 11.98 m2</b>              |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles  | 12m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Floor Coverings Res/Textile                                   | Vinyl Tiles - Adhesive                                   |      |            |                    |         |                    |                             |
| <b>B006 - R0008 - Staff Study - 13.44 m2</b>                  |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles  | 14m2 | North      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                    | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles - Adhesive                                   |      |            |                    |         |                    |                             |
| <b>B006 - R0009 - System Administrators Office - 35.42 m2</b> |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles  | 36m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Floor Coverings Res/Textile                                   | Vinyl Tiles - Adhesive                                   |      |            |                    |         |                    |                             |
| <b>B006 - R0010 - Cleaning Store - Distributed - 2.32 m2</b>  |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles  | 3m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Floor Coverings Res/Textile                                   | Vinyl Tiles - Adhesive                                   |      |            |                    |         |                    |                             |
| <b>B006 - R0011 - Chemical Store - 10.81 m2</b>               |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles  | 11m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                    | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles - Adhesive                                   |      |            |                    |         |                    |                             |
| <b>B006 - R0012 - Distribution Board Cupboard - .93 m2</b>    |  |      |            |                    |         |                    |                             |
| <b>Note: No inspection of live electrical installation</b>    |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles  | 1m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Floor Coverings Res/Textile                                   | Vinyl Tiles - Adhesive                                   |      |            |                    |         |                    |                             |
| <b>B006 - R0013 - Apparatus Store - 31.35 m2</b>              |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B006 - R0014 - Staff - Toilet - 8.11 m2</b>                |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                    | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )     |      |            |                    |         |                    |                             |
| <b>B006 - R0015 - Resources Store - 4.5 m2</b>                |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles  | 5m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                    | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )     |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                   | Vinyl Tiles - Adhesive                                   |      |            |                    |         |                    |                             |
| <b>B006 - R0016 - Staff - Toilet - 5.22 m2</b>                |  |      |            |                    |         |                    |                             |
| No Asbestos   |  |      |            |                    |         |                    |                             |
| <b>B006 - R0017 - Movement - 85.92 m2</b>                     |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                    | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |                    |         |                    |                             |



|   |   |         |            |                    |         |                    |                             |
|---|---|---------|------------|--------------------|---------|--------------------|-----------------------------|
| <b>B006 - R0018 - Stairs - 5.54 m2</b>                  |   |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )    |         |            |                    |         |                    |                             |
| <b>B006 - R0019 - General Storeroom - 8.57 m2</b>       |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B006 - R0020 - External Movement - 1.72 m2</b>       |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B006 - R0021 - External Movement - 54.24 m2</b>      |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B006 - R0022 - External Stairs - 5.02 m2</b>         |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B006 - R0023 - External Movement - .97 m2</b>        |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B006 - R0024 - External Movement - .97 m2</b>        |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B006 - R1001 - General Learning Space - 53.23 m2</b> |   |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles   | 53.22m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B006 - R1002 - Resources Store - 18.3 m2</b>         |   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles   | 19m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| <b>B006 - R1003 - General Learning Space - 52.72 m2</b> |   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles   | 53m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| <b>B006 - R1004 - General Learning Space - 52.72 m2</b> |   |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles   | 53m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B006 - R1005 - Shared Study Space - 18.28 m2</b>     |   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles   | 19m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |
| <b>B006 - R1006 - General Learning Space - 52.87 m2</b> |   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles   | 53m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                              | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                             | Vinyl Tiles - Adhesive                                  |         |            |                    |         |                    |                             |

| <b>B006 - R1007 - General Learning Space - 53.81 m2</b>     |  |         |            |                    |         |                    |                             |
|---|--|---------|------------|--------------------|---------|--------------------|-----------------------------|
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 54m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| <b>B006 - R1008 - Shared Study Space - 40.5 m2</b>          |  |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 40.49m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B006 - R1009 - General Learning Space - 40.52 m2</b>     |  |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 40.5m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B006 - R1010 - Distribution Board Cupboard - 1.47 m2</b> |  |         |            |                    |         |                    |                             |
| <b>Note: No inspection of live electrical installation</b>  |  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 2m2     | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Floor Coverings Res/Textile                                 | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Flat AC Sheeting   | 1.47m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B006 - R1011 - Cleaning Store - Distributed - 3.5 m2</b> |  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )     |         |            |                    |         |                    |                             |
| <b>B006 - R1012 - General Storeroom - 11.05 m2</b>          |  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 12m2    | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| <b>B006 - R1013 - Staff Study - 40.82 m2</b>                |  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 42m2    | North      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| <b>B006 - R1014 - Movement - 72.19 m2</b>                   |  |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles  | 50m2    | East, West | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                                 | Vinyl Tiles - Adhesive                                   |         |            |                    |         |                    |                             |
| <b>B006 - R1015 - Stairs - 13.07 m2</b>                     |  |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |         |            |                    |         |                    |                             |
| <b>B006 - R1016 - External Movement - .91 m2</b>            |  |         |            |                    |         |                    |                             |
| No Asbestos   |  |         |            |                    |         |                    |                             |

|   |   |      |            |                    |         |                    |                             |
|---|---|------|------------|--------------------|---------|--------------------|-----------------------------|
| <b>B006 - R1017 - External Movement - 14.47 m2</b>                    |   |      |            |                    |         |                    |                             |
| No Asbestos   |   |      |            |                    |         |                    |                             |
| <b>B006 - R1018 - External Movement - 14 m2</b>                       |   |      |            |                    |         |                    |                             |
| No Asbestos   |   |      |            |                    |         |                    |                             |
| <b>B006 - R1019 - External Movement - 17.82 m2</b>                    |   |      |            |                    |         |                    |                             |
| No Asbestos   |   |      |            |                    |         |                    |                             |
| <b>B006 - R1020 - External Stairs - 12.77 m2</b>                      |   |      |            |                    |         |                    |                             |
| No Asbestos   |   |      |            |                    |         |                    |                             |
| <b>B007 - General Learning/Computer Learning - 1975 - Brick/Block</b> |   |      |            |                    |         |                    |                             |
| <b>Exterior</b>   |   |      |            |                    |         |                    |                             |
| Ceiling Voids - Raked Ceiling   | Non Accessible Area                                     |      |            |                    |         |                    |                             |
| Underfloor Voids - Slab on Ground                                     | Non Accessible Area                                     |      |            |                    |         |                    |                             |
| <b>Interior</b>   |   |      |            |                    |         |                    |                             |
| <b>B007 - R0001 - Staff - Toilet - 5.08 m2</b>                        |   |      |            |                    |         |                    |                             |
| No Asbestos   |   |      |            |                    |         |                    |                             |
| <b>B007 - R0002 - General Storeroom - 4.26 m2</b>                     |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 5m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B007 - R0003 - Staff - Toilet - 8.3 m2</b>                         |   |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - (< 10 m2) - ( X2 )     |      |            |                    |         |                    |                             |
| <b>B007 - R0004 - Fitness Laboratory - 31.67 m2</b>                   |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 32m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B007 - R0005 - Distribution Board Cupboard - .92 m2</b>            |   |      |            |                    |         |                    |                             |
| <b>Note: No inspection of live electrical installation</b>            |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 1m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B007 - R0006 - General Storeroom - 11.55 m2</b>                    |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 11m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |      |            |                    |         |                    |                             |
| <b>B007 - R0007 - Cleaning Store - Distributed - 2.66 m2</b>          |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 3m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B007 - R0008 - Resources Store - 9.41 m2</b>                       |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 10m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |      |            |                    |         |                    |                             |
| <b>B007 - R0009 - General Storeroom - 5.12 m2</b>                     |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 6m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B007 - R0010 - Staff Study - 50.14 m2</b>                          |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 53m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |      |            |                    |         |                    |                             |
| <b>B007 - R0011 - General Learning Space - 53.23 m2</b>               |   |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 53m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |      |            |                    |         |                    |                             |

|  |  |      |            |                    |         |                    |                             |
|--|--|------|------------|--------------------|---------|--------------------|-----------------------------|
| <b>B007 - R0012 - Careers Advisers Office - 24.82 m2</b> |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                              | Vinyl Tiles  | 25m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                               | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |                    |         |                    |                             |
| <b>B007 - R0013 - General Learning Space - 53.67 m2</b>  |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                              | Vinyl Tiles  | 54m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                               | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B007 - R0014 - Resources Store - 10.65 m2</b>         |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                              | Vinyl Tiles  | 11m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B007 - R0015 - General Learning Space - 53.67 m2</b>  |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                              | Vinyl Tiles  | 54m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                               | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B007 - R0016 - General Learning Space - 53.31 m2</b>  |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                              | Vinyl Tiles  | 54m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                               | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B007 - R0018 - Stairs - 5.35 m2</b>                   |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                               | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )     |      |            |                    |         |                    |                             |
| <b>B007 - R0019 - External Movement - 1.76 m2</b>        |  |      |            |                    |         |                    |                             |
| No Asbestos  |  |      |            |                    |         |                    |                             |
| <b>B007 - R0020 - External Movement - 45.12 m2</b>       |  |      |            |                    |         |                    |                             |
| No Asbestos  |  |      |            |                    |         |                    |                             |
| <b>B007 - R0021 - General Storeroom - 8.62 m2</b>        |  |      |            |                    |         |                    |                             |
| No Asbestos  |  |      |            |                    |         |                    |                             |
| <b>B007 - R0022 - External Stairs - .72 m2</b>           |  |      |            |                    |         |                    |                             |
| No Asbestos  |  |      |            |                    |         |                    |                             |
| <b>B007 - R0023 - External Movement - .93 m2</b>         |  |      |            |                    |         |                    |                             |
| No Asbestos  |  |      |            |                    |         |                    |                             |
| <b>B007 - R0024 - General Learning Space - 82.16 m2</b>  |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                               | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |                    |         |                    |                             |
| <b>B007 - R0025 - Movement - 50.63 m2</b>                |  |      |            |                    |         |                    |                             |
| Ceiling Structures/Linings                               | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B007 - R0026 - Movement - 4.17 m2</b>                 |  |      |            |                    |         |                    |                             |
| Require Inspection                                       |  |      |            |                    |         |                    |                             |
| <b>B007 - R0027 - Lift - 2.66 m2</b>                     |  |      |            |                    |         |                    |                             |
| Require Inspection                                       |  |      |            |                    |         |                    |                             |
| <b>B007 - R0028 - Movement - 6.37 m2</b>                 |  |      |            |                    |         |                    |                             |
| Require Inspection                                       |  |      |            |                    |         |                    |                             |
| <b>B007 - R1001 - Staff Study - 39.96 m2</b>             |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                              | Vinyl Tiles  | 40m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                               | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |                    |         |                    |                             |
| <b>B007 - R1002 - Office/Store - 10.68 m2</b>            |  |      |            |                    |         |                    |                             |
| Floor Coverings Res/Textile                              | Vinyl Tiles  | 11m2 | East, West | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |

|  |  |      |            |  |         |                    |                             |  |
|--|--|------|------------|--|---------|--------------------|-----------------------------|--|
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |  |         |                    |                             |  |
| <b>B007 - R1003 - Cleaning Store - Distributed - 3.66 m2</b> |  |      |            |  |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 4m2  | East, West | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )     |      |            |  |         |                    |                             |  |
| <b>B007 - R1004 - Distribution Board Cupboard - 1.48 m2</b>  |  |      |            | <b>Note: No inspection of live electrical installation</b> |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 2m2  | East, West | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                                   | Flat AC Sheeting   | 2m2  | Throughout | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B007 - R1005 - General Learning Space - 39.63 m2</b>      |  |      |            |  |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |  |         |                    |                             |  |
| <b>B007 - R1006 - Computer Learning Space - 39.63 m2</b>     |  |      |            |  |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |  |         |                    |                             |  |
| <b>B007 - R1007 - Seminar - 54.03 m2</b>                     |  |      |            |  |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |  |         |                    |                             |  |
| <b>B007 - R1008 - General Learning Space - 52.8 m2</b>       |  |      |            |  |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |  |         |                    |                             |  |
| <b>B007 - R1009 - Student Kitchen - 17.51 m2</b>             |  |      |            |  |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 19m2 | East, West | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |  |         |                    |                             |  |
| <b>B007 - R1010 - General Learning Space - 52.8 m2</b>       |  |      |            |  |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |  |         |                    |                             |  |
| <b>B007 - R1011 - General Learning Space - 52.8 m2</b>       |  |      |            |  |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |  |         |                    |                             |  |
| <b>B007 - R1012 - Resources Store - 18.46 m2</b>             |  |      |            |  |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |  |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 19m2 | East, West | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| <b>B007 - R1013 - General Learning Space - 53.09 m2</b>      |  |      |            |  |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )  |      |            |  |         |                    |                             |  |
| <b>B007 - R1014 - Movement - 73.17 m2</b>                    |  |      |            |  |         |                    |                             |  |
| Floor Coverings Res/Textile                                  | Vinyl Tiles  | 50m2 | East, West | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |  |         |                    |                             |  |
| <b>B007 - R1015 - Stairs - 13.33 m2</b>                      |  |      |            |  |         |                    |                             |  |
| Ceiling Structures/Linings                                   | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )  |      |            |  |         |                    |                             |  |
| <b>B007 - R1016 - External Movement - 1.34 m2</b>            |  |      |            |  |         |                    |                             |  |
| No Asbestos  |  |      |            |  |         |                    |                             |  |
| <b>B007 - R1017 - External Movement - 44.1 m2</b>            |  |      |            |  |         |                    |                             |  |
| No Asbestos  |  |      |            |  |         |                    |                             |  |
| <b>B007 - R1018 - External Stairs - 9.27 m2</b>              |  |      |            |  |         |                    |                             |  |
| No Asbestos  |  |      |            |  |         |                    |                             |  |

## B008 - Other/General Learning - 1975 - Brick/Block

### Exterior

|                                   |                     |  |  |  |  |  |  |  |
|-----------------------------------|---------------------|--|--|--|--|--|--|--|
| Ceiling Voids - Raked Ceiling     | Non Accessible Area |  |  |  |  |  |  |  |
| Underfloor Voids - Slab on Ground | Non Accessible Area |  |  |  |  |  |  |  |

### Interior

#### B008 - R0001 - General Learning Space - 91.24 m2

|                             |  |      |            |                    |         |                    |                             |
|-----------------------------|--|------|------------|--------------------|---------|--------------------|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles  | 91m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |                    |         |                    |                             |

#### B008 - R0002 - Staff Study - 48.47 m2

|                             |   |      |            |                    |         |                    |                             |
|-----------------------------|---|------|------------|--------------------|---------|--------------------|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles   | 49m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |      |            |                    |         |                    |                             |

#### B008 - R0003 - Special Learning Space - 90.42 m2

|                             |  |      |            |                    |         |                    |                             |
|-----------------------------|--|------|------------|--------------------|---------|--------------------|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles  | 91m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |                    |         |                    |                             |

#### B008 - R0004 - Distribution Board Cupboard - .71 m2

Note: No inspection of live electrical installation

|                            |                |     |       |                    |         |                    |                             |
|----------------------------|----------------|-----|-------|--------------------|---------|--------------------|-----------------------------|
| Electrical - Backing Board | Resinous Board | 0.3 | North | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
|----------------------------|----------------|-----|-------|--------------------|---------|--------------------|-----------------------------|

#### B008 - R0006 - Cleaning Store - Distributed - .99 m2

No Asbestos

#### B008 - R0009 - General Storeroom - 22.72 m2

No Asbestos

#### B008 - R0010 - External Movement - 80.22 m2

No Asbestos

#### B008 - R0011 - General Storeroom - 1.08 m2

No Asbestos

#### B008 - R0012 - External Movement - 11.76 m2

No Asbestos

#### B008 - R1001 - Special Learning Space - 90.23 m2

|                             |  |      |            |                    |         |                    |                             |
|-----------------------------|--|------|------------|--------------------|---------|--------------------|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles  | 91m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 ) |      |            |                    |         |                    |                             |

#### B008 - R1005 - General Storeroom - 1.04 m2

No Asbestos

#### B008 - R1006 - Distribution Board Cupboard - .72 m2

Note: No inspection of live electrical installation

|                            |                |      |       |                    |         |                    |                             |
|----------------------------|----------------|------|-------|--------------------|---------|--------------------|-----------------------------|
| Electrical - Backing Board | Resinous Board | 0.23 | North | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
|----------------------------|----------------|------|-------|--------------------|---------|--------------------|-----------------------------|

#### B008 - R1007 - General Storeroom - .67 m2

|                            |                  |        |            |                    |         |                    |                             |
|----------------------------|------------------|--------|------------|--------------------|---------|--------------------|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 0.67m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
|----------------------------|------------------|--------|------------|--------------------|---------|--------------------|-----------------------------|

#### B008 - R1008 - Cleaning Store - Distributed - .74 m2

No Asbestos

#### B008 - R1010 - External Movement - 90.88 m2

|                            |                  |      |            |                    |         |                    |                             |
|----------------------------|------------------|------|------------|--------------------|---------|--------------------|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 52m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
|----------------------------|------------------|------|------------|--------------------|---------|--------------------|-----------------------------|

#### B008 - R1011 - Toilets-Disabled - 12.92 m2

No Asbestos

|   |   |         |            |                    |         |                    |                             |
|---|---|---------|------------|--------------------|---------|--------------------|-----------------------------|
| <b>B008 - R1012 - General Storeroom - 7.1 m2</b>                                |   |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - (< 10 m2) - ( X2 )     |         |            |                    |         |                    |                             |
| <b>B008 - R1013 - External Movement - 1.72 m2</b>                               |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B008 - R1014 - Staff Study - 40.69 m2</b>                                    |   |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 40.68m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B008 - R1015 - Special Learning Space - 48.45 m2</b>                         |   |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 48.44m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B008 - R1016 - Seminar - Type 1 - 17.91 m2</b>                               |   |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 1.9m2   | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B008 - R1017 - Practice/Seminar - 27.41 m2</b>                               |   |         |            |                    |         |                    |                             |
| Ceiling Structures/Linings  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |         |            |                    |         |                    |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles   | 27.4m2  | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B009 - Multi Purpose Facilities/Other-Community Use - 1975 - Brick/Block</b> |   |         |            |                    |         |                    |                             |
| <b>Exterior</b>   |   |         |            |                    |         |                    |                             |
| Ceiling Voids - Raked Ceiling   | Non Accessible Area                                     |         |            |                    |         |                    |                             |
| Underfloor Voids - Slab on Ground   | Non Accessible Area                                     |         |            |                    |         |                    |                             |
| <b>Interior</b>   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0002 - Other-Community Use - 4.3 m2</b>                              |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0003 - Office/Store - 8.47 m2</b>                                    |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0004 - General Storeroom - 13.8 m2</b>                               |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0005 - Toilets-Girls - 37.21 m2</b>                                  |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0006 - Toilets-Boys - 28.74 m2</b>                                   |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0007 - Multi-Purpose Space - 63.43 m2</b>                            |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0009 - Plant - 12.57 m2</b>  |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0011 - General Storeroom - 10.57 m2</b>                              |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0013 - Staff - Toilet - 2.87 m2</b>                                  |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0014 - Staff - Toilet - 2.87 m2</b>                                  |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0015 - Distribution Board Cupboard - .31 m2</b>                      |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>B009 - R0016 - Cleaning Store - Distributed - 2.3 m2</b>                     |   |         |            |                    |         |                    |                             |
| No Asbestos   |   |         |            |                    |         |                    |                             |
| <b>Note: No inspection of live electrical installation</b>                      |   |         |            |                    |         |                    |                             |

|  |  |
|--|--|
| No Asbestos  |  |
| <b>B009 - R0017 - Staff Kitchen - 29.34 m2</b>               |  |
| No Asbestos  |  |
| <b>B009 - R0018 - Stage - 127.81 m2</b>                      |  |
| No Asbestos  |  |
| <b>B009 - R0019 - Multi-Purpose Space - 365.73 m2</b>        |  |
| No Asbestos  |  |
| <b>B009 - R0020 - General Storeroom - 18.67 m2</b>           |  |
| No Asbestos  |  |
| <b>B009 - R0021 - General Storeroom - 18.66 m2</b>           |  |
| No Asbestos  |  |
| <b>B009 - R0022 - Movement - 4.75 m2</b>                     |  |
| No Asbestos  |  |
| <b>B009 - R0023 - Movement - 4.71 m2</b>                     |  |
| No Asbestos  |  |
| <b>B009 - R0024 - Chair Store - 12.68 m2</b>                 |  |
| No Asbestos  |  |
| <b>B009 - R0025 - Chair Store - 225.12 m2</b>                |  |
| No Asbestos  |  |
| <b>B009 - R0026 - Main Switchroom - 10.35 m2</b>             |  |
| No Asbestos  |  |
| <b>B009 - R0027 - Plant - .4 m2</b>                          |  |
| No Asbestos  |  |
| <b>B009 - R0028 - General Storeroom - 7.59 m2</b>            |  |
| No Asbestos  |  |
| <b>B009 - R0029 - Cleaning Store - Distributed - 1.43 m2</b> |  |
| No Asbestos  |  |
| <b>B009 - R0030 - Movement - 31.02 m2</b>                    |  |
| No Asbestos  |  |
| <b>B009 - R0031 - Stairs - 3.99 m2</b>                       |  |
| No Asbestos  |  |
| <b>B009 - R0032 - Multi-Purpose Space - 99.14 m2</b>         |  |
| No Asbestos  |  |
| <b>B009 - R0033 - Stairs - 4.84 m2</b>                       |  |
| No Asbestos  |  |
| <b>B009 - R0034 - Movement - 142.64 m2</b>                   |  |
| No Asbestos  |  |
| <b>B009 - R0035 - External Movement - 14.75 m2</b>           |  |
| No Asbestos  |  |
| <b>B009 - R0036 - Stairs - 6.02 m2</b>                       |  |
| No Asbestos  |  |
| <b>B009 - R0037 - External Movement - 2.06 m2</b>            |  |
| No Asbestos  |  |
| <b>B009 - R0038 - External Movement - 2.56 m2</b>            |  |
| No Asbestos  |  |
| <b>B009 - R0039 - External Movement - 2.56 m2</b>            |  |
| No Asbestos  |  |
| <b>B009 - R0040 - External Movement - 2.06 m2</b>            |  |
| No Asbestos  |  |
| <b>B009 - R0041 - External Movement - 11.08 m2</b>           |  |
| No Asbestos  |  |
| <b>B009 - R0042 - External Movement - 8.07 m2</b>            |  |



|   |                      |     |       |                    |         |                    |                             |
|---|----------------------|-----|-------|--------------------|---------|--------------------|-----------------------------|
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1001 - Movement - 32.69 m2</b>               |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1002 - Plant - 100.21 m2</b>                 |                      |     |       |                    |         |                    |                             |
| Plant / Equipment - Flue                                | Fibre Cement Moulded | 2   | North | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Electrical - Backing Board                              | Resinous Board       | 1.5 | South | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Door - Insulation                                       | Insulation Material  | 1   | North | Good Condition (1) | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B009 - R1003 - Plant - 15.14 m2</b>                  |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1004 - Multi-Purpose Space - 181.12 m2</b>   |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1005 - General Storeroom - 6.38 m2</b>       |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1006 - Plant - 6.69 m2</b>                   |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1007 - Control Room - 16.64 m2</b>           |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1010 - Stairs - 7.69 m2</b>                  |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1011 - Movement - 18.45 m2</b>               |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1012 - Plant - .49 m2</b>                    |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1013 - Stairs - 6.87 m2</b>                  |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B009 - R1014 - External Movement - 1.66 m2</b>       |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B010 - Storage - 2008 - Metal Shed</b>               |                      |     |       |                    |         |                    |                             |
| <b>Exterior</b>   |                      |     |       |                    |         |                    |                             |
| Ceiling Voids - Flat Roof                               | Non Accessible Area  |     |       |                    |         |                    |                             |
| Underfloor Voids - Slab on Ground                       | Non Accessible Area  |     |       |                    |         |                    |                             |
| <b>Interior</b>   |                      |     |       |                    |         |                    |                             |
| <b>B010 - R0001 - Machine Storage - 21.79 m2</b>        |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B011 - General Learning - 2010 - Brick/Veneer</b>    |                      |     |       |                    |         |                    |                             |
| <b>Exterior</b>   |                      |     |       |                    |         |                    |                             |
| Ceiling Voids - Raked Ceiling                           | Non Accessible Area  |     |       |                    |         |                    |                             |
| Underfloor Voids - Slab on Ground                       | Non Accessible Area  |     |       |                    |         |                    |                             |
| <b>Interior</b>   |                      |     |       |                    |         |                    |                             |
| <b>B011 - R0001 - General Learning Space - 91.92 m2</b> |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B011 - R0002 - Seminar - 18.78 m2</b>                |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B011 - R0003 - Secure Storeroom - 10.14 m2</b>       |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |
| <b>B011 - R0004 - Secure Storeroom - 9.03 m2</b>        |                      |     |       |                    |         |                    |                             |
| No Asbestos   |                      |     |       |                    |         |                    |                             |

**B011 - R0005 - External Movement - 26.97 m2**

No Asbestos

**B012 - Building Services - 1973 - Brick/Block****Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

**Interior****B012 - R0001 - Plant - 3.72 m2**

No Asbestos

**B012 - R0002 - Plant - 2.99 m2**

No Asbestos

**Demountables**

**OS 971 80029 - Shed - Container (Garden/Sports/Bulk) - Placement Date : 30-JUN-1995**

No Asbestos Found