

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kirrawee Public School (4075)
Region:	Sydney AMU
State Electorate:	Miranda
Local Government Area:	Sutherland

Last Reviewed By:	WSP 01-NOV-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning - 1955 - Timber							
Exterior							
Underfloor Voids	Flat AC Sheeting	1	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	AC Fragments/Debris	1	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Interior							
B00A - R0001 - General Storeroom - 6.46 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces, Upper portion, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0002 - Movement - 26.81 m2							
Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0003 - Practical Activities - 1hb - 50.78 m2							
Wall Linings Internal	Flat AC Sheeting	60m2	All surfaces, Upper portion, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	51m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0004 - Home Base - 47.33 m2							
Wall Linings Internal	Flat AC Sheeting	60m2	All surfaces, Upper portion, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	48m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0005 - Movement - 36.91 m2							
Ceiling Structures/Linings	Flat AC Sheeting	34m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0006 - Toilets - Boys/Girls - 3.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0007 - Practical Activities - 1hb - 25.85 m2							
Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0008 - Home Base - 53.45 m2							
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0010 - Toilets - Boys/Girls - 4.19 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces, Upper portion, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0011 - Shower/Change - 13.1 m2							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0012 - Access Shower/Toilet - 11.7 m2							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0013 - Staff Kitchen - 28.08 m2							

Ceiling Structures/Linings	Flat AC Sheeting	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - General Learning/Communal Facilities - 1955 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Gable Verge Lining	Flat AC Sheeting						
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Interior							
B00B - R0001 - Toilets - Boys - 31.84 m2							
No Asbestos							
B00B - R0002 - Toilets - Girls - 31.95 m2							
No Asbestos							
B00B - R0003 - Home Base Store - 4.78 m2							
No Asbestos							
B00B - R0004 - Personal Effects Storage - 5.46 m2							
No Asbestos							
B00B - R0005 - Movement - 3.17 m2							
No Asbestos							
B00B - R0006 - Movement - 4.28 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0007 - Home Base - 56.99 m2							
No Asbestos							
B00B - R0008 - Home Base - 57.08 m2							
No Asbestos							
B00B - R0009 - Home Base Store - 5.22 m2							
No Asbestos							
B00B - R0010 - Personal Effects Storage - 8.79 m2							
No Asbestos							
B00B - R0011 - Movement - 9.81 m2							
No Asbestos							
B00B - R0012 - Withdrawal Space - 1hb - 21.06 m2							
No Asbestos							
B00B - R0013 - Personal Effects Storage - 10.06 m2							
No Asbestos							
B00B - R0014 - Movement - 4.5 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0015 - Home Base - 55.81 m2							
No Asbestos							
B00B - R0016 - Home Base - 57.23 m2							
No Asbestos							
B00B - R0017 - Personal Effects Storage - 10.43 m2							
No Asbestos							
B00B - R0018 - Cleaning Distributed Store - 1.02 m2							
No Asbestos							
B00B - R0019 - Staff Room Annexe - 18.17 m2							
No Asbestos							
B00B - R0020 - General Storeroom - 10.37 m2							

No Asbestos							
B00B - R0021 - Movement - 13.76 m2							
No Asbestos							
B00B - R0022 - Movement - 9.45 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0023 - Movement - 3.06 m2							
No Asbestos							
B00B - R0024 - General Storeroom - 10.38 m2							
No Asbestos							
B00B - R0025 - Movement - 3.08 m2							
No Asbestos							
B00B - R0026 - Hall Chair Store - 9.4 m2							
No Asbestos							
B00B - R0027 - Raised Platform - 38.08 m2							
No Asbestos							
B00B - R0028 - Communal Space - 177.69 m2							
No Asbestos							
B00B - R0029 - Movement - 4.97 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0030 - Distribution Board - .31 m2							
Note: No inspection of live electrical installation							
No Asbestos							
B00B - R0031 - P.E Store - 25.27 m2							
No Asbestos							
B00B - R0032 - Staff Kitchen - 12.2 m2							
No Asbestos							
B00B - R0034 - Movement - 63.8 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00B - R0035 - Plant - .31 m2							
No Asbestos							
B00B - R0036 - General Assistant/Bulk Store - 17.17 m2							
No Asbestos							
B00B - R0037 - General Assistant/Bulk Store - 17.12 m2							
No Asbestos							
B00B - R9001 - Staff Shower/Change - 3.72 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R9002 - Staff Room - 71.62 m2							
Ceiling Structures/Linings	Flat AC Sheeting	72m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R9003 - Movement - 23.72 m2							
No Asbestos							
B00B - R9004 - Plant - 71.15 m2							
Ceiling Structures/Linings	Flat AC Sheeting	72m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R9005 - General Storeroom - 27.51 m2							
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R9006 - General Storeroom - 3.2 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - Library - 1955 - Timber							

Exterior							
Underfloor Voids	Flat AC Sheeting	1	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Interior							
B00C - R0001 - External Movement - 70.95 m2							
Ceiling Structures/Linings	Flat AC Sheeting	88m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0002 - Reading Area - 171.47 m2							
Wall Linings Internal	Flat AC Sheeting	8m2	South west corner middle and lower portion by heater	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0003 - Library Office/Workroom - 12 m2							
No Asbestos							
B00C - R0008 - General Storeroom - 19.04 m2							
No Asbestos							
B00C - R0009 - External Stairs - 7.03 m2							
No Asbestos							
B00D - General Learning - 1959 - Brick/Block							
Exterior							
Gable Verge Lining	Flat AC Sheeting						
Ceiling Voids	AC Fragments/Debris	1	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	AC Fragments/Debris - Vinyl Floor Tile						
Eaves Linings	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Interior							
B00D - R0001 - Home Base - 65.36 m2							
No Asbestos							
B00D - R0002 - Personal Effects Storage - 12.04 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00D - R0003 - Personal Effects Storage - 12.04 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00D - R0004 - Movement - 6.75 m2							
No Asbestos							
B00D - R0005 - Movement - 8.29 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0006 - Home Base - 65.46 m2							
No Asbestos							
B00D - R0008 - Toilets - Boys - 9.68 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0009 - Disabled Shower/Toilet - 9.51 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - General Learning/Pupil Facilities - 1959 - Brick/Block							
Exterior							

Gable Verge Lining	Flat AC Sheeting						
Underfloor Voids	AC Fragments/Debris	1	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	100m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior

B00E- R0001 - Home Base - 57.22 m2

No Asbestos

B00E- R0002 - Home Base Store - 5.31 m2

No Asbestos

B00E- R0003 - Personal Effects Storage - 4.07 m2

No Asbestos

B00E- R0004 - Movement - 10.09 m2

No Asbestos

B00E- R0005 - Movement - 9.45 m2

No Asbestos

B00E- R0006 - General Storeroom - 10.8 m2

No Asbestos

B00E- R0007 - Personal Effects Storage - 4.85 m2

No Asbestos

B00E- R0008 - Home Base - 57.22 m2

No Asbestos

B00E- R0009 - Home Base Store - 5.1 m2

No Asbestos

B00E- R0010 - Home Base - 57.22 m2

No Asbestos

B00E- R0011 - Home Base Store - 6.66 m2

No Asbestos

B00E- R0012 - Movement - 14.69 m2

No Asbestos

B00E- R0013 - Movement - 4.4 m2

No Asbestos

B00E- R0014 - General Storeroom - 6.66 m2

No Asbestos

B00E- R0015 - Communal Space - 57.22 m2

No Asbestos

B00E- R0016 - Home Base - 57.29 m2

No Asbestos

B00E- R0017 - Home Base Store - 5.22 m2

No Asbestos

B00E- R0018 - Movement - 17.28 m2

No Asbestos

B00E- R0019 - Movement - 4.4 m2

No Asbestos

B00E- R0020 - Home Base Store - 5.22 m2

No Asbestos

B00E- R0021 - Home Base - 57.28 m2

No Asbestos

B00E- R0022 - Toilets - Girls - 37.54 m2

No Asbestos							
B00E - R0023 - Toilets - Boys - 38.81 m2							
No Asbestos							
B00E - R0024 - Staff Toilet - 2.6 m2							
No Asbestos							
B00E - R0025 - Staff Toilet - 3.06 m2							
No Asbestos							
B00E - R9001 - General Assistant/Bulk Store - 25.55 m2							
No Asbestos							
B00E - R9002 - General Storeroom - 29.25 m2							
Ceiling Structures/Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubides)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R9003 - General Storeroom - 27.52 m2							
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubides)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - Administration - 1960 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	80m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	AC Fragments/Debris - Vinyl Floor Tile						
Ceiling Voids	No Asbestos Found						
Interior							
B00F - R0001 - Principal - 16.71 m2							
No Asbestos							
B00F - R0002 - Movement - 28.44 m2							
No Asbestos							
B00F - R0003 - Staff Toilet - 4.73 m2							
Partition Walls (Cubides)	Flat AC Sheeting	4m2	South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0004 - Cleaning Distributed Store - 1.14 m2							
Partition Walls (Cubides)	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0005 - Staff Toilet - 4.6 m2							
Partition Walls (Cubides)	Flat AC Sheeting	4m2	South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0006 - General Storeroom - 11.59 m2							
No Asbestos							
B00F - R0007 - Sick Bay - 5.88 m2							
No Asbestos							
B00F - R0008 - Movement - 5.74 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0009 - Clerical Office/Workroom - 16.35 m2							
No Asbestos							
B00F - R0010 - General Storeroom - 2.71 m2							
No Asbestos							
B00F - R0011 - Distribution Board - .48 m2							
							Note: No inspection of live electrical installation

Wall Linings Internal	Flat AC Sheeting	8m2	South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0012 - Uniform Shop - 3.78 m2							
No Asbestos							
B00F - R0013 - Interview - 12.61 m2							
No Asbestos							
B00F - R0014 - Deputy Principal - 16.66 m2							
No Asbestos							
B00F - R0015 - Movement - 5.71 m2							
No Asbestos							
B00G - Staff Facilities - 1960 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	52m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Gable Verge Lining	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00G - R0001 - Staff Room - 57.7 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R0002 - Staff Room Annexe - 21.3 m2							
No Asbestos							
B00G - R0003 - General Storeroom - 21.53 m2							
No Asbestos							
B00G - R0004 - Movement - 13.05 m2							
No Asbestos							
B00G - R0005 - Movement - 1.85 m2							
No Asbestos							
B00I - Pupil Facilities - 1960 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00I - R0001 - Canteen - 28.75 m2							
Ceiling Structures/Linings	Flat AC Sheeting	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0002 - Canteen Office/Store - 2.89 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0003 - Canteen Office/Store - 3.13 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0004 - Canteen Office/Store - 1.56 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0005 - Distribution Board - 1.13 m2							
Note: No inspection of live electrical installation							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00I - R0006 - Staff Toilet - 3.25 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0007 - Movement - 12.08 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0011 - Sports Store - 21.95 m2							
No Asbestos							
B00I - R0012 - General Storeroom - 7.98 m2							
No Asbestos							
B00I - R0013 - External Movement - 13.58 m2							
No Asbestos							
B00J - Communal Facilities - 1970 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00J - R0001 - Hall Chair Store - 37.21 m2							
No Asbestos							
B00J - R0002 - External Movement - 64.01 m2							
No Asbestos							
B00K - Library/General Learning - 2011 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00K - R0001 - Movement - 2.33 m2							
No Asbestos							
B00K - R0002 - Staff Toilet - 4.45 m2							
No Asbestos							
B00K - R0003 - Distribution Board - .84 m2							
No Asbestos							
B00K - R0004 - Cleaning Distributed Store - 3.67 m2							
No Asbestos							
B00K - R0005 - Resource/Toy Space - 14.86 m2							
No Asbestos							
B00K - R0006 - Communications Room - 8 m2							
No Asbestos							
B00K - R0007 - Library Office/Workroom - 22.91 m2							
No Asbestos							
B00K - R0008 - Reading Area - 167.94 m2							
No Asbestos							
B00K - R0009 - External Movement - 20.66 m2							
No Asbestos							
B00L - General Learning/Multi Purpose Facilities - 2011 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						

Ceiling Voids	No Asbestos Found	
Interior		
B00L - R0001 - Home Base - 58.36 m2		
No Asbestos		
B00L - R0002 - Home Base Store - 5.74 m2		
No Asbestos		
B00L - R0003 - Practical Activities - 18.37 m2		
No Asbestos		
B00L - R0004 - Withdrawal Space - 1hb - 9.02 m2		
No Asbestos		
B00L - R0005 - External Movement - 33.21 m2		
No Asbestos		
B00L - R0006 - Special Programs Room - 38.04 m2		
No Asbestos		
B00L - R0007 - Home Base Store - 6.15 m2		
No Asbestos		
B00L - R0008 - Security Store - 6.34 m2		
No Asbestos		

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020