


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kambora Public School (4515)
Region:	Northern Sydney AMU
State Electorate:	Davidson
Local Government Area:	Northern Beaches

Last Reviewed By:	AECOM 28-JUN-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/General Learning - 1979 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	500m2	All surfaces	Mnimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Ends	Flat AC Sheeting	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00A - M0001 - Withdrawal Space - 1hb - 11.32 m2							
No Asbestos							
B00A - M0002 - Communications Room - 42.95 m2							
No Asbestos							
B00A - M0003 - Staff Room - 51.11 m2							
No Asbestos							
B00A - M0004 - Distribution Board - .48 m2							
						Note: No inspection of live electrical installation	
Wall Linings Internal	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - M0005 - Plant - 9.84 m2							
No Asbestos							
B00A - M0006 - Movement - 9.76 m2							
No Asbestos							
B00A - M0007 - Communications Room - 44.95 m2							
No Asbestos							
B00A - M0008 - Stairs - 4.79 m2							
No Asbestos							
B00A - M0009 - Stairs - 3.21 m2							
No Asbestos							
B00A - M0010 - Stairs - 1.82 m2							
No Asbestos							
B00A - R0001 - Toilets - Boys - 14.94 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0002 - Personal Effects Storage - 15.46 m2							
No Asbestos							
B00A - R0003 - Main Switch Board - 5.92 m2							
Wall Linings Internal	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Electrical - Mounting Board	Resinous Board	1	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Floor Coverings Res/Textile	Compressed AC Sheet	1.5m2	South	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
B00A - R0004 - Movement - 11.62 m2							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0005 - Kiln Room - 5.27 m2							
Furniture / Fixtures	Compressed AC Sheet	3	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0006 - General Storeroom - 10.15 m2							
No Asbestos							
B00A - R0007 - General Storeroom - 10.05 m2							

No Asbestos							
B00A - R0008 - Seminar/Study - 8.94 m2							
No Asbestos							
B00A - R0009 - K.L.A. Store - 8.87 m2							
No Asbestos							
B00A - R0010 - Library Office/Workroom - 5.95 m2							
No Asbestos							
B00A - R0011 - Communications Room - 13.5 m2							
No Asbestos							
B00A - R0012 - Distribution Board - .59 m2							
Note: No inspection of live electrical installation							
Wall Linings Internal	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0013 - Library Office/Workroom - 20.56 m2							
No Asbestos							
B00A - R0014 - Movement - 30.8 m2							
No Asbestos							
B00A - R0015 - Movement - 26.66 m2							
No Asbestos							
B00A - R0016 - Reading Area - 173.9 m2							
No Asbestos							
B00A - R0017 - Craft Store - 12.36 m2							
No Asbestos							
B00A - R0018 - Personal Effects Storage - 17.18 m2							
No Asbestos							
B00A - R0019 - Toilets - Girls - 11.06 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0020 - Distribution Board - .64 m2							
Note: No inspection of live electrical installation							
Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0021 - Kiln Room - 7.55 m2							
Furniture / Fixtures	Compressed AC Sheet	3	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0022 - Practical Activities - 1hb - 35.92 m2							
No Asbestos							
B00A - R0023 - Cleaning Distributed Store - 2.77 m2							
No Asbestos							
B00A - R0024 - Craft Store - 2.77 m2							
No Asbestos							
B00A - R0025 - Home Base - 56.77 m2							
No Asbestos							
B00A - R0026 - Movement - 35.54 m2							
Ceiling Structures/Linings	Flat AC Sheeting	36m2	All surfaces	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0027 - Withdrawal Space - 1hb - 12.32 m2							
No Asbestos							
B00A - R0028 - Movement - 11.89 m2							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0029 - Movement - 28.55 m2							
Ceiling Structures/Linings	Flat AC Sheeting	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0030 - Movement - 140.86 m2							
No Asbestos							

B00A - R0031 - Movement - 26.84 m2							
Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0032 - Toilets - Boys - 14.89 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0033 - Personal Effects Storage - 15.41 m2							
No Asbestos							
B00A - R0034 - Practical Activities - 1hb - 37.48 m2							
No Asbestos							
B00A - R0035 - Cleaning Distributed Store - 2.86 m2							
No Asbestos							
B00A - R0036 - Craft Store - 2.89 m2							
No Asbestos							
B00A - R0037 - Movement - 36.85 m2							
Ceiling Structures/Linings	Flat AC Sheeting	37m2	All surfaces	Mnimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0038 - Home Base - 57.13 m2							
No Asbestos							
B00A - R0039 - Withdrawal Space - 1hb - 12.26 m2							
No Asbestos							
B00A - R0040 - General Storeroom - 10.12 m2							
No Asbestos							
B00A - R0041 - Movement - 31.32 m2							
No Asbestos							
B00A - R0043 - General Storeroom - 2.87 m2							
No Asbestos							
B00A - R0044 - General Storeroom - 3.08 m2							
No Asbestos							
B00A - R0045 - Cleaning Supplies - 5.86 m2							
No Asbestos							
B00A - R0046 - Raised Platform - 47.53 m2							
No Asbestos							
B00A - R0047 - Communal Space - 156.31 m2							
No Asbestos							
B00A - R0048 - Hall Chair Store - 30.81 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0049 - Cleaning Supplies - 7.5 m2							
No Asbestos							
B00A - R0050 - Toilets - Girls - 1.95 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0051 - Toilets - Boys - 1.95 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0052 - Staff Toilet - 1.95 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0053 - Movement - 34.08 m2							
Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0054 - Canteen - 28.04 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0055 - Canteen Office/Store - 2.44 m2							

Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0056 - Staff Toilet - 2.29 m2							
Wall Linings Internal	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0057 - Canteen Office/Store - 6.13 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0059 - Movement - 16.92 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0060 - General Storeroom - 9.03 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Flat AC Sheeting	9.02m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	33.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0061 - General Assistant/Bulk Store - 9.02 m2							
Wall Linings Internal	Flat AC Sheeting	45.8m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	9.02m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0062 - Garden Store - 12.36 m2							
Wall Linings Internal	Insulation Material	36.5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	12.35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0063 - Communications Room - 40.8 m2							
No Asbestos							
B00A - R0064 - General Assistant/Bulk Store - 24.86 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0065 - Deputy Principal - 11.83 m2							
No Asbestos							
B00A - R0066 - Clerical Office - 24.86 m2							
No Asbestos							
B00A - R0067 - Sick Bay - 9.94 m2							
No Asbestos							
B00A - R0068 - Duplicating Workroom - 18.61 m2							
No Asbestos							
B00A - R0069 - Movement - 24.13 m2							
No Asbestos							
B00A - R0070 - Entry Vestibule - 24.97 m2							
No Asbestos							
B00A - R0071 - Movement - 2.7 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0072 - Principal - 21.64 m2							
No Asbestos							
B00A - R0073 - Movement - 31.18 m2							
No Asbestos							
B00A - R0074 - Movement - 15.15 m2							
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0075 - Staff Toilet - 3.95 m2							
Wall Linings Internal	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0076 - Staff Toilet - 3.95 m2							

Wall Linings Internal	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0077 - Movement - 8.07 m2							
No Asbestos							
B00A - R0078 - Deputy Principal - 12.26 m2							
No Asbestos							
B00A - R0079 - General Storeroom - 12.36 m2							
No Asbestos							
B00A - R0080 - Toilets - Boys - 1.94 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
B00A - R0081 - Toilets - Girls - 1.92 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
B00A - R0082 - Toilets - Girls - 1.94 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
B00A - R0083 - Disabled Toilet - 2.98 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
B00A - R0084 - Personal Effects Storage - 25.02 m2							
No Asbestos							
B00A - R0085 - General Storeroom - 2.89 m2							
No Asbestos							
B00A - R0087 - Uniform Shop - 3.9 m2							
No Asbestos							
B00A - R0088 - Uniform Shop - 11.45 m2							
No Asbestos							
B00A - R0089 - Staff Toilet - 1.88 m2							
Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0090 - Toilets - Boys/Girls - 2.93 m2							
No Asbestos							
B00A - R0091 - Practical Activities - 1hb - 34.55 m2							
No Asbestos							
B00A - R0092 - Movement - 27.63 m2							
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0093 - Home Base - 54.75 m2							
No Asbestos							
B00A - R0094 - General Storeroom - 2.81 m2							
No Asbestos							
B00A - R0095 - General Storeroom - 2.81 m2							
No Asbestos							
B00A - R0096 - Home Base - 56.31 m2							
No Asbestos							
B00A - R0097 - Withdrawal Space - 1hb - 11.31 m2							
No Asbestos							
B00A - R0098 - Movement - 80.77 m2							
No Asbestos							
B00A - R0099 - Practical Activities - 1hb - 37.65 m2							
No Asbestos							
B00A - R0100 - General Storeroom - 2.8 m2							
No Asbestos							

B00A - R0101 - Cleaning Distributed Store - 2.8 m2							
No Asbestos							
B00A - R0102 - Home Base - 55.81 m2							
No Asbestos							
B00A - R0103 - Withdrawal Space - 1hb - 12.25 m2							
No Asbestos							
B00A - R0104 - Home Base - 57.87 m2							
No Asbestos							
B00A - R0105 - Movement - 27.69 m2							
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0106 - Disabled Toilet - 3.11 m2							
Wall Linings Internal	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0107 - Toilets - Girls - 1.91 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0108 - Toilets - Girls - 1.92 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0109 - Personal Effects Storage - 21.9 m2							
No Asbestos							
B00A - R0111 - General Storeroom - 11.32 m2							
No Asbestos							
B00A - R0112 - Withdrawal Space - 1hb - 17.65 m2							
No Asbestos							
B00A - R0113 - Practical Activities - 1hb - 37.73 m2							
No Asbestos							
B00A - R0114 - General Storeroom - 2.8 m2							
No Asbestos							
B00A - R0115 - Cleaning Distributed Store - 2.8 m2							
No Asbestos							
B00A - R0116 - Home Base - 55.6 m2							
No Asbestos							
B00A - R0117 - Movement - 27.53 m2							
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0118 - Home Base - 55.79 m2							
No Asbestos							
B00A - R0119 - Withdrawal Space - 1hb - 11.35 m2							
No Asbestos							
B00A - R0120 - Movement - 2.91 m2							
No Asbestos							
B00A - R0121 - Movement - 3.23 m2							
No Asbestos							
B00A - R0122 - Movement - 19.16 m2							
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0123 - Stairs - 2.66 m2							
No Asbestos							
B00A - R0124 - Stairs - 4.18 m2							
No Asbestos							
B00A - R0125 - Stairs - 1.15 m2							
No Asbestos							

B00B - Other-After School Care - 1996 - Brick/Block**Exterior**

Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area	
Eaves Linings	Flat AC Sheeting	

Interior**B00B - R0001 - Out Of School Hours Care Centre - 62.61 m2**

No Asbestos

B00B - R0002 - Toilets - Boys/Girls - 2.32 m2

No Asbestos

B00B - R0003 - Movement - 16.72 m2

Ceiling Structures/Linings	Flat AC Sheeting	
----------------------------	------------------	--

B00B - R0004 - Movement - 7.27 m2

No Asbestos

B00D - General Learning - 2010 - Brick/Veneer**Exterior**

Ceiling Voids	No Asbestos Found	
Underfloor Voids	Non Accessible Area	

Interior**B00D - R0001 - Home Base - 60.78 m2**

No Asbestos

B00D - R0002 - Home Base - 60.83 m2

No Asbestos

B00D - R0003 - Home Base Store - 6.34 m2

No Asbestos

B00D - R0004 - Toilets - Girls - 22.84 m2

No Asbestos

B00D - R0005 - Access Shower/Toilet/Change - 5.94 m2

No Asbestos

B00D - R0006 - Toilets - Boys - 16.21 m2

No Asbestos

B00D - R0007 - Practical Activities - 1hb - 18.62 m2

No Asbestos

B00D - R0008 - Withdrawal Space - 2hb - 11.34 m2

No Asbestos

B00D - R0009 - Practical Activities - 1hb - 18.5 m2

No Asbestos

B00D - R0010 - Home Base Store - 6.34 m2

No Asbestos

B00D - R0011 - External Movement - 77.66 m2

No Asbestos

Demountables

OS 606 18302 - Learning Unit - Standard With P.A.A A/C - Placement Date : 24-OCT-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found