


# Asbestos Register

(Hazardous Materials and Risk Assessment)

|                               |                                     |
|-------------------------------|-------------------------------------|
| <b>School:</b>                | <b>Lakemba Public School (2360)</b> |
| <b>Region:</b>                | <b>South Western Sydney AMU</b>     |
| <b>State Electorate:</b>      | <b>Lakemba</b>                      |
| <b>Local Government Area:</b> | <b>Canterbury-Bankstown</b>         |

|                          |                             |
|--------------------------|-----------------------------|
| <b>Last Reviewed By:</b> | <b>Greencap 14-DEC-2017</b> |
| <b>Last Revised By:</b>  |                             |

|   |            |
|---|------------|
| <b>Historical Fibro In Grounds Investigations/Events</b>  | <b>Yes</b> |
| Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2). |            |



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

| Rating                     | Description  |
|----------------------------|--|
| Good condition (1)         | For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles  |
| Minimal damage (2)         | For non-friable asbestos that has a very small amount of damage, eg hairline cracks.   |
| Some damage / unsealed (3) | For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed. |
| Poor condition (4)         | For non-friable asbestos that has extensive damage. Visible asbestos debris  |
| Friable asbestos (5)       | Any occurrence of friable asbestos   |

| Product   | Material Description | Extent | Location                        | Material Condition | Risk Status | Remediation Priority                                       | Result   |
|---|----------------------|--------|---------------------------------|--------------------|-------------|--|--|
| <b>B00A - General Learning/Tiered Learning - 1922 - Brick/Block</b> |                      |        |                                 |                    |             |  |  |
| <b>Exterior</b>   |                      |        |                                 |                    |             |  |  |
| Ceiling Voids   | AC Fragments/Debris  | 1      | Throughout                      | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos) |
| Underfloor Voids  | Vinyl Tiles          | 1      | Scattered Throught Western side | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)  |
| <b>Interior</b>   |                      |        |                                 |                    |             |  |  |
| <b>B00A - R0001 - Movement - 12.79 m2</b>                           |                      |        |                                 |                    |             |  |  |
| No Asbestos   |                      |        |                                 |                    |             |  |  |
| <b>B00A - R0002 - Cleaning Supplies - 12.14 m2</b>                  |                      |        |                                 |                    |             |  |  |
| No Asbestos   |                      |        |                                 |                    |             |  |  |
| <b>B00A - R0003 - Toilets - Boys - 20.3 m2</b>                      |                      |        |                                 |                    |             |  |  |
| Partition Walls (Cubicles)  | Compressed AC Sheet  | 6m2    | All surfaces                    | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)  |
| Ceiling Structures/Linings  | No Asbestos Found    |        |                                 |                    |             |  |  |
| <b>B00A - R0004 - General Storeroom - 3.9 m2</b>                    |                      |        |                                 |                    |             |  |  |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 4m2    | Throughout                      | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)  |
| <b>B00A - R0005 - Distribution Board - .57 m2</b>                   |                      |        |                                 |                    |             | <b>Note: No inspection of live electrical installation</b> |  |
| Non Accessible  |                      |        |                                 |                    |             |  |  |
| <b>B00A - R0006 - Toilets - Girls - 23.54 m2</b>                    |                      |        |                                 |                    |             |  |  |
| Partition Walls (Cubicles)  | Compressed AC Sheet  | 6m2    | All surfaces                    | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)  |
| Ceiling Structures/Linings  | No Asbestos Found    |        |                                 |                    |             |  |  |
| <b>B00A - R0007 - Special Programs Room - 35.26 m2</b>              |                      |        |                                 |                    |             |  |  |
| Non Accessible  |                      |        |                                 |                    |             |  |  |
| <b>B00A - R0008 - Withdrawal Space - 1hb - 12.33 m2</b>             |                      |        |                                 |                    |             |  |  |
| Ceiling Structures/Linings  | No Asbestos Found    |        |                                 |                    |             |  |  |
| <b>B00A - R0009 - Home Base - 59.75 m2</b>                          |                      |        |                                 |                    |             |  |  |
| No Asbestos   |                      |        |                                 |                    |             |  |  |
| <b>B00A - R0010 - Home Base Store - 5.42 m2</b>                     |                      |        |                                 |                    |             |  |  |
| Ceiling Structures/Linings  | No Asbestos Found    |        |                                 |                    |             |  |  |
| <b>B00A - R0011 - Home Base - 59.8 m2</b>                           |                      |        |                                 |                    |             |  |  |
| Ceiling Structures/Linings  | No Asbestos Found    |        |                                 |                    |             |  |  |
| <b>B00A - R0012 - Home Base Store - 5.29 m2</b>                     |                      |        |                                 |                    |             |  |  |
| Ceiling Structures/Linings  | No Asbestos Found    |        |                                 |                    |             |  |  |
| <b>B00A - R0013 - Movement - 64.51 m2</b>                           |                      |        |                                 |                    |             |  |  |
| Non Accessible  |                      |        |                                 |                    |             |  |  |
| <b>B00A - R0014 - Practical Activities - 1hb - 22.8 m2</b>          |                      |        |                                 |                    |             |  |  |
| No Asbestos   |                      |        |                                 |                    |             |  |  |
| <b>B00A - R0015 - Withdrawal Space - 1hb - 12.13 m2</b>             |                      |        |                                 |                    |             |  |  |
| Ceiling Structures/Linings  | Flat AC Sheeting     | 13m2   | Variable positions              | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)  |

|   |                   |  |
|---|-------------------|--|
| <b>B00A - R0016 - Personal Effects Storage - 13.39 m2</b>   |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0017 - Home Base - 61.5 m2</b>                   |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0018 - Home Base Store - 5.13 m2</b>             |                   |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |  |
| <b>B00A - R0019 - Home Base - 62.24 m2</b>                  |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0020 - Home Base Store - 5.42 m2</b>             |                   |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |  |
| <b>B00A - R0021 - Practical Activities - 1hb - 31.62 m2</b> |                   |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |  |
| <b>B00A - R0022 - Movement - 9.66 m2</b>                    |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0023 - Movement - 1.9 m2</b>                     |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0024 - General Storeroom - 4.79 m2</b>           |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0025 - Personal Effects Storage - 7.22 m2</b>    |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0026 - Withdrawal Space - 1hb - 12.01 m2</b>     |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0027 - Home Base - 62.41 m2</b>                  |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0028 - Home Base Store - 5.41 m2</b>             |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0029 - Practical Activities - 1hb - 31.43 m2</b> |                   |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |  |
| <b>B00A - R0030 - Home Base - 61.19 m2</b>                  |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0031 - Home Base Store - 5.4 m2</b>              |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0032 - Main Switch Board - 12.72 m2</b>          |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0033 - Movement - 9.72 m2</b>                    |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0034 - Movement - 2.02 m2</b>                    |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0035 - General Storeroom - 5.44 m2</b>           |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0036 - Lift - 1.61 m2</b>                        |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0037 - External Movement - 159.48 m2</b>         |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0038 - Stairs - 5.5 m2</b>                       |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0039 - Stairs - 7.67 m2</b>                      |                   |  |
| No Asbestos   |                   |  |
| <b>B00A - R0040 - Stairs - 7.27 m2</b>                      |                   |  |

|   |   |      |                    |                    |         |                    |  |
|---|---|------|--------------------|--------------------|---------|--------------------|--|
| No Asbestos   |   |      |                    |                    |         |                    |  |
| <b>B00A - R1001 - Movement - 13.44 m2</b>                   |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | Flat AC Sheeting  | 14m2 | All surfaces       | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00A - R1002 - Toilets - Boys - 20.23 m2</b>             |   |      |                    |                    |         |                    |  |
| Partition Walls (Cubicles)                                  | Compressed AC Sheet                                     | 6m2  | All surfaces       | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos)                            |
| Ceiling Structures/Linings                                  | No Asbestos Found                                       |      |                    |                    |         |                    |  |
| <b>B00A - R1003 - General Storeroom - 3.81 m2</b>           |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )    |      |                    |                    |         |                    |  |
| <b>B00A - R1004 - Cleaning Distributed Store - .74 m2</b>   |   |      |                    |                    |         |                    |  |
| No Asbestos   |   |      |                    |                    |         |                    |  |
| <b>B00A - R1005 - Toilets - Girls - 23.52 m2</b>            |   |      |                    |                    |         |                    |  |
| Partition Walls (Cubicles)                                  | Compressed AC Sheet                                     | 6m2  | All surfaces       | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos)                            |
| Ceiling Structures/Linings                                  | No Asbestos Found                                       |      |                    |                    |         |                    |  |
| <b>B00A - R1006 - Special Programs Room - 47.16 m2</b>      |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | Flat AC Sheeting  | 48m2 | All surfaces       | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00A - R1007 - Practical Activities - 1hb - 23.12 m2</b> |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | Flat AC Sheeting  | 24m2 | All surfaces       | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos)                            |
| <b>B00A - R1008 - Home Base Store - 6.37 m2</b>             |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | Flat AC Sheeting  | 7m2  | All surfaces       | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos)                            |
| <b>B00A - R1009 - Security Store - 16.05 m2</b>             |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | Flat AC Sheeting  | 17m2 | All surfaces       | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos)                            |
| <b>B00A - R1010 - Movement - 53.58 m2</b>                   |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | Flat AC Sheeting  | 34m2 | Variable positions | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos)                            |
| Ceiling Structures/Linings                                  | Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 ) |      |                    |                    |         |                    |  |
| <b>B00A - R1011 - Movement - 17.55 m2</b>                   |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found                                       |      |                    |                    |         |                    |  |
| <b>B00A - R1012 - Movement - 3.4 m2</b>                     |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found                                       |      |                    |                    |         |                    |  |
| <b>B00A - R1013 - Home Base - 62.18 m2</b>                  |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found                                       |      |                    |                    |         |                    |  |
| <b>B00A - R1014 - Practical Activities - 1hb - 43.95 m2</b> |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found                                       |      |                    |                    |         |                    |  |
| <b>B00A - R1015 - Home Base - 61.42 m2</b>                  |   |      |                    |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found                                       |      |                    |                    |         |                    |  |
| <b>B00A - R1016 - Home Base Store - 5.33 m2</b>             |   |      |                    |                    |         |                    |  |

|   |                   |      |            |                    |         |                    |  |
|---|-------------------|------|------------|--------------------|---------|--------------------|--|
| Ceiling Structures/Linings                                  | No Asbestos Found |      |            |                    |         |                    |  |
| <b>B00A - R1017 - Movement - 7.95 m2</b>                    |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |      |            |                    |         |                    |  |
| <b>B00A - R1018 - Home Base - 61.13 m2</b>                  |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |      |            |                    |         |                    |  |
| <b>B00A - R1019 - Home Base Store - 5.33 m2</b>             |                   |      |            |                    |         |                    |  |
| No Asbestos   |                   |      |            |                    |         |                    |  |
| <b>B00A - R1020 - General Storeroom - 12.6 m2</b>           |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |      |            |                    |         |                    |  |
| <b>B00A - R1021 - Practical Activities - 1hb - 43.71 m2</b> |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |      |            |                    |         |                    |  |
| <b>B00A - R1022 - Home Base - 60.95 m2</b>                  |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |      |            |                    |         |                    |  |
| <b>B00A - R1023 - Home Base Store - 5.12 m2</b>             |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |      |            |                    |         |                    |  |
| <b>B00A - R1024 - Personal Effects Storage - 12.44 m2</b>   |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |      |            |                    |         |                    |  |
| <b>B00A - R1025 - Movement - 3.56 m2</b>                    |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | No Asbestos Found |      |            |                    |         |                    |  |
| <b>B00A - R1026 - Stairs - 19.26 m2</b>                     |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | Flat AC Sheeting  | 20m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Assumed Asbestos   |
| <b>B00A - R1027 - Stairs - 12.55 m2</b>                     |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | Flat AC Sheeting  | 13m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Assumed Asbestos   |
| <b>B00A - R1028 - Stairs - 12.56 m2</b>                     |                   |      |            |                    |         |                    |  |
| Ceiling Structures/Linings                                  | Flat AC Sheeting  | 13m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) | Assumed Asbestos   |
| <b>B00B - Administration/Library - 1964 - Brick/Block</b>   |                   |      |            |                    |         |                    |  |
| <b>Exterior</b>   |                   |      |            |                    |         |                    |  |
| Ceiling Voids   | No Asbestos Found |      |            |                    |         |                    |  |
| Underfloor Voids  | No Asbestos Found |      |            |                    |         |                    |  |
| Eaves Linings   | Flat AC Sheeting  |      |            |                    |         |                    |  |
| <b>Interior</b>   |                   |      |            |                    |         |                    |  |
| <b>B00B - R0001 - Interview - 13.22 m2</b>                  |                   |      |            |                    |         |                    |  |
| No Asbestos   |                   |      |            |                    |         |                    |  |
| <b>B00B - R0002 - Interview - 12.97 m2</b>                  |                   |      |            |                    |         |                    |  |
| No Asbestos   |                   |      |            |                    |         |                    |  |
| <b>B00B - R0003 - Distribution Board - 1.44 m2</b>          |                   |      |            |                    |         |                    |  |
|   |                   |      |            |                    |         |                    | <b>Note: No inspection of live electrical installation</b> |
| No Asbestos   |                   |      |            |                    |         |                    |  |
| <b>B00B - R0005 - Principal - 21.81 m2</b>                  |                   |      |            |                    |         |                    |  |
| No Asbestos   |                   |      |            |                    |         |                    |  |
| <b>B00B - R0006 - Duplicating Workroom - 22.35 m2</b>       |                   |      |            |                    |         |                    |  |
| No Asbestos   |                   |      |            |                    |         |                    |  |

|   |  |
|---|--|
| <b>B00B - R0007 - Security Store - 9.69 m2</b>            |  |
| No Asbestos   |  |
| <b>B00B - R0008 - Plant - .32 m2</b>                      |  |
| No Asbestos   |  |
| <b>B00B - R0009 - Staff Room - 58.74 m2</b>               |  |
| No Asbestos   |  |
| <b>B00B - R0014 - Sick Bay - 8.63 m2</b>                  |  |
| No Asbestos   |  |
| <b>B00B - R0015 - Clerical Office/Workroom - 13.26 m2</b> |  |
| No Asbestos   |  |
| <b>B00B - R0016 - Entry Vestibule - 28.9 m2</b>           |  |
| No Asbestos   |  |
| <b>B00B - R0017 - Movement - 2.47 m2</b>                  |  |
| Ceiling Structures/Linings                                | Flat AC Sheeting   |
| <b>B00B - R0018 - Access Shower/Toilet - 5.49 m2</b>      |  |
| No Asbestos   |  |
| <b>B00B - R0019 - Toilet - Lobby - 2.29 m2</b>            |  |
| No Asbestos   |  |
| <b>B00B - R0020 - Staff Toilet - 2.17 m2</b>              |  |
| No Asbestos   |  |
| <b>B00B - R0021 - Toilet - Lobby - 1.3 m2</b>             |  |
| No Asbestos   |  |
| <b>B00B - R0022 - Staff Toilet - 1.72 m2</b>              |  |
| No Asbestos   |  |
| <b>B00B - R0023 - Toilet - Lobby - 1.3 m2</b>             |  |
| No Asbestos   |  |
| <b>B00B - R0024 - Staff Toilet - 1.72 m2</b>              |  |
| No Asbestos   |  |
| <b>B00B - R0025 - Deputy Principal - 19.02 m2</b>         |  |
| No Asbestos   |  |
| <b>B00B - R0026 - Entry Vestibule - 22.6 m2</b>           |  |
| No Asbestos   |  |
| <b>B00B - R0027 - Lift - 1.61 m2</b>                      |  |
| No Asbestos   |  |
| <b>B00B - R0028 - External Movement - 48.66 m2</b>        |  |
| No Asbestos   |  |
| <b>B00B - R0029 - Stairs - 12.84 m2</b>                   |  |
| No Asbestos   |  |
| <b>B00B - R1001 - Reading Area - 169.29 m2</b>            |  |
| No Asbestos   |  |
| <b>B00B - R1002 - Distribution Board - 1.61 m2</b>        |  |
| No Asbestos   | <b>Note: No inspection of live electrical installation</b> |
| <b>B00B - R1003 - Movement - 18.14 m2</b>                 |  |
| No Asbestos   |  |
| <b>B00B - R1004 - K.L.A. Store - 22.4 m2</b>              |  |
| No Asbestos   |  |
| <b>B00B - R1005 - Communications Room - 12.11 m2</b>      |  |
| No Asbestos   |  |
| <b>B00B - R1006 - Library Office/Workroom - 24.59 m2</b>  |  |
| No Asbestos   |  |
| <b>B00B - R1007 - Stairs - 12.84 m2</b>                   |  |

|   |                     |       |                               |                          |            |  |                             |
|---|---------------------|-------|-------------------------------|--------------------------|------------|--|-----------------------------|
| No Asbestos   |                     |       |                               |                          |            |  |                             |
| <b>B00C - General Learning/Staff Facilities - 1922 - Brick/Block</b>    |                     |       |                               |                          |            |  |                             |
| <b>Exterior</b>   |                     |       |                               |                          |            |  |                             |
| Eaves Linings   | Flat AC Sheeting    | 40m2  | North facing,<br>South facing | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| Ceiling Voids   | Non Accessible Area |       |                               |                          |            |  |                             |
| Underfloor Voids  | Non Accessible Area |       |                               |                          |            |  |                             |
| <b>Interior</b>   |                     |       |                               |                          |            |  |                             |
| <b>B00C - R0001 - Staff Room Annexe - 17.3 m2</b>                       |                     |       |                               |                          |            |  |                             |
| Ceiling<br>Structures/Linings   | Flat AC Sheeting    | 18m2  | All surfaces                  | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| <b>B00C - R0002 - Staff Toilet - 2.15 m2</b>                            |                     |       |                               |                          |            |  |                             |
| Ceiling<br>Structures/Linings   | Flat AC Sheeting    | 3m2   | All surfaces                  | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| <b>B00C - R0003 - Movement - 8.69 m2</b>                                |                     |       |                               |                          |            |  |                             |
| Ceiling<br>Structures/Linings   | Flat AC Sheeting    | 9m2   | All surfaces                  | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| <b>B00C - R0004 - Movement - 2.16 m2</b>                                |                     |       |                               |                          |            |  |                             |
| Ceiling<br>Structures/Linings   | Flat AC Sheeting    | 3m2   | All surfaces                  | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| <b>B00C - R0005 - Practical Activities - 1hb - 17.36 m2</b>             |                     |       |                               |                          |            |  |                             |
| Ceiling<br>Structures/Linings   | Flat AC Sheeting    | 18m2  | All surfaces                  | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| <b>B00C - R0006 - Home Base - 54.42 m2</b>                              |                     |       |                               |                          |            |  |                             |
| Ceiling<br>Structures/Linings   | Flat AC Sheeting    | 55m2  | All surfaces                  | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| <b>B00C - R0007 - Home Base Store - 10.66 m2</b>                        |                     |       |                               |                          |            |  |                             |
| Ceiling<br>Structures/Linings   | Flat AC Sheeting    | 11m2  | All surfaces                  | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| <b>B00C - R0008 - Distribution Board - .35 m2</b>                       |                     |       |                               |                          |            | <b>Note: No inspection of live electrical installation</b> |                             |
| No Asbestos   |                     |       |                               |                          |            |  |                             |
| <b>B00C - R0009 - Personal Effects Storage - 5.38 m2</b>                |                     |       |                               |                          |            |  |                             |
| Ceiling<br>Structures/Linings   | Flat AC Sheeting    | 6m2   | All surfaces                  | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| <b>B00C - R0010 - Movement - 2.79 m2</b>                                |                     |       |                               |                          |            |  |                             |
| Ceiling<br>Structures/Linings   | Flat AC Sheeting    | 3m2   | All surfaces                  | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| <b>B00D - Communal Facilities/Pupil Facilities - 1964 - Brick/Block</b> |                     |       |                               |                          |            |  |                             |
| <b>Exterior</b>   |                     |       |                               |                          |            |  |                             |
| Eaves Linings   | Flat AC Sheeting    |       |                               |                          |            |  |                             |
| Ceiling Voids   | No Asbestos Found   |       |                               |                          |            |  |                             |
| Underfloor Voids  | No Asbestos Found   |       |                               |                          |            |  |                             |
| <b>Interior</b>   |                     |       |                               |                          |            |  |                             |
| <b>B00D - R0001 - Movement - 159.34 m2</b>                              |                     |       |                               |                          |            |  |                             |
| Ceiling<br>Structures/Linings   | Flat AC Sheeting    | 160m2 | All surfaces                  | Good<br>Condition<br>(1) | Low<br>(1) | Low Priority<br>(2-3)                                      | Chrysotile (white asbestos) |
| <b>B00D - R0002 - Toilets - Boys - 12.92 m2</b>                         |                     |       |                               |                          |            |  |                             |



|   |                     |      |              |                    |         |  |                             |
|---|---------------------|------|--------------|--------------------|---------|--|-----------------------------|
| Partition Walls (Cubicles)                                  | Compressed AC Sheet | 4m2  | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)   | Chrysotile (white asbestos) |
| <b>B00D - R0003 - Cleaning Supplies - 6.86 m2</b>           |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0004 - Toilets - Girls - 12.94 m2</b>            |                     |      |              |                    |         |  |                             |
| Partition Walls (Cubicles)                                  | Compressed AC Sheet | 4m2  | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)   | Chrysotile (white asbestos) |
| <b>B00D - R0005 - General Storeroom - 25.32 m2</b>          |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0006 - Canteen Office/Store - 3.11 m2</b>        |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0007 - Staff Toilet - 3.09 m2</b>                |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0008 - Canteen Office/Store - 5.29 m2</b>        |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0009 - Canteen - 26.74 m2</b>                    |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0010 - Communal Space - 156.5 m2</b>             |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0011 - Hall Chair Store - 2.41 m2</b>            |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0012 - Movement - 2.46 m2</b>                    |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0013 - Movement - 2.46 m2</b>                    |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0014 - General Storeroom - 11.73 m2</b>          |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0015 - Raised Platform - 31.7 m2</b>             |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0016 - Distribution Board - .75 m2</b>           |                     |      |              |                    |         |  |                             |
|   |                     |      |              |                    |         | <b>Note: No inspection of live electrical installation</b> |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0017 - Sports Store - 19.97 m2</b>               |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0018 - Distribution Board - .68 m2</b>           |                     |      |              |                    |         |  |                             |
|   |                     |      |              |                    |         | <b>Note: No inspection of live electrical installation</b> |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0019 - General Storeroom - 4.39 m2</b>           |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0020 - Practical Activities - 1hb - 38.55 m2</b> |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0021 - Home Base Store - 5.36 m2</b>             |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0022 - Home Base Store - 4.78 m2</b>             |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0023 - Home Base - 59.43 m2</b>                  |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0024 - Movement - 10.16 m2</b>                   |                     |      |              |                    |         |  |                             |
| Ceiling Structures/Linings                                  | Flat AC Sheeting    | 11m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)   | Chrysotile (white asbestos) |
| <b>B00D - R0025 - Withdrawal Space - 1hb - 10.12 m2</b>     |                     |      |              |                    |         |  |                             |
| No Asbestos   |                     |      |              |                    |         |  |                             |
| <b>B00D - R0026 - Movement - 9.8 m2</b>                     |                     |      |              |                    |         |  |                             |

|  |                  |      |              |                    |         |                    |                             |
|--|------------------|------|--------------|--------------------|---------|--------------------|-----------------------------|
| Ceiling Structures/Linings   | Flat AC Sheeting | 10m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00D - R0027 - Home Base - 59.55 m2</b>                           |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00D - R0028 - Home Base Store - 4.85 m2</b>                      |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00D - R0029 - General Assistant/Bulk Store - 11.64 m2</b>        |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00D - R0030 - Movement - 12.55 m2</b>                            |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - General Learning - 2010 - Brick/Veneer</b>                 |                  |      |              |                    |         |                    |                             |
| <b>Exterior</b>  |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>Interior</b>  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0001 - Practical Activities/Movement - 1hb - 19.04 m2</b> |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0002 - Home Base - 60.56 m2</b>                           |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0003 - Home Base Store - 6.09 m2</b>                      |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0004 - Withdrawal Space - 2hb - 11.68 m2</b>              |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0005 - Practical Activities/Movement - 1hb - 19.14 m2</b> |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0006 - Home Base - 60.44 m2</b>                           |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0007 - Home Base Store - 6.12 m2</b>                      |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0008 - Practical Activities/Movement - 1hb - 18.61 m2</b> |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0009 - Home Base - 60.56 m2</b>                           |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0010 - Home Base Store - 6.09 m2</b>                      |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0011 - Withdrawal Space - 2hb - 11.75 m2</b>              |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0012 - Practical Activities - 1hb - 19.12 m2</b>          |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0013 - Home Base - 60.57 m2</b>                           |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0014 - Home Base Store - 6.12 m2</b>                      |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0015 - External Movement - 91.3 m2</b>                    |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |
| <b>B00J - R0016 - No Access - .39 m2</b>                             |                  |      |              |                    |         |                    |                             |
| No Asbestos  |                  |      |              |                    |         |                    |                             |

**Demountables****OS 751 12139 - Learning Unit - ESL - Placement Date : 30-JUN-1995****Exterior**

|               |                     |         |                  |
|---------------|---------------------|---------|------------------|
| Eaves Linings | Flat AC Sheeting    | 11.52m2 | Assumed Asbestos |
| Landing       | Compressed AC Sheet | 1.2m2   | Assumed Asbestos |
| Step Treads   | Compressed AC Sheet | 1.08m2  | Assumed Asbestos |

**Interior****R1- EsI**

|                            |                  |      |                  |
|----------------------------|------------------|------|------------------|
| End Wall Panel             | Flat AC Sheeting | 18m2 | Assumed Asbestos |
| Ceiling Structures/Linings | Flat AC Sheeting | 36m2 | Assumed Asbestos |

**R2- EsI**

|                            |                  |      |                  |
|----------------------------|------------------|------|------------------|
| End Wall Panel             | Flat AC Sheeting | 18m2 | Assumed Asbestos |
| Ceiling Structures/Linings | Flat AC Sheeting | 36m2 | Assumed Asbestos |

**OS 602 12391 - Learning Unit - Standard With P.A.A. - Placement Date : 16-NOV-2012**

No Asbestos Found

**OS 534 12563 - Library/Group Study/Office/A V Store - Placement Date : 11-MAR-2003****Exterior**

|               |                     |         |                  |
|---------------|---------------------|---------|------------------|
| Eaves Linings | Flat AC Sheeting    | 23.04m2 | Assumed Asbestos |
| Landing       | Compressed AC Sheet | 1.2m2   | Assumed Asbestos |
| Step Treads   | Compressed AC Sheet | 1.08m2  | Assumed Asbestos |

**Interior****R1- Clerical Office**

|                            |                  |      |                  |
|----------------------------|------------------|------|------------------|
| End Wall Panel             | Flat AC Sheeting | 18m2 | Assumed Asbestos |
| Ceiling Structures/Linings | Flat AC Sheeting | 8m2  | Assumed Asbestos |

**R2- Staff Room**

|                            |                  |      |                  |
|----------------------------|------------------|------|------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 36m2 | Assumed Asbestos |
|----------------------------|------------------|------|------------------|

**R3- Security Store**

|                            |                  |     |                  |
|----------------------------|------------------|-----|------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 8m2 | Assumed Asbestos |
|----------------------------|------------------|-----|------------------|

**R4- Principal**

|                            |                  |      |                  |
|----------------------------|------------------|------|------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 16m2 | Assumed Asbestos |
|----------------------------|------------------|------|------------------|

**R5- Staff Toilet**

|                            |                     |     |                  |
|----------------------------|---------------------|-----|------------------|
| Toilet Partitions          | Compressed AC Sheet | 4m2 | Assumed Asbestos |
| Ceiling Structures/Linings | Flat AC Sheeting    | 5m2 | Assumed Asbestos |

**R6- Staff Toilet**

|                            |                     |     |                  |
|----------------------------|---------------------|-----|------------------|
| Toilet Partitions          | Compressed AC Sheet | 4m2 | Assumed Asbestos |
| Ceiling Structures/Linings | Flat AC Sheeting    | 5m2 | Assumed Asbestos |

**R7- Reading Area**

|                            |                  |      |                  |
|----------------------------|------------------|------|------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 54m2 | Assumed Asbestos |
|----------------------------|------------------|------|------------------|

**R8- Entry**

|                            |                  |      |                  |
|----------------------------|------------------|------|------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 14m2 | Assumed Asbestos |
|----------------------------|------------------|------|------------------|

**OS 602 14067 - Learning Unit - Standard With P.A.A. - Placement Date : 13-FEB-2014**

No Asbestos Found

**OS 602 15795 - Learning Unit - Standard With P.A.A. - Placement Date : 14-MAR-2013****Exterior**

|               |                     |         |                  |
|---------------|---------------------|---------|------------------|
| Eaves Linings | Flat AC Sheeting    | 11.52m2 | Assumed Asbestos |
| Landing       | Compressed AC Sheet | 1.2m2   | Assumed Asbestos |
| Step Treads   | Compressed AC Sheet | 1.08m2  | Assumed Asbestos |

**Interior****R1- Learning space/withdrawal/entry**

|   |                  |      |                  |
|---|------------------|------|------------------|
| Ceiling Structures/Linings  | Flat AC Sheeting | 70m2 | Assumed Asbestos |
| <b>R2- Home Base Store</b>  |                  |      |                  |
| End Wall Panel  | Flat AC Sheeting | 18m2 | Assumed Asbestos |
| Ceiling Structures/Linings  | Flat AC Sheeting | 3m2  | Assumed Asbestos |
| <b>OS 840 16225 - Girls Toilet - Placement Date : 25-JUL-2014</b>                                       |                  |      |                  |
| <b>Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.</b> |                  |      |                  |
| No Asbestos Found   |                  |      |                  |
| <b>OS 602 18259 - Learning Unit - Standard With P.A.A. - Placement Date : 18-JAN-2017</b>               |                  |      |                  |
| <b>Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.</b> |                  |      |                  |
| No Asbestos Found   |                  |      |                  |