

Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning/Pupil Facilities - 1981 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	110m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Gable Verge Lining	Flat AC Sheeting	100m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - External Movement - 42.1 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0002 - Toilets - Girls - 19.8 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0005 - P.E Store - 20.59 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0006 - Movement - 10.79 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0007 - General Storeroom - 5.33 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B00A - R0008 - Garden Store - 15.25 m2							
No Asbestos							
B00A - R0009 - External Movement - 179.36 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0010 - General Storeroom - 13.39 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B00A - R0011 - Distribution Board - .45 m2							
						Note: No inspection of live electrical installation	
No Asbestos							
B00A - R0012 - General Storeroom - 13 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0013 - Teachers Aide Special Ed - 16.06 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0014 - Home Base - M - 51.63 m2							
No Asbestos							
B00A - R0015 - Practical Activities - M - 1hb - 18.83 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0016 - External Movement - 77.4 m2							
No Asbestos							
B00A - R0017 - Music Store - 14.13 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0018 - Movement - 9.44 m2							

Floor Coverings Res/Textile	Vinyl Tiles							
B00A - R0021 - P.E. Store - 7.12 m2								
No Asbestos								
B00A - R0022 - Cleaning Distributed Store - 2.3 m2								
No Asbestos								
B00A - R0023 - Distribution Board - .39 m2								
Note: No inspection of live electrical installation								
Non Accessible								
B00A - R0024 - Toilets - Boys - 20.58 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00A - R0025 - Canteen - 45.06 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00A - R0026 - Canteen Office/Store - 2.91 m2								
No Asbestos								
B00A - R0027 - Staff Toilet - 9.7 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00A - R0028 - Adjoining School - 7.5 m2								
Ceiling Structures/Linings	Flat AC Sheeting							
B00A - R0030 - Adjoining School - 6.93 m2								
No Asbestos								
B00A - R0031 - Communal Space - 256.63 m2								
No Asbestos								
B00A - R0032 - Raised Platform - 105.55 m2								
No Asbestos								
B00A - R0033 - Movement - 4.01 m2								
No Asbestos								
B00A - R0034 - Movement - 8.35 m2								
No Asbestos								
B00A - R0035 - Communal/Performance Store - 11.27 m2								
No Asbestos								
B00A - R0036 - Cleaning Distributed Store - 3.42 m2								
No Asbestos								
B00A - R0037 - Disabled Toilet - 2.88 m2								
No Asbestos								
B00A - R1001 - Movement - 14.24 m2								
No Asbestos								
B00A - R1002 - Movement - 44.84 m2								
No Asbestos								
B00A - R1003 - General Storeroom - 9.21 m2								
No Asbestos								
B00A - R1004 - Practical Activities - 1hb - 18.8 m2								
No Asbestos								
B00A - R1005 - Home Base - 51.94 m2								
No Asbestos								
B00A - R1006 - Home Base - 51.87 m2								
No Asbestos								
B00A - R1007 - Practical Activities - 1hb - 18.64 m2								
No Asbestos								

B00A - R1008 - Withdrawal Space - 1hb - 9.07 m2							
No Asbestos							
B00A - R1009 - Security Store - 18.66 m2							
No Asbestos							
B00A - R1010 - Home Base - 51.71 m2							
No Asbestos							
B00A - R1011 - Practical Activities - 1hb - 18.4 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R1012 - Distribution Board - .36 m2							Note: No inspection of live electrical installation
No Asbestos							
B00A - R1013 - Cleaning Distributed Store - 4.5 m2							
No Asbestos							
B00A - R1014 - General Storeroom - 13.78 m2							
No Asbestos							
B00A - R1015 - Withdrawal Space - 1hb - 15.46 m2							
No Asbestos							
B00A - R1016 - Home Base - 51.64 m2							
No Asbestos							
B00A - R1017 - Practical Activities - 1hb - 18.56 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R1018 - Movement - 72.49 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R1019 - Movement - 7.37 m2							
No Asbestos							
B00A - R1020 - Toilets - Girls - 17.47 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R1021 - Practical Activities - 1hb - 18.56 m2							
No Asbestos							
B00A - R1022 - Home Base - 51.87 m2							
No Asbestos							
B00A - R1023 - Home Base - 51.79 m2							
No Asbestos							
B00A - R1024 - Practical Activities - 1hb - 18.49 m2							
No Asbestos							
B00A - R1025 - Toilets - Boys - 19.25 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R1026 - Adjoining School - 19.46 m2							
No Asbestos							
B00A - R1027 - Adjoining School - 15.38 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00B - General Learning - 1981 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	70m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Gable Verge Lining	Flat AC Sheeting	40m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00B - R0001 - Home Base - 66.69 m2							
No Asbestos							
B00B - R0002 - Practical Activities - 1hb - 22.98 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0003 - Toilets - Boys/Girls - 2.87 m2							
No Asbestos							
B00B - R0004 - Toilets - Girls - 23.66 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0005 - Cleaning Distributed Store - .97 m2							
No Asbestos							
B00B - R0006 - Toilets - Boys - 17.76 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0007 - Movement - 61.05 m2							
Ceiling Structures/Linings	Flat AC Sheeting	62m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0008 - Home Base - 73.71 m2							
No Asbestos							
B00B - R0009 - Toilets - Boys/Girls - 2.87 m2							
No Asbestos							
B00B - R0010 - Practical Activities - 1hb - 16.71 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0011 - Practical Activities - 1hb - 16.71 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0012 - Toilets - Boys/Girls - 2.82 m2							
No Asbestos							
B00B - R0013 - Home Base - 73.71 m2							
No Asbestos							
B00B - R0014 - General Storeroom - 13.86 m2							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0015 - Distribution Board - .54 m2							
Note: No inspection of live electrical installation							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0016 - Craft Store - 9.79 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0017 - External Movement - 14.36 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00C - Administration/Library - 1981 - Brick/Block

Exterior

Eaves Linings	Flat AC Sheeting	3m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						

Interior

B00C - R0001 - Deputy Principal - 11.36 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
----------------------------	---------------------------------------------------------	--	--	--	--	--	--

B00C - R0002 - Movement - 22.82 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
----------------------------	---------------------------------------------------------	--	--	--	--	--	--

B00C - R0003 - Staff Kitchen - 11.49 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
----------------------------	---------------------------------------------------------	--	--	--	--	--	--

B00C - R0004 - Staff Room - 109 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	North west	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00C - R0005 - Staff Toilet - 5.85 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
----------------------------	------------------------------------------------------	--	--	--	--	--	--

B00C - R0006 - Staff Toilet - 4.17 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
----------------------------	------------------------------------------------------	--	--	--	--	--	--

B00C - R0007 - General Storeroom - 1.35 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
----------------------------	------------------------------------------------------	--	--	--	--	--	--

B00C - R0008 - Deputy Principal - 11.33 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
----------------------------	---------------------------------------------------------	--	--	--	--	--	--

B00C - R0009 - Movement - 17.31 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
----------------------------	---------------------------------------------------------	--	--	--	--	--	--

B00C - R0010 - Distribution Board - 2.98 m2

Note: No inspection of live electrical installation

Electrical - Mounting Board	Resinous Board	5	West facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
-----------------------------	----------------	---	---------------------------------	--------------------	---------	--------------------	-----------------------------

B00C - R0011 - Principal - 15.46 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
----------------------------	---------------------------------------------------------	--	--	--	--	--	--

B00C - R0012 - Staff Toilet - 4.2 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
----------------------------	------------------------------------------------------	--	--	--	--	--	--

B00C - R0013 - Entry Vestibule - 21.47 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	North west	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00C - R0014 - Clerical Office/Workroom - 8.36 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
----------------------------	------------------------------------------------------	--	--	--	--	--	--

B00C - R0015 - Clerical Office - 12.39 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R0016 - Duplicating Workroom - 21.82 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0017 - General Storeroom - 8.99 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00C - R0018 - Staff Toilet - 2.94 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00C - R0019 - Cleaning Distributed Store - 1.23 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00C - R0020 - Sick Bay - 12.21 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R1001 - Seminar/Study - 19.59 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R1002 - Seminar/Study - 16.15 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R1003 - Reading Area - 236.14 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (120 - 250 m2) - (X15)						
B00C - R1004 - External Movement - 1.82 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00C - R1005 - Movement - 12.01 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R1006 - Entry Vestibule - 2.66 m2							
No Asbestos							
B00C - R1007 - Toilets - Boys - 5.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1008 - Cleaning Distributed Store - 1.66 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1009 - Toilets - Girls - 4.87 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1010 - Communications Room - 13.03 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R1011 - Library Office/Workroom - 8.56 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00C - R1012 - K.L.A. Store - 4.96 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						

B00C - R1013 - Library Office/Workroom - 19.5 m2		
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)	
B00D - General Learning/Other - 1975 - Brick/Block		
Exterior		
Require Inspection		
Interior		
B00D - M0001 - Movement - 10.01 m2		
Require Inspection		
B00D - M0002 - Toilets - Boys - 16.5 m2		
Require Inspection		
B00D - M0003 - Stairs - 2.76 m2		
Require Inspection		
B00D - M1001 - Movement - 10.47 m2		
Require Inspection		
B00D - M1002 - Toilets - Girls - 16.4 m2		
Require Inspection		
B00D - M1003 - Stairs - 2.76 m2		
Require Inspection		
B00D - R0001 - External Movement - 139.3 m2		
Require Inspection		
B00D - R0002 - Cleaning Distributed Store - 4.26 m2		
Require Inspection		
B00D - R0003 - Toilets - Boys - 40.27 m2		
Require Inspection		
B00D - R0004 - Plant - 5.18 m2		
Require Inspection		
B00D - R0005 - Cleaning Distributed Store - 3.13 m2		
Require Inspection		
B00D - R0006 - Toilets - Girls - 57.64 m2		
Require Inspection		
B00D - R0007 - Plant - 3.41 m2		
Require Inspection		
B00D - R0008 - Staff Toilet - 4.03 m2		
Require Inspection		
B00D - R0009 - Movement - 2.56 m2		
Require Inspection		
B00D - R0010 - Staff Toilet - 4.68 m2		
Require Inspection		
B00D - R0011 - Distribution Board Cupboard - .56 m2		Note: No inspection of live electrical installation
Require Inspection		
B00D - R0012 - Cleaning Distributed Store - 2.43 m2		
Require Inspection		
B00D - R0013 - Other - Regional Use - 63.05 m2		
Require Inspection		
B00D - R0014 - Cleaning Supplies - 7.73 m2		
Require Inspection		
B00D - R0015 - Special Programs Room - 29.75 m2		
Require Inspection		
B00D - R0016 - Home Base - 41.41 m2		
Require Inspection		
B00D - R0017 - Practical Activities - 1hb - 32.18 m2		

Require Inspection
B00D - R0018 - Home Base - 38.29 m2
Require Inspection
B00D - R0019 - P.E Store - 22.77 m2
Require Inspection
B00D - R0020 - Staff Kitchen - 18.43 m2
Require Inspection
B00D - R0021 - General Storeroom - 10.86 m2
Require Inspection
B00D - R0022 - Movement - 5.12 m2
Require Inspection
B00D - R0024 - Staff Kitchen - 3.44 m2
Require Inspection
B00D - R0025 - Maintenance Bulk Store - 13.61 m2
Require Inspection
B00D - R0026 - Cleaning Supplies - 16.57 m2
Require Inspection
B00D - R0027 - Movement - 1.85 m2
Require Inspection
B00D - R0028 - Stairs - 4.27 m2
Require Inspection
B00D - R0029 - External Stairs - .59 m2
Require Inspection
B00D - R0030 - External Stairs - 10.39 m2
Require Inspection
B00D - R0031 - Staff Toilet - 2.48 m2
Require Inspection
B00D - R0032 - Toilet - Lobby - 2.55 m2
Require Inspection
B00D - R1001 - Movement - 47.36 m2
Require Inspection
B00D - R1005 - Home Base - 62.81 m2
Require Inspection
B00D - R1006 - Distribution Board Cupboard - .55 m2
Note: No inspection of live electrical installation
Require Inspection
B00D - R1007 - Cleaning Distributed Store - 2.43 m2
Require Inspection
B00D - R1008 - Movement - 74.25 m2
Require Inspection
B00D - R1010 - Security Store - 13.19 m2
Require Inspection
B00D - R1013 - Distribution Board Cupboard - .18 m2
Note: No inspection of live electrical installation
Require Inspection
B00D - R1020 - Stairs - 6.39 m2
Require Inspection
B00D - R1022 - Stairs - 8.76 m2
Require Inspection
B00D - R1023 - Stairs - 17.22 m2
Require Inspection
B00D - R1024 - Adjoining School - 74.41 m2
Require Inspection
B00D - R1025 - Adjoining School - 74.32 m2

Require Inspection
B00D - R1026 - Adjoining School - 74 m2
Require Inspection
B00D - R1027 - Adjoining School - 125.77 m2
Require Inspection
B00D - R1028 - Movement - 5.14 m2
Require Inspection
B00D - R2001 - Movement - 45.47 m2
Require Inspection
B00D - R2005 - Home Base - 62.8 m2
Require Inspection
B00D - R2006 - Distribution Board Cupboard - .55 m2
Note: No inspection of live electrical installation
Require Inspection
B00D - R2007 - Cleaning Distributed Store - 2.43 m2
Require Inspection
B00D - R2008 - Movement - 60.32 m2
Require Inspection
B00D - R2009 - General Storeroom - 13.19 m2
Require Inspection
B00D - R2012 - Distribution Board Cupboard - .18 m2
Note: No inspection of live electrical installation
Require Inspection
B00D - R2019 - Stairs - 12.16 m2
Require Inspection
B00D - R2020 - Stairs - 7.57 m2
Require Inspection
B00D - R2021 - Stairs - 2.76 m2
Require Inspection
B00D - R2022 - Other-Commercial - 74.65 m2
Require Inspection
B00D - R2023 - Other-Commercial - 74.24 m2
Require Inspection
B00D - R2024 - Adjoining School - 125.85 m2
Require Inspection
B00D - R2025 - Adjoining School - 74 m2
Require Inspection

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020