

Asbestos Register


(Hazardous Materials and Risk Assessment)

School:	Lindfield Learning Village (4658)
Region:	Northern Sydney AMU
State Electorate:	
Local Government Area:	Ku-Ring-Gai

Last Reviewed By:	
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

4658 - Lindfield Learning Village
Site Plan (14771)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
A - General Learning - 1976 - Concrete Framed							
Exterior							
Underfloor Voids	Requires Inspection						
Ceiling Voids	Requires Inspection						
Interior							
A - 2.999 - No Access - 193.6 m2							
Requires Inspection							
A - 3.999 - No Access - 243.97 m2							
Requires Inspection							
A - 4.1 - Gymnasium - 559.17 m2							
Requires Inspection							
A - 4.10 - Stairs - 2.78 m2							
Requires Inspection							
A - 4.11 - Movement - 17.35 m2							
Requires Inspection							
A - 4.12 - Movement - 14 m2							
Requires Inspection							
A - 4.13 - General Assistant/Bulk Store - 52.98 m2							
Requires Inspection							
A - 4.14 - Movement - 4.81 m2							
Requires Inspection							
A - 4.15 - Plant - 7.9 m2							
Requires Inspection							
A - 4.16 - Movement - 16.95 m2							
Requires Inspection							
A - 4.17 - Stairs - 5.42 m2							
Requires Inspection							
A - 4.18 - Stairs - 2.56 m2							
Requires Inspection							
A - 4.19 - Stairs - 6.33 m2							
Requires Inspection							
A - 4.2 - Cleaning Supplies Store - 3.59 m2							
Requires Inspection							
A - 4.20 - Movement - 1.94 m2							
Requires Inspection							
A - 4.3 - First Aid - 15.86 m2							
Requires Inspection							
A - 4.4 - Distribution Board Cupboard - 1.06 m2							
Requires Inspection							Note: No inspection of live electrical installation
A - 4.5 - Sport Equipment Store - 54.72 m2							
Requires Inspection							
A - 4.6 - Distribution Board - 1.82 m2							
Requires Inspection							Note: No inspection of live electrical installation
A - 4.7 - Distribution Board - .9 m2							
Requires Inspection							Note: No inspection of live electrical installation
A - 4.8 - Plant - 30.76 m2							
Requires Inspection							
A - 4.9 - Distribution Board - .88 m2							
Requires Inspection							Note: No inspection of live electrical installation
A - 5.1 - Materials Store - 32.67 m2							

Requires Inspection							
A - 5.10 - Toilets-Boys - 120.53 m2							
Requires Inspection							
A - 5.11 - Toilets-Unisex - 6.35 m2							
Requires Inspection							
A - 5.12 - Distribution Board - 2.12 m2						Note: No inspection of live electrical installation	
Requires Inspection							
A - 5.13 - Toilets-Girls - 118.77 m2							
Requires Inspection							
A - 5.14 - Plant - 15.79 m2							
Requires Inspection							
A - 5.15 - Movement - 140.95 m2							
Requires Inspection							
A - 5.16 - Stairs - 2.76 m2							
Requires Inspection							
A - 5.17 - Stairs - 5.01 m2							
Requires Inspection							
A - 5.18 - Stairs - 6.06 m2							
Requires Inspection							
A - 5.19 - Stairs - 3.02 m2							
Requires Inspection							
A - 5.2 - Materials Store - 9.69 m2							
Requires Inspection							
A - 5.20 - Lift - 2.52 m2							
Requires Inspection							
A - 5.21 - External Movement - 3.13 m2							
Requires Inspection							
A - 5.3 - Workshop - 123.03 m2							
Requires Inspection							
A - 5.4 - Kitchen - Type 1 - 139.74 m2							
Requires Inspection							
A - 5.5 - Pantry - 5.76 m2							
Requires Inspection							
A - 5.6 - Preparation - 20.13 m2							
Requires Inspection							
A - 5.7 - Sports Store - 13.34 m2							
Requires Inspection							
A - 5.8 - Distribution Board Cupboard - 1.01 m2						Note: No inspection of live electrical installation	
Requires Inspection							
A - 5.9 - Cleaning Distributed Store - 5.03 m2							
Requires Inspection							
A - 6.1 - Chemical Store - 16.63 m2							
Requires Inspection							
A - 6.2 - Preparation - Science - 61.46 m2							
Requires Inspection							
A - 6.3 - Science Laboratory - 165.5 m2							
Requires Inspection							
A - 6.4 - Movement - 89.96 m2							
Requires Inspection							
A - 6.5 - Stairs - 10.83 m2							
Requires Inspection							
A - 6.6 - Stairs - 11.17 m2							

Requires Inspection									
B - General Learning - 1973 - Concrete Framed									
Exterior									
Underfloor Voids	Requires Inspection								
Ceiling Voids	Requires Inspection								
Underfloor Voids	Requires Inspection								
Ceiling Voids	Requires Inspection								
Interior									
B - 3.999 - No Access - 52.28 m2									
Requires Inspection									
B - 4.10 - Toilets-Boys - 9.18 m2									
Requires Inspection									
B - 4.11 - Distribution Board - .96 m2						Note: No inspection of live electrical installation			
Requires Inspection									
B - 4.12 - Distribution Board Cupboard - 1.87 m2						Note: No inspection of live electrical installation			
Requires Inspection									
B - 4.13 - Student Change - Type 2 - 31.83 m2									
Requires Inspection									
B - 4.14 - Resources Space - 25.34 m2									
Requires Inspection									
B - 4.15 - Multi-Purpose Space - 85.65 m2									
Requires Inspection									
B - 4.16 - Movement - 42.94 m2									
Requires Inspection									
B - 4.17 - Movement - 117.09 m2									
Requires Inspection									
B - 4.18 - General Storeroom - 2.84 m2									
Requires Inspection									
B - 4.4 - Toilets-Unisex - 6.48 m2									
Requires Inspection									
B - 4.5 - Student Change - Type 2 - 26.86 m2									
Requires Inspection									
B - 4.6 - Plant - 1.19 m2									
Requires Inspection									
B - 4.7 - Toilets-Girls - 9.29 m2									
Requires Inspection									
B - 4.8 - Cleaning Distributed Store - 1.85 m2									
Requires Inspection									
B - 4.9 - Movement - 1.16 m2									
Requires Inspection									
B - 5.10 - Student Reception - 11.43 m2									
Requires Inspection									
B - 5.11 - Toilets-Girls - 2.8 m2									
Requires Inspection									
B - 5.12 - Toilets-Boys - 3.29 m2									
Requires Inspection									
B - 5.13 - Out Of School Hours Care Centre - 82.71 m2									
Requires Inspection									
B - 5.14 - Communications Cupboard - 1.6 m2									
Requires Inspection									
B - 5.15 - Distribution Board - 1.35 m2						Note: No inspection of live electrical installation			

Requires Inspection								
B - 5.16 - Administration - Clerical - 12.8 m2								
Requires Inspection								
B - 5.17 - Clinic - Girls - 14.72 m2								
Requires Inspection								
B - 5.18 - Clinic - Boys - 15.13 m2								
Requires Inspection								
B - 5.19 - Toilets-Boys - 20.96 m2								
Requires Inspection								
B - 5.2 - Principal - 20.09 m2								
Requires Inspection								
B - 5.20 - Toilets-Girls - 18.15 m2								
Requires Inspection								
B - 5.21 - Toilets-Boys - 2.19 m2								
Requires Inspection								
B - 5.22 - Cleaning Distributed Store - 1.97 m2								
Requires Inspection								
B - 5.23 - Toilets-Unisex - 4.82 m2								
Requires Inspection								
B - 5.24 - Covered Area - 50.9 m2								
Requires Inspection								
B - 5.25 - Canteen - 27.32 m2								
Requires Inspection								
B - 5.26 - Canteen Office/Store - 30.07 m2								
Requires Inspection								
B - 5.27 - Visual Arts Store - 11.42 m2								
Requires Inspection								
B - 5.28 - Visual Arts Workshop - 96.87 m2								
Requires Inspection								
B - 5.29 - Visual Arts Store - 15.45 m2								
Requires Inspection								
B - 5.3 - Printing/Photocopying - 9.79 m2								
Requires Inspection								
B - 5.30 - Movement - 594.05 m2								
Requires Inspection								
B - 5.31 - Communications Cupboard - 1.89 m2								
Requires Inspection								
B - 5.32 - Distribution Board - .88 m2								Note: No inspection of live electrical installation
Requires Inspection								
B - 5.33 - Toilets-Boys - 11.56 m2								
Requires Inspection								
B - 5.34 - Cleaning Distributed Store - 1.58 m2								
Requires Inspection								
B - 5.35 - Toilets-Unisex - 7.06 m2								
Requires Inspection								
B - 5.36 - Toilets-Girls - 12.52 m2								
Requires Inspection								
B - 5.37 - Cleaning Distributed Store - 3.75 m2								
Requires Inspection								
B - 5.38 - Administration - Clerical - 18.73 m2								
Requires Inspection								
B - 5.39 - Movement - 71.33 m2								

Requires Inspection								
B - 5.4 - Deputy Principal - 12.56 m2								
Requires Inspection								
B - 5.40 - Public Entry - 29.66 m2								
Requires Inspection								
B - 5.41 - Tea Room - 6.29 m2								
Requires Inspection								
B - 5.42 - Movement - 8.5 m2								
Requires Inspection								
B - 5.43 - Stairs - 6.58 m2								
Requires Inspection								
B - 5.44 - Movement - 3.8 m2								
Requires Inspection								
B - 5.45 - Movement - 46.43 m2								
Requires Inspection								
B - 5.46 - Study Space - 50.84 m2								
Requires Inspection								
B - 5.47 - Canteen - 110.26 m2								
Requires Inspection								
B - 5.48 - Staff Study - 149.65 m2								
Requires Inspection								
B - 5.49 - Movement - 21.63 m2								
Requires Inspection								
B - 5.5 - Deputy Principal - 12.67 m2								
Requires Inspection								
B - 5.50 - Communications Cupboard - 2.15 m2								
Requires Inspection								
B - 5.51 - Distribution Board Cupboard - 1.05 m2								
Note: No inspection of live electrical installation								
Requires Inspection								
B - 5.52 - Staff Kitchen - 8.83 m2								
Requires Inspection								
B - 5.53 - Staff Room - 65.27 m2								
Requires Inspection								
B - 5.54 - Stairs - 4.47 m2								
Requires Inspection								
B - 5.55 - Stairs - 18.99 m2								
Requires Inspection								
B - 5.56 - Lift - 1.68 m2								
Requires Inspection								
B - 5.57 - Movement - 71.02 m2								
Requires Inspection								
B - 5.58 - Movement - 16.1 m2								
Requires Inspection								
B - 5.59 - Communications Cupboard - 1.56 m2								
Requires Inspection								
B - 5.6 - Administration - Executive - 13.09 m2								
Requires Inspection								
B - 5.60 - Distribution Board - 2.2 m2								
Note: No inspection of live electrical installation								
Requires Inspection								
B - 5.61 - External Movement - 35.17 m2								
Requires Inspection								
B - 5.62 - Movement - 11.1 m2								

Requires Inspection								
B - 5.63 - Stairs - 19.5 m2								
Requires Inspection								
B - 5.64 - Stairs - 6.12 m2								
Requires Inspection								
B - 5.65 - Stairs - 1.8 m2								
Requires Inspection								
B - 5.66 - External Movement - 78.83 m2								
Requires Inspection								
B - 5.7 - Interview - 13.3 m2								
Requires Inspection								
B - 5.8 - Interview - 11.07 m2								
Requires Inspection								
B - 5.9 - Public Reception - 16.69 m2								
Requires Inspection								
B - 6.10 - Distribution Board - 2.01 m2								
Note: No inspection of live electrical installation								
Requires Inspection								
B - 6.11 - Distribution Board - 2.24 m2								
Note: No inspection of live electrical installation								
Requires Inspection								
B - 6.12 - Withdrawal Space - 1hb - 13.45 m2								
Requires Inspection								
B - 6.13 - Home Base - 68.04 m2								
Requires Inspection								
B - 6.14 - Home Base - 60.09 m2								
Requires Inspection								
B - 6.15 - Withdrawal Space - 1hb - 10.23 m2								
Requires Inspection								
B - 6.16 - Practical Activities - 15.33 m2								
Requires Inspection								
B - 6.17 - Distribution Board - 1.97 m2								
Note: No inspection of live electrical installation								
Requires Inspection								
B - 6.18 - Distribution Board Cupboard - 1.42 m2								
Note: No inspection of live electrical installation								
Requires Inspection								
B - 6.19 - Communications Cupboard - 29.77 m2								
Requires Inspection								
B - 6.2 - Home Base X2 - 81.6 m2								
Requires Inspection								
B - 6.20 - Store - 11.86 m2								
Requires Inspection								
B - 6.21 - Toilets-Girls - 2.13 m2								
Requires Inspection								
B - 6.22 - Toilets - Girls/Disabled Cubicle - 2.51 m2								
Requires Inspection								
B - 6.23 - Toilets - Boys/Disabled Cubicle - 2.84 m2								
Requires Inspection								
B - 6.24 - Toilets-Boys - 2.65 m2								
Requires Inspection								
B - 6.25 - Toilets-Unisex - 5.5 m2								
Requires Inspection								
B - 6.26 - Practical Activities - 49.56 m2								
Requires Inspection								

B - 6.27 - Distribution Board - .68 m2		Note: No inspection of live electrical installation					
Requires Inspection							
B - 6.28 - Plant - 1.43 m2							
Requires Inspection							
B - 6.29 - Practical Activities - 34.41 m2							
Requires Inspection							
B - 6.3 - Withdrawal Space - 2hb - 12.62 m2							
Requires Inspection							
B - 6.30 - Stairs - 10.42 m2							
Requires Inspection							
B - 6.31 - Home Base - 35.84 m2							
Requires Inspection							
B - 6.32 - Practical Activities - 1hb - 39.16 m2							
Requires Inspection							
B - 6.33 - Movement - 46.39 m2							
Requires Inspection							
B - 6.34 - Practical Activities - 1hb - 27.64 m2							
Requires Inspection							
B - 6.36 - Movement - 198.71 m2							
Requires Inspection							
B - 6.37 - Stairs - 10 m2							
Requires Inspection							
B - 6.38 - Movement - 3.83 m2							
Requires Inspection							
B - 6.39 - Practical Activities - 25.12 m2							
Requires Inspection							
B - 6.4 - Toilets-Boys - 14.96 m2							
Requires Inspection							
B - 6.40 - Stairs - 9.27 m2							
Requires Inspection							
B - 6.41 - Stairs - 15.94 m2							
Requires Inspection							
B - 6.42 - External Movement - 19.43 m2							
Requires Inspection							
B - 6.5 - Cleaning Supplies Store - 2.83 m2							
Requires Inspection							
B - 6.6 - Toilets-Disabled - 7.07 m2							
Requires Inspection							
B - 6.7 - Toilets-Girls - 12 m2							
Requires Inspection							
B - 6.8 - Home Base - 55.95 m2							
Requires Inspection							
B - 6.9 - Withdrawal Space - 1hb - 9.69 m2							
Requires Inspection							
B - 7.999 - No Access - 36.96 m2							
Requires Inspection							
C - General Learning - 1983 - Concrete Framed							
Exterior							
Underfloor Voids	Requires Inspection						
Ceiling Voids	Requires Inspection						
Underfloor Voids	Requires Inspection						

Ceiling Voids	Requires Inspection						
Interior							
C - 4.1 - Toilets-Girls - 2.49 m2							
Requires Inspection							
C - 4.10 - Communications Cupboard - 1.68 m2							
Requires Inspection							
C - 4.11 - General Storeroom - 4.08 m2							
Requires Inspection							
C - 4.12 - Stairs - 8.52 m2							
Requires Inspection							
C - 4.13 - Stairs - 4.48 m2							
Requires Inspection							
C - 4.14 - Home Base X3 - 233.36 m2							
Requires Inspection							
C - 4.15 - Movement - 17.08 m2							
Requires Inspection							
C - 4.16 - Stairs - 5.39 m2							
Requires Inspection							
C - 4.17 - External Movement - 5.7 m2							
Requires Inspection							
C - 4.2 - Toilets-Girls - 2.55 m2							
Requires Inspection							
C - 4.3 - Toilets-Unisex - 6.62 m2							
Requires Inspection							
C - 4.4 - Toilets-Boys - 2.18 m2							
Requires Inspection							
C - 4.5 - Toilets - Boys/Disabled Cubicle - 2.35 m2							
Requires Inspection							
C - 4.6 - Plant - 1.36 m2							
Requires Inspection							
C - 4.7 - Withdrawal Space - 2hb - 14.53 m2							
Requires Inspection							
C - 4.8 - Plant - .69 m2							
Requires Inspection							
C - 4.9 - Distribution Board - .63 m2							
Requires Inspection							
C - 5.1 - Toilets-Girls - 3.04 m2							
Requires Inspection							
C - 5.10 - Stairs - 7.74 m2							
Requires Inspection							
C - 5.11 - Lift - 2.52 m2							
Requires Inspection							
C - 5.12 - Home Base X3 - 256.45 m2							
Requires Inspection							
C - 5.13 - Movement - 10.26 m2							
Requires Inspection							
C - 5.14 - Careers Advisers Office - 18.96 m2							
Requires Inspection							
C - 5.15 - Stairs - 3.31 m2							
Requires Inspection							
C - 5.16 - Stairs - 5.82 m2							

Note: No inspection of live electrical installation

Requires Inspection									
C - 5.17 - Movement - 3.53 m2									
Requires Inspection									
C - 5.2 - Toilets-Girls - 2.5 m2									
Requires Inspection									
C - 5.3 - Toilets-Boys - 2.7 m2									
Requires Inspection									
C - 5.4 - Toilets-Boys - 2.51 m2									
Requires Inspection									
C - 5.5 - Withdrawal Space - 2hb - 14.06 m2									
Requires Inspection									
C - 5.6 - Plant - .69 m2									
Requires Inspection									
C - 5.7 - Distribution Board - .63 m2									Note: No inspection of live electrical installation
Requires Inspection									
C - 5.8 - Communications Cupboard - 1.68 m2									
Requires Inspection									
C - 5.9 - Movement - 14.74 m2									
Requires Inspection									
C - 6.1 - Toilets-Girls - 2.33 m2									
Requires Inspection									
C - 6.10 - Movement - 15.02 m2									
Requires Inspection									
C - 6.11 - Home Base X3 - 244.02 m2									
Requires Inspection									
C - 6.12 - Practical Activities - 3hb - 32.85 m2									
Requires Inspection									
C - 6.13 - Stairs - 13.11 m2									
Requires Inspection									
C - 6.14 - Movement - 10.18 m2									
Requires Inspection									
C - 6.15 - Withdrawal Space - 2hb - 19.35 m2									
Requires Inspection									
C - 6.2 - Toilets - Girls/Disabled Cubicle - 2.68 m2									
Requires Inspection									
C - 6.3 - Toilets-Boys - 2.33 m2									
Requires Inspection									
C - 6.4 - Toilets-Girls - 2.15 m2									
Requires Inspection									
C - 6.5 - Toilets - Boys/Disabled Cubicle - 2.78 m2									
Requires Inspection									
C - 6.6 - Toilets-Boys - 2.24 m2									
Requires Inspection									
C - 6.7 - Plant - .69 m2									
Requires Inspection									
C - 6.8 - Distribution Board - .63 m2									Note: No inspection of live electrical installation
Requires Inspection									
C - 6.9 - Communications Cupboard - 1.68 m2									
Requires Inspection									
D - Library - 1971 - Concrete Framed									
Exterior									

Underfloor Voids	Requires Inspection						
Ceiling Voids	Requires Inspection						
Interior							
D - 1.997 - No Access - 95.98 m2							
Requires Inspection							
D - 1.998 - No Access - 343.73 m2							
Requires Inspection							
D - 1.999 - No Access - 479.42 m2							
Requires Inspection							
D - 2.999 - No Access - 4280.67 m2							
Requires Inspection							
D - 3.999 - No Access - 4878.27 m2							
Requires Inspection							
D - 4.1 - Music Learning Space - 105.62 m2							
Requires Inspection							
D - 4.10 - Practice/Seminar - 5.81 m2							
Requires Inspection							
D - 4.11 - Practice/Seminar - 11.66 m2							
Requires Inspection							
D - 4.12 - Practice/Seminar - 6.72 m2							
Requires Inspection							
D - 4.13 - Practice/Seminar - 5.92 m2							
Requires Inspection							
D - 4.14 - Practice/Seminar - 5.49 m2							
Requires Inspection							
D - 4.15 - Practice/Seminar - 5.72 m2							
Requires Inspection							
D - 4.16 - Practice/Seminar - 5.46 m2							
Requires Inspection							
D - 4.17 - Practice/Seminar - 5.38 m2							
Requires Inspection							
D - 4.2 - Music Learning Space - 105.66 m2							
Requires Inspection							
D - 4.3 - Music Store - 33.77 m2							
Requires Inspection							
D - 4.4 - Movement - 62.78 m2							
Requires Inspection							
D - 4.6 - Practice/Seminar - 5.66 m2							
Requires Inspection							
D - 4.7 - Practice/Seminar - 5.66 m2							
Requires Inspection							
D - 4.8 - Practice/Seminar - 5.9 m2							
Requires Inspection							
D - 4.9 - Practice/Seminar - 5.72 m2							
Requires Inspection							
D - 5.999 - No Access - 2277.39 m2							
Requires Inspection							
D - 6.999 - No Access - 823.43 m2							
Requires Inspection							
D - 7.999 - No Access - 42.73 m2							
Requires Inspection							

D - 8.999 - No Access - 6.1 m2							
Requires Inspection							
E - General Learning - 1984 - Concrete Framed							
Exterior							
Underfloor Voids	Requires Inspection						
Ceiling Voids	Requires Inspection						
Interior							
E - 1.999 - No Access - 629.53 m2							
Requires Inspection							
E - 2.999 - No Access - 716.75 m2							
Requires Inspection							
E - 3.999 - No Access - 679.59 m2							
Requires Inspection							
E - 4.999 - No Access - 679.59 m2							
Requires Inspection							
E - G999 - No Access - 281.01 m2							
Requires Inspection							
F - Agricultural Science - 1988 - Concrete Framed							
Exterior							
Underfloor Voids	Requires Inspection						
Ceiling Voids	Requires Inspection						
Interior							
F - 1.999 - No Access - 97.54 m2							
Requires Inspection							
F - 2.999 - No Access - 97.54 m2							
Requires Inspection							
G - Agricultural Science - 1988 - Brick/Block							
Exterior							
Underfloor Voids	Requires Inspection						
Ceiling Voids	Requires Inspection						
Interior							
G - 2.999 - No Access - 46.06 m2							
Requires Inspection							

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020