
VENTILATION AUDIT REPORT Version 2



SCHOOL:	Ballimore Public School (1111)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Dubbo
LOCAL GOVERNMENT AREA:	Dubbo



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
•	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (17.41 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Home Base - (54.45 SQM) - Teaching Space: 1	Student Space (33)	
B00A - R0004 - Staff Room - (13.85 SQM)	Office (3)	
B00B - R0001 - Movement - (17.87 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Reading Area - (59.86 SQM)	Student Space (27)	
OS 500 18109 - OS 500 18109 - Admin - Library - (133 SQM)	Office (33)	