
VENTILATION AUDIT REPORT Version 2



SCHOOL:	Bendemeer Public School (1191)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Tamworth

1191 - Bendemeer Public School Site Plan (10774)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with COVID safe school operations. It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Reading Area - (46.83 SQM)	Student Space (21)	
B00A - R0005 - Home Base - (47.01 SQM) - Teaching Space: 1	Student Space (30)	
B00A - R0008 - Home Base - (67.07 SQM) - Teaching Space: 1	Student Space (49)	
B00A - R0013 - Movement - (14.51 SQM)	Not Applicable	Circulation or storage space.
B00A - R0014 - Movement - (55.86 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Movement - (35.2 SQM)	Not Applicable	Circulation or storage space.
B00F - R0005 - Reading Area - (72.12 SQM)	Student Space (33)	