

## **VENTILATION AUDIT REPORT Version 2**



SCHOOL:	Bullarah Public School (4228)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Moree Plains





Site plan is indicative only and is included to show building numbers used by the Department.

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
•	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (20.97 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Clerical Office/Workroom - (16.32 SQM)	Office (4)	
B00A - R0009 - Reading Area - (53.33 SQM)	Student Space (24)	
B00E - R0001 - Withdrawal Space - 1hb - (20.14 SQM)	Student Space (9)	
B00F - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	Student Space (87)	