
## **VENTILATION AUDIT REPORT Version 2**



SCHOOL:	Capertee Public School (1501)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Lithgow





Site plan is indicative only and is included to show building numbers used by the Department.

## **Ventilation Audit Key**

Category	Description
	Category A  Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation.  NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B  This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> .  The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (24.22 SQM)	Office (6)	
B00A - R0002 - Home Base - (49.1 SQM) - Teaching Space: 1	Student Space (47)	
B00A - R0003 - Reading Area - (47.52 SQM)	Student Space (22)	
B00A - R0004 - Staff Room - (6.62 SQM)	Office (1)	
B00A - R0005 - Movement - (28.2 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Reading Area - (59.9 SQM)	Student Space (27)	