
## **VENTILATION AUDIT REPORT Version 2**



SCHOOL:	Cullen Bullen Public School (1700)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Lithgow

1700 - Cullen Bullen Public School Site Plan (10281)



Site plan is indicative only and is included to show building numbers used by the Department.

## **Ventilation Audit Key**

Category	Description
	Category A  Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation.  NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B  This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> .  The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Principal - (13.67 SQM)	Office (3)	
B00A - R0003 - Reading Area - (33.22 SQM)	Student Space (15)	
B00A - R0004 - Home Base - (53.69 SQM) - Teaching Space: 1	Student Space (42)	
B00A - R0006 - Movement - (21.37 SQM)	Not Applicable	Circulation or storage space.
B00A - R0007 - Entry Vestibule - (7.58 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Staff Room - (9.68 SQM)	Office (2)	
B00D - R0001 - Special Programs Room - (33.6 SQM)	Student Space (15)	
B00D - R0003 - Movement - (5.42 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Movement - (35.65 SQM)	Not Applicable	Circulation or storage space.
B00F - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	Student Space (47)	