VENTILATION AUDIT REPORT Version 2

4

5 20

0


1:861

30

Meters



SCHOOL:	Dungay Public School (1791)
AMU REGION:	North Coast
STATE ELECTORATE:	Lismore
LOCAL GOVERNMENT AREA:	Tweed



1791 - Dungay Public School Site Plan (12054)

Site plan is indicative only and is included to show building numbers used by the Department.

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
•	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (66.66 SQM) - Teaching Space: 1	Student Space (56)	
B00A - R0003 - Practical Activities - 1hb - (8.49 SQM)	Student Space (3)	
B00A - R0005 - Clerical Office - (11.06 SQM)	Office (2)	
B00A - R0006 - Principal - (10.76 SQM)	Office (2)	
B00B - R0001 - Reading Area - (39.8 SQM)	Student Space (18)	
B00C - R0001 - Home Base - (53.87 SQM) - Teaching Space: 1	Student Space (47)	
B00C - R0002 - Practical Activities - 1hb - (8.31 SQM)	Student Space (3)	
B00C - R0004 - Staff Room - (17.36 SQM)	Office (4)	
B00E - R0001 - Canteen - (16.64 SQM)	Not Applicable	Circulation or storage space.
B00F - R0002 - Practical Activities - (19.61 SQM)	Student Space (9)	
B00F - R0004 - Home Base - (58.9 SQM) - Teaching Space: 1	Student Space (47)	
B00F - R0005 - Withdrawal Space - 2hb - (10.67 SQM)	Student Space (4)	
B00F - R0006 - Home Base - (59.01 SQM) - Teaching Space: 1	Student Space (47)	
B00F - R0008 - Practical Activities - (19.61 SQM)	Student Space (9)	
OS 505 11784 - OS 505 11784 - Admin Staff/Principal/Secure Store - (76 SQM)	Office (19)	