
VENTILATION AUDIT REPORT Version 2



SCHOOL:	Dungowan Public School (1793)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Tamworth

1793 - Dungowan Public School Site Plan (13142)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Movement - (40.19 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Practical Activities - 1hb - (8.18 SQM)	Student Space (3)	
B00A - R0005 - Home Base - (62.99 SQM) - Teaching Space: 1	Student Space (35)	
B00A - R0006 - Home Base - (66.41 SQM) - Teaching Space: 1	Student Space (65)	
B00A - R0007 - Practical Activities - 1hb - (7.28 SQM)	Student Space (3)	
B00A - R0008 - Clerical Office - (14.19 SQM)	Office (3)	
B00A - R0010 - Staff Room - (9.49 SQM)	Office (2)	
B00A - R0014 - Movement - (8.83 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Communal Space - (59.86 SQM)	Student Space (27)	
OS 503 15293 - OS 503 15293 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	Office (38)	