

VENTILATION AUDIT REPORT Version 2



SCHOOL:	Fassifern Public School (1904)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Lake Macquarie
LOCAL GOVERNMENT AREA:	Lake Macquarie





Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
•	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (10.55 SQM)	Office (2)	
B00A - R0002 - Home Base - (47.15 SQM) - Teaching Space: 1	Student Space (56)	
B00A - R0003 - Movement - (22.55 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Home Base - (49.86 SQM) - Teaching Space: 1	Student Space (93)	
B00A - R0005 - Interview - (7.85 SQM)	Office (1)	
B00A - R0012 - Movement - (9.5 SQM)	Not Applicable	Circulation or storage space.
B00A - R0013 - Sick Bay - (8.07 SQM)	Student Space (3)	
B00A - R0014 - Principal - (12.89 SQM)	Office (3)	
B00A - R0015 - Clerical Office - (18.14 SQM)	Office (4)	
B00D - R0001 - Reading Area - (66.67 SQM)	Student Space (30)	
B00E - R0001 - Staff Room - (37.34 SQM)	Office (9)	
B00F - R0002 - Reading Area - (91.95 SQM)	Student Space (42)	
NS 100 10837 - NS 100 10837 - Learning Unit - Single Primary/PAA - (76 SQM)	Student Space (35)	
NS 300 11867 - NS 300 11867 - FSU/Bulk Store/Toilet - (57 SQM)	Not Applicable	Circulation or storage space.