VENTILATION AUDIT REPORT Version 2



SCHOOL:	Ganmain Public School (1954)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Coolamon

1954 - Ganmain Public School Site Plan (11434)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Reading Area - (47.79 SQM)	Student Space (22)	
B00A - R0002 - Home Base - (98.01 SQM) - Teaching Space: 1	Student Space (54)	
B00A - R0003 - Home Base - M - (47.38 SQM) - Teaching Space: 1	Student Space (25)	
B00A - R0007 - Movement - (7.74 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Staff Room - (17.17 SQM)	Office (4)	
B00A - R0009 - Clerical Office - (10.86 SQM)	Office (2)	
B00A - R0012 - Principal - (11.83 SQM)	Office (2)	
B00A - R0013 - Clerical Office/Workroom - (18.48 SQM)	Office (4)	
B00B - R0002 - Movement - (24.64 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Movement - (36.07 SQM)	Not Applicable	Circulation or storage space.
B00E - R0002 - Special Programs Room - (30.45 SQM)	Student Space (14)	
B00F - R0001 - Withdrawal Space - 1hb - (12.94 SQM)	Student Space (6)	
B00F - R0002 - Home Base - (60.97 SQM) - Teaching Space: 1	Student Space (34)	
B00F - R0003 - Movement - (6.71 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Clerical Office - (59.86 SQM)	Office (14)	