

VENTILATION AUDIT REPORT Version 2



SCHOOL:	Hermidale Public School (2155)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Bogan







2155 - Hermidale Public School
Site Plan (13080)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Home Base - (50.01 SQM) - Teaching Space: 1	 Student Space (28)	
B00A - R0004 - Staff Room - (14.72 SQM)	 Office (3)	
B00A - R0005 - Movement - (24.65 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Clerical Office - (32.12 SQM)	 Office (8)	
B00C - R0001 - Clerical Office - (11.23 SQM)	 Office (2)	
B00C - R0002 - Home Base - (41.44 SQM) - Teaching Space: 1	 Student Space (23)	
B00C - R0004 - Special Programs Room - (20.3 SQM)	 Student Space (9)	