
VENTILATION AUDIT REPORT Version 2



SCHOOL:	Jennings Public School (2223)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Lismore
LOCAL GOVERNMENT AREA:	Tenterfield

2223 - Jennings Public School Site Plan (12547)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Sick Bay - (7.62 SQM)	Student Space (3)	
B00A - R0004 - Entry Vestibule - (7.63 SQM)	Not Applicable	Circulation or storage space.
B00A - R0006 - Principal - (14.89 SQM)	Office (3)	
B00A - R0008 - Home Base - (57.66 SQM) - Teaching Space: 1	Student Space (90)	
B00A - R0011 - Clerical Office/Workroom - (22.68 SQM)	Office (5)	
B00A - R0013 - Staff Room - (14.96 SQM)	Office (3)	
B00A - R0014 - Movement - (6.2 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Seminar/Study - (15.83 SQM)	Office (3)	
B00B - R0002 - Reading Area - (65.91 SQM)	Student Space (30)	
B00C - R0001 - Special Programs Room - (14.37 SQM)	Student Space (6)	
B00C - R0002 - Special Programs Room - (53.25 SQM)	Student Space (24)	
B00C - R0003 - Movement - (10.13 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Home Base - (60.61 SQM) - Teaching Space: 1	Student Space (75)	