

## **VENTILATION AUDIT REPORT Version 2**



SCHOOL:	Longneck Lagoon Environmental Education Centre (5690)
AMU REGION:	Western Sydney
STATE ELECTORATE:	Hawkesbury
LOCAL GOVERNMENT AREA:	Hawkesbury





Site plan is indicative only and is included to show building numbers used by the Department.

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
•	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0007 - Movement - (10.61 SQM)	Not Applicable	Circulation or storage space.
B00B - R0005 - Movement - (8.81 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - General Learning Space - (52.86 SQM) - Teaching Space: 1	Student Space (29)	
B00C - R0002 - Canteen - (12.88 SQM)	Not Applicable	Circulation or storage space.
B00C - R0005 - Movement - (75.85 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - General Assistants - (29.47 SQM)	Office (7)	
OS 601 14378 - OS 601 14378 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	