
## **VENTILATION AUDIT REPORT Version 2**



SCHOOL:	Louth Public School (3594)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Bourke

3594 - Louth Public School Site Plan (10640)



Site plan is indicative only and is included to show building numbers used by the Department.

## **Ventilation Audit Key**

Category	Description
	Category A  Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation.  NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B  This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> .  The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (44.21 SQM) - Teaching Space: 1	Student Space (24)	
B00A - R0002 - Reading Area - (15.5 SQM)	Student Space (7)	
B00A - R0003 - Outdoor Learning Area - (25.93 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Special Programs Room - (20.09 SQM)	Student Space (9)	
B00D - R0001 - Staff Kitchen - (6.71 SQM)	Office (1)	
B00F - R0001 - Home Base - (60.03 SQM) - Teaching Space: 1	Student Space (34)	