
VENTILATION AUDIT REPORT Version 2



SCHOOL:	Lue Public School (2432)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Dubbo
LOCAL GOVERNMENT AREA:	Mid-Western

2432 - Lue Public School Site Plan (12775)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
•	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Duplicating Workroom - (11.28 SQM)	Office (2)	
B00A - R0002 - Reading Area - (44.1 SQM) - Teaching Space: 1	Student Space (55)	
B00A - R0003 - Home Base - (42.94 SQM) - Teaching Space: 1	Student Space (56)	
B00A - R0004 - Staff Room - (11.14 SQM)	Office (2)	
B00A - R0005 - Movement - (17.93 SQM)	Not Applicable	Circulation or storage space.
B00A - R0006 - Principal - (14.75 SQM)	Office (3)	
B00A - R0007 - Movement - (59.55 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Special Programs Room - (22.59 SQM)	Student Space (10)	
B00D - R0001 - Reading Area - (59.92 SQM)	Student Space (27)	