
VENTILATION AUDIT REPORT Version 2



SCHOOL:	Lyndhurst Public School (2436)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Blayney

2436 - Lyndhurst Public School Site Plan (12776)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (39.04 SQM) - Teaching Space: 1	Student Space (22)	
B00A - R0002 - Reading Area - (33.02 SQM)	Student Space (15)	
B00A - R0004 - Staff Room Annexe - (12.96 SQM)	Office (3)	
B00A - R0005 - Clerical Office - (5.53 SQM)	Office (1)	
B00B - R0001 - Home Base - Bd/Cd/Ed - (29.3 SQM) - Teaching Space: 1	Student Space (16)	
B00B - R0002 - Movement - (13.87 SQM)	Not Applicable	Circulation or storage space.
B00B - R0003 - Staff Kitchen - (8.37 SQM)	Office (2)	
B00B - R0004 - Practical Activities - 1hb - (20.08 SQM)	Student Space (9)	
B00F - R0001 - Reading Area - (59.89 SQM)	Student Space (27)	