

## **VENTILATION AUDIT REPORT Version 2**



SCHOOL:	Manifold Public School (2464)
AMU REGION:	North Coast
STATE ELECTORATE:	Clarence
LOCAL GOVERNMENT AREA:	Richmond Valley





Site plan is indicative only and is included to show building numbers used by the Department.

## Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
•	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (55.04 SQM) - Teaching Space: 1	Student Space (93)	
B00F - R0001 - Home Base - (60.02 SQM) - Teaching Space: 1	Student Space (75)	
OS 500 18113 - OS 500 18113 - Admin - Library - (133 SQM)	Office (33)	