
## **VENTILATION AUDIT REPORT Version 2**



SCHOOL:	Marra Creek Public School (4454)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Warren

4454 - Marra Creek Public School Site Plan (13088)



Site plan is indicative only and is included to show building numbers used by the Department.

## **Ventilation Audit Key**

Category	Description
	Category A  Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation.  NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B  This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> .  The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (66.75 SQM) - Teaching Space: 1	Student Space (36)	
B00B - R0001 - Movement - (27.28 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Movement - (20.54 SQM)	Not Applicable	Circulation or storage space.
B00B - R0003 - Reading Area - (29.14 SQM)	Student Space (13)	
B00B - R0004 - Staff Room - (12.29 SQM)	Office (3)	