
## **VENTILATION AUDIT REPORT Version 2**



SCHOOL:	Mullaley Public School (2660)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Gunnedah



Site plan is indicative only and is included to show building numbers used by the Department.

## **Ventilation Audit Key**

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
Category B  This space should be occupied at 1 person per 4m <sup>2</sup> to comply with COVID safe school operations and the guided use of The report details the number of people who can be accommodated safely in each of the identified spaces.		

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Movement - (10.08 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Withdrawal Space - 1hb - (25.81 SQM)	Student Space (11)	
B00A - R0005 - Principal - (8.84 SQM)	Office (2)	
B00B - R0002 - Home Base - (39.68 SQM) - Teaching Space: 1	Student Space (38)	
B00B - R0003 - Movement - (14.18 SQM)	Not Applicable	Circulation or storage space.
B00B - R0004 - Practical Activities - 1hb - (13.03 SQM)	Student Space (6)	
B00C - R0001 - Movement - (22.49 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Home Base - (48.64 SQM) - Teaching Space: 1	Student Space (26)	
B00C - R0006 - Staff Room - (11.16 SQM)	Office (2)	
B00D - R0001 - Movement - (24.15 SQM)	Not Applicable	Circulation or storage space.
B00D - R0004 - Home Base - (48.58 SQM) - Teaching Space: 1	Student Space (26)	
B00D - R0007 - Clerical/Printing - (22.24 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Outdoor Learning Area - (18.48 SQM)	Not Applicable	Circulation or storage space.