
VENTILATION AUDIT REPORT Version 2



SCHOOL:	Old Bonalbo Public School (2800)
AMU REGION:	North Coast
STATE ELECTORATE:	Lismore
LOCAL GOVERNMENT AREA:	Kyogle



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Principal - (11.76 SQM)	Office (2)	
B00A - R0002 - Clerical Office - (11.76 SQM)	Office (2)	
B00A - R0004 - Home Base - (44.56 SQM) - Teaching Space: 1	Student Space (36)	
B00A - R0012 - Clerical Office - (16.72 SQM)	Office (4)	
B00A - R0013 - Staff Room - (22.24 SQM)	Office (5)	
B00A - R0014 - Movement - (34.46 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Movement - (15.79 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Home Base - (44.11 SQM) - Teaching Space: 1	Student Space (47)	
B00H - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	Student Space (41)	