

## **VENTILATION AUDIT REPORT Version 2**



SCHOOL:	Pomona Public School (2893)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Wentworth





Site plan is indicative only and is included to show building numbers used by the Department.

## Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
•	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0001 - Home Base - (53.45 SQM) - Teaching Space: 1	Student Space (29)	
B00B - R0005 - Reading Area - (30.16 SQM)	Student Space (13)	
B00B - R0006 - Special Programs Room - (22.64 SQM)	Student Space (10)	
B00D - R0001 - Principal - (11.59 SQM)	Office (2)	
B00D - R0004 - Staff Kitchen - (10.51 SQM)	Office (2)	
B00D - R0005 - Clerical Office - (10.25 SQM)	Office (2)	
B00D - R0006 - Clerical Office - (7.72 SQM)	Office (1)	
B00D - R0009 - Home Base - (67.48 SQM) - Teaching Space: 1	Student Space (37)	
B00D - R0011 - Reading Area - (25.29 SQM)	Student Space (11)	
B00D - R0012 - Special Programs Room - (24.42 SQM)	Student Space (11)	